## **Tender Clarification Request No. 7**

## <u>Hiring of Directional & Performance Drilling Services</u> TENDER ENQUIRY NO. PROC-SERVICES/CB/DO-4073/2018

Following Correction/Clarification may be considered against the subject Tender Inquiry for submission of bid proposal.

High temperature and high torque mud motors are not required for hole sizes 26", 22" and 17-1/2"/ 17" instead of these only high torque mud motors are required for hole sizes 26", 22" and 17-1/2"/ 17" for both directional and performance drilling for North and South/center regions.

Therefore bidder may be advised to quote only High torque mud motors for hole sizes 26", 22" and 17-1/2"/ 17" for both directional and performance drilling for North and South/center regions