

Clarification No. 01

TENDER ENQUIRY NO. PROC-SERVICES/CB/DO-3050/2017

Some of the Prospective bidders have made a few queries against the subject Tender Enquiry. The queries along with OGDCL replies are given below for information of all the prospective bidders.

OGDCL Tender Document Reference/Description		Bidder's Query/Clarification request	OGDCL RESPONSE
Notes in format of rates Section/Tender page 21 of 45	Run charge will be zero if under reamer did not enlarge hole more than 10 meter	Please clarify what this term implies i.e the hole section length required to be enlarged is greater than 10 meter and tool fails to enlarge required length resulting in pull out after enlarging less than 10 meter.	Already explained in the tender. Run charge will be zero in this case.
Notes in format of rates Section/Tender page 21 of 45	Run charge will be zero if under reamer did not enlarge hole more than 10 meter	Please confirm that in the event the actual hole section length required to be enlarged is less than 10 meter that OGDCL will pay the quoted rate by the contractor.	OGDCL will pay the quoted rates in this case