

Clarification No. 02

Hiring of Directional & Performance Drilling Services against TE# PROC-SER/CB/DO-4073/2018

After review of subject tender enquiry found some typo error in Directional Driller & MWD Engineer operating days in “**Evaluation Criteria for Performance Drilling in North Region**”. Corrected version be read as:

S. NO.	SECTION/ HOLE SIZE	DESCRIPTION	ERROR DAYS	CORRECTED DAYS
01	SECTION-C 17-1/2" / 17" HOLE	(4) CREW MWD Engineer	20	40
02.	SECTION-D 12-1/4" HOLE	(4) CREW MWD Engineer	25	50
03.	SECTION-E 8-1/2" HOLE	(4) CREW MWD Engineer	15	30
04.	SECTION-F 6" / 6-1/2" HOLE	(4) CREW MWD Engineer	10	15
05.	SECTION-G 4-1/8" HOLE	(3) CREW Directional Driller	7	4
06.	SECTION-G 4-1/8" HOLE	(3) CREW MWD Engineer	7	4

2. Some typo error also found in operating days of Directional Driller & MWD Engineer in “**Evaluation Criteria for Directional Drilling in South/ Centre Region**”. Corrected version be read as:

S. NO.	SECTION/ HOLE SIZE	DESCRIPTION	ERROR DAYS	CORRECTED DAYS
01	SECTION-G 4-1/8" HOLE	(5) Professional Directional Driller	7	4
02.	SECTION-G 4-1/8" HOLE	(5) Professional MWD Engineer	7	4