

OIL & GAS DEVELOPMENT COMPANY LIMITED

UCH GAS FIELD - BALOCHISTAN

Tender: PROC-SERVICES/CB/P&P-5411/2022 "HIRING OF SERVICES FOR EXECUTION OF ANNUAL TURN AROUND (ATA) 2022 OF UCH-I GAS PLANT"


Clarification: UCH-I Cooling Tower FRP Repair SOW

Ref: SOW Clause-ME7 (6) and Explanatory Note Clause No. 27 of Tender Document

Representative of M/s Pak Fiber Glass Industry, Lahore through M/s Pak Arab Engg. (Pvt.) Ltd visited the UCH-I Plant Site for clarification of FRP repair work of Cooling Tower; after joint visit of UCH-I Cooling Tower, the detail of FRP Repair SOW is given as below:

1. Reinforcement / bonding of top floor fiber sheets with FRP material.
2. Reinforcement / repair of fiber sheets of hot water distribution deck floor.
3. FRP repair of hot water distribution pipe supports at cooling tower top.
4. FRP coating / repairing of angle valves water distribution boxes.
5. Fixing and tightening of fan deck foundation bolts and supports.
6. Dismantling and proper re-fitting of side walls corrugated sheets and sealing/filling of sheets joints with FRP material.
7. Louvers fitting / setting, tightening and joints sealing/filling with FRP material.
8. Reinforcement and addition of FRP supports for drift eliminators.
9. Reinforcement, tightening and FRP repair of various damage structure members.

Note: "Supply of FRP material required for above SOW is in the scope of contractor/sub-contractor"


MUHAMMAD SHAFIQUE TAHIR
M/s Pak Fiber Glass Industry, Lahore
On behalf of M/s Pak Arab Engg. (Pvt.) Ltd. Dharaki


IFTIKHAR AHMED
I/C Maintenance
Uch Gas Field-OGDCL