OIL & GAS DEVELOPMENT COMPANY LIMITED PROCUREMENT DEPARTMENT, ISLAMABAD FOREIGN SECTION C

(To be completed, filled in, signed and stamped by the principal)

ANNEXURE 'A'

Material

50K HOURS MAINTENANCE SPARES FOR ABB TURBO CHARGERS (MODEL: TPS 57D01) INSTALLED AT WAUKESHA

GAS ENGINES

Tender Enquiry No

PROC-FC/CB/P&P/PIRKOH-3108/2017

Due Date

Evaluation Criteria

FULL

SCHEDULE OF REQUIREMENT

Sr No	Description	Unit	Quantity	Unit Price	QUIREMENT Unit Price Total Price Unit Price Total Price			Dordot J.E.
		Cint	Quantity	(FOB)	(FOB)	C & F BY SEA	C & F BY SEA	Deviated From Tender Spec, If An
1	BASIC REPLACEMENT TURBOCHARGER, MATERIAL NO.	Number	2 .					
	HZTL430500M0001, PART # 10100, EQUIPMENT SERIAL # HT499412RHS & HT507078LHS OR EQUIVALENT							
2	BLADED SHAFT (KW8TR1TT16TV1), MATERIAL NO.	NTl				The second second		
1	HZTL115665R0016, PART # 21000, EQUIPMENT SERIAL # HT499412RHS,	Number	4					
	HT507078LHS, HT507080RHS & HT505325LH OR EQUIVALENTS							
3	COMPRESSOR WHEEL (KV11CR1CT70CV10), MATERIAL NO.	Number	4			5 g		
	HZTL220871P0070, PART # 25000, EQUIPMENT SERIAL # HT499412RHS,					_	• • •	
	HT507078LHS, HT507080RHS & HT505325LH OR EQUIVALENTS							
4	COMPRESSOR & TURBINE CHECK (SPARE PART SET # 1), MATERIAL	Number	4					
	NO. HZTL439812R0001, PART # 97070, EQUIPMENT SERIAL #							
	HT499412RHS, HT507078LHS, HT507080RHS & HT505325LH OR							
	EQUIVALENTS							
5	BEARING CHECK (SPARE PART SET # 2), MATERIAL NO.	Number	4					
	HZTL431969R0001, PART # 97076, EQUIPMENT SERIAL # HT499412RHS,							
	HT507078LHS, HT507080RHS & HT505325LH OR EQUIVALENTS		•					
6	BEARING CHANGE (RADIAL), (SPARE PART SET # 3), MATERIAL NO.	Number	` 4			, 1		
	HZTL453810R0001, PART # 97081, EQUIPMENT SERIAL # HT499412RHS,							
	HT507078LHS, HT507080RHS & HT505325LH OR EQUIVALENTS							
7	BEARING CHANGE (AXIAL), (SPARE PART SET # 4), MATERIAL NO.	Number	4				2	
	HZTL453809R0001, PART # 97084, EQUIPMENT SERIAL # HT499412RHS.						1	*
	HT507078LHS, HT507080RHS & HT505325LH OR EQUIVALENTS							

Note: (1) PURSUANT TO TENDER CLAUSE # 2.2, 11.4, 13 & 35.3.2, BID BOND AMOUNTING TO USD 7,600.00 (US DOLLAR SEVEN THOUSAND SIX HUNDRED ONLY) SHOULD BE SUBMITTED WITH THE TECHNICAL BID. (2) EVALUATION CRITERIA: FULL CONSIGNMENT WISE ON C&F BY SEA, KARACHI.

SPARE PARTS ARE REQUIRED FOR ABB TURBOCHARGERS HAVING FOLLOWING SPECS: >>

ABB TURBOCHARGERS (PU - 10121 & 10122):

MODEL: TPS 57D01

SR. NOS. HT 499412 & HT 507078 AND HT 507080 & HT 505325

INSTALLED AT WAUKESHA 16V-275GL ENGINES

TERMS AND CONDITIONS FOR INDENT NO. PK/ST/286/17:

- 01- OEM AUTHORIZED DISTRIBUTORS OR OEM ONLY IS ELIGIBLE.
- 02- IN CASE OF AUTHORIZED DISTRIBUTOR ADEQUATE PROOF TO BE FURNISHED.
- **03-** THE BIDDER MAY BE REPRESENTED BY A LOCAL AGENT WITHIN PAKISTAN BUT SHOULD NOT INVOLVE ANY THIRD PARTY IN THE BIDDING.
- O4- IN CASE OF EQUIVALENT ITEMS OR SUPERSEEDED PART NO. QUOTED DUE TO ANY REASON, INSTEAD OF REQUIRED PART NOS. AS PER SCHEDULE OF REQUIREMENT, THEN 100% REPLACEMENT WITH SAME FIT & TOLERANCES ALONG WITH SUPPORTING DOCUMENTATION FROM ABB TURBO SYSTEMS MUST BE PROVIDED.
- 05- STANDARD WARRANTY / GURANTTEE FOR ALL ITEMS.
- 06- DELIVERY PERIOD: 03-04 MONTHS AFTER THE ISSUANCE OF L.C.
- 07- OEM LITERATURE (ONLY RELEVANT AND HIGH LIGHTED).
- 08- STANDARD TEST / QUALITY CONTROL DOCUMENT/CERTIFICATES.
- 09- PARTS CATALOGUE/MANUAL TO BE PROVIDED.

COMPLIANCE SHEET

INDENT# PK/ST/286/17 "PROCUREMENT OF 50K HRS MAINTENANCE SPARES FOR ABB TURBOCHARGERS (MODEL: TPS 57D01)"

S. No.	DESCRIPTION AS PER TENDER DOCUMENT	BIDDER OFFER YES / NO	DEVIATION IF ANY
1	BASIC REPLACEMENT TURBOCHARGER, MATERIAL NO. HZTL430500M0001, PART # 10100, EQUIPMENT SERIAL # HT499412RHS & HT507078LHS		
2	BLADED SHAFT (KW8TR1TT16TV1), MATERIAL NO. HZTL115665R0016, PART # 21000, EQUIPMENT SERIAL # HT499412RHS, HT507078LHS, HT507080RHS & HT505325LH		
3	COMPRESSOR WHEEL (KV11CR1CT70CV10), MATERIAL NO. HZTL220871P0070, PART # 25000, EQUIPMENT SERIAL # HT499412RHS, HT507078LHS, HT507080RHS & HT505325LH		
4	COMPRESSOR & TURBINE CHECK (SPARE PART SET # 1), MATERIAL NO. HZTL439812R0001, PART # 97070, EQUIPMENT SERIAL # HT499412RHS, HT507078LHS, HT507080RHS & HT505325LH		*
5.	BEARING CHECK (SPARE PART SET # 2), MATERIAL NO. HZTL431969R0001, PART # 97076, EQUIPMENT SERIAL # HT499412RHS, HT507078LHS, HT507080RHS & HT505325LH		
6	BEARING CHANGE (RADIAL), (SPARE PART SET # 3), MATERIAL NO. HZTL453810R0001, PART # 97081, EQUIPMENT SERIAL # HT499412RHS, HT507078LHS, HT507080RHS & HT505325LH		
7]	BEARING CHANGE (AXIAL), (SPARE PART SET # 4), MATERIAL NO. HZTL453809R0001, PART # 97084, EQUIPMENT SERIAL # HT499412RHS, HT507078LHS, HT507080RHS & HT505325LH		