

Technical Evaluation Report.

Tender inquiry# PROC-FE/CB/Engg-3211/2018.

S/No	Name of firm	Responsive/Non Responsive	Reason for rejection
1	Mitsubishi Heavy Industries Japan.	Responsive	
2	Zhejiang Hongcha Imp & Exp Co.Ltd, China.	Non Responsive	1- Engine and machine are not of same OEM. Clause 2 of terms and conditions not complied. 2- Load Capacity 5000kg @ 500 mm instead of 600 mm load centre. Clause 9 of terms and conditions not complied. 3- OEM's experience of 25 years certificate not provided. Clause 21.i not complied. 4- Dealers experience in Pakistan, record not provided. Clause 21.h not complied. 5- 3 S facilities not confirmed. Clause 21.c of terms and conditions not complied.
3	Mitsubishi Longisnext Co. ltd. Japan	Responsive	
4	Komatsu Ltd. Japan.	Responsive	
5	Anhui Heli Industrial vehicle Imp & Exp. Co. Ltd. China.	Non Responsive	1- Under size engine, Engine and machine are not of same OEM. Clause-2 of terms and conditions not complied. 2- Load capacity 5000kg @ 500mm instead of 600 mm load centre. Clause 9 of terms and conditions not complied. 3- Ground clearance is 175mm instead of 220 mm. Clause 13 of terms and conditions not complied. 4- Technical data of engine and machine not provided in original. Clause 21.a of terms and conditions not complied. 5- 3S facilities not confirmed. Clause 21.c not complied.