# **OIL & GAS DEVELOPMENT COMPANY LIMITED**



### TENDER ENQUIRY NO. PROC-SERVICES/CB/P&P-5076/2021

# HIRING OF SERVICES FOR EXECUTION OF ANNUAL TURN AROUND (ATA) 2021 OF UCH-I GAS PLANT

#### Note:

Bid bond of PKR 800,000/- (Pak Rupees Eight Hundred Thousand Only) must be submitted with the technical bid. Please see tender documents for further detail.

The master set of tender documents (services) uploaded on OGDCL website (<u>www.ogdcl.com</u>) is the integral part of this TOR.

# HIRING OF SERVICES FOR EXECUTION OF ANNUAL TURN AROUND (ATA) 2021 OF UCH-I GAS PLANT

## **TERMS & CONDITIONS**

#### **OGDCL'S RESPONSIBILITIES:**

- 1- OGDCL will provide blind/spades for isolation and pressure testing. However the blinds which are not available in stock, contactor may fabricate with available SS/MS sheets.
- 2- Only lodging (accommodation) will be provided to the Contractor manpower. The arrangement for 300 persons is available at site.
- 3- Only Emergency/First Aid medical coverage will be the responsibility of OGDCL.
- 4- All gaskets and direct material/spare parts will be provided.
- 5- OGDCL will provide paint for jobs wherever mentioned in scope of work.
- 6- OGDCL will provide pumps, tanks and hosepipes for in-place chemical cleaning of plate type heat exchangers, vessels & columns only.
- 7- Although the plant has a safe history however adequate security umbrella as provided to the Company's employees will be extended for Contractor's manpower.

#### **CONTRACTOR'S RESPONSIBILITIES:**

- 1- The technical manpower must be qualified/skilled and have at least five years experience in its trade in the field of Oil & Gas/Petrochemical Processing Plants. Contractor skilled manpower will be interviewed by OGDCL professionals in all disciplines (Mechanical, Electrical and Instrument), if deemed necessary and contractor should arrange the interview at their premises. The detailed CV's of direct manpower/supervisors is mandatory.
- 2- Contractor will ensure mobilization of all manpower and resources at least two weeks before commencement of ATA.
- 3- Skilled manpower will be deployed for seven days after completion of shutdown for testing/startup activities. Moreover, Rotary Team shall remain at site until satisfactory operation/testing of all rotary equipment. (Approximately 7-10 days after plant startup).
- 4- Locals should be given preference while hiring of skilled/unskilled manpower.
- 5- The contractor should plan ATA activities (direct/associated) using latest version of Primavera and submit their planned schedule covering all the activities for carrying out

ATA of UCH-I Gas Plant successfully with high level quality within stipulated time period. (Soft copy of Primavera Plan is mandatory with summarized plan and a detailed plan indicating critical path activities, equipment wise resource planning and deployment)

- 6- Contractor should prepare/submit daily progress report and percentage Gantt chart (planned vs actual) at end of the day.
- 7- Tools and consumables for the execution of each job including welding / fabrication consumables for all repair and modification jobs.
- 8- Painting job where ever given in the scope including painting equipment/tool like brushes, rollers, spray nozzles/guns, hosepipes etc.
- 9- Pneumatic Ejectors/Blowers for the ventilation of Columns and Vessels as per job scope requirement.
- 10- 24V Lighting arrangement for confined space jobs, i.e. inside the columns and vessels.
- 11- In case of any accident, OGDCL will provide only general first aid whereas any other medical treatment would be the responsibility of contractor.
- 12- Contractor shall arrange the standardized test bench for manual valves, control valves & PSV's pressure testing and interconnecting pipes, tubes, hoses for hydro-test and PSV's bench.
- 13- All tools, consumables and calibration equipment/tools for all instruments, control valves & PSV's should be the responsibility of contractor.
- 14- Site administration personnel with associated resources like computer, printers, photocopiers etc.
- 15- Contractor should arrange the blind flanges for PSV's, control valves and manual valves testing which will not be available at OGDCL store stock.
- 16- Contractor will arrange certified E & I calibration and testing equipments, the certificates will be submitted before execution of ATA. Original 3<sup>rd</sup> party calibration certificates will be verified by OGDCL representative upon arrival of equipment.
- 17- Nitrogen gas for PSV's and Regulators testing will be arranged by contractor.
- 18- Certified Cranes and fork lifters suitable to carry out the activities within stipulated time frame.
- 19- Precision Lathe machines for the repair of manual valves, control valves & PSV's as per work scope requirement.
- 20- Gaskets for pressure testing/bench test of manual valves, control valves & PSV's.
- 21- Water jetting machines with PSV calibration certificate and all other accessories up to 15000psig operating pressure for hydro-jetting of heat exchangers etc. as per job scope requirement.

- 22- Refractory work of Incinerators and Boilers including material is responsibility of contractor and should be carried out through any local expert firm/company in this field (Refer clause # 24 of explanatory notes).
- 23- Scaffolding material and services, as when and where required.
- 24- Electrical Supply Boards/Cables along with earth leakage circuit breaker as per HSE standard.
- 25- Pneumatic/24V tools for confined spaces i.e. grinders/power brushes (Vessel and Columns).
- 26- Contractor will arrange sufficient air compressors in view of complete scope of work (ventilation/filter cleaning/pneumatic tools etc.)
- 27- Shock absorbing safety harness and respirators for contractor employees as per job requirement.
- 28- Contractor will submit Company HSE Policy manual for implementation of safe execution of each activity with zero-injury target. In case of any accident, OGDCL will not be liable for any claim like insurance etc.
- 29- Provision of PPE'S to their manpower and each worker should display ID card (HSE concern)
- Original certificates of lifting gears, cranes, crane operators, hydro-jetting machines, drivers etc. will be mandatory checked by OGDCL HSE representative. Furthermore, contractor will submit copy of these certificates to HSE representative of OGDCL (HSE Concern)
- 31- The valid certification of welders, scaffolder etc. will be mandatory. Tags should be displayed for certified scaffolding (HSE Concern).

#### 32- HSEQ Manpower by Contractor:

- a. I/C HSEQ should be B.E Mech/Chemical with Nebosh certification with at least 05 Years of relevant experience.
- b. Supervisors should Graduate/D.A.E having Safety Courses certificates with at least 5 Years of relevant experience.
- c. HSE assistant should be at least Intermediate having Safety Courses/ certificates with at least 5 Years of relevant experience)
- d. Well-equipped First Aider & Rescuers (Trained/Certified at least 02 Nos.) e.g ropes/pulley, tri-pod, stretchers, medicines etc.
- e. HSEQ crew will be interviewed by OGDCL HSEQ representative before commencement of ATA.
- 33- Contractor shall arrange Decanting pumps for ETP Sump Pit, Cooling Tower basin, Cooling Water Pump suction pit etc. wherever mentioned in SOW.

- 34- Contractor shall submit WPS & PQR for welding jobs prior to execution of job no deviation will be permissible.
- 35- Contractor shall depute qualified quality control Engineer having Level-II, Level-III CSWIP 3.1, API certification for the supervision of welding/modification jobs.
- 36- DPT of all welding jobs (Repair work/Modifications) shall be the responsibility of main execution contractor including material.
- 37- Submit Total no's of deployed manpower list (designation wise) for the execution of individual job.
- 38- Contractor shall provide adequate meals and laundry services to their employees. Local area Contractor's may be introduced to provide such services.
- 39- Contractor will arrange transport for the pick and drop for their manpower from Colony to Plant and back for the whole period and also from Jacobabad to field & back. Fitness certificate for vehicles and drivers will be mandatory. Vehicles deployed for said purpose will be inspected by OGDCL and will not be allowed to use if found unfit.
- 40- Contractor should ensure the police verification of all manpower direct and indirect and must have bio-data file of each. (Security concern)
- 41- Contractor manpower must have CNIC and Contractor identity card.
- 42- Contractor should ensure his manpower has no any kind of ammunition and narcotics. (Security concern)
- 43- Mobiles and photo camera are prohibited in the plant premises and contractor should be ensured. (Security concern).
- 44- Contractor should deploy his own fully equipped security to control the manpower's in/out movement in plant as well as at colony with the coordination of OGDCL security incharge. (Security concern).

#### **ATA-2021 MAIN EXECUTION CONTRACTOR EXPLANATORY NOTES**

- The Owner, Oil &Gas Development Company Limited (OGDCL) is interested in inviting bids for the provision of services (Mechanical, Electrical & Instrumentation) at their UCH-I Gas Processing Plant for the execution of the Annual Turnaround (ATA) 2021 maintenance activities from reputable companies in this field.
- 2- The tentative schedule of annual shutdown of UCH-I Gas Plant is from 18-10-2021 to 29-10-2021 (12 days) after handing over of site to the contractor, only 09 days should be available for maintenance activities and remaining 01 day will be required for the shutting down and 02 days for startup activities.
- 3- The contractor shall develop and submit a detailed work schedule including mobilization and preparatory works prior to shutdown.
- 4- The Contractor shall quote separate rate in PKR for each activity against the quantities mentioned in the scope of work.

- 5- The items mentioned in the scope of work consist of furnishing all plant, labor, equipment, machinery, scaffolding and materials for completing the work. The work shall be done, complete in all respects in accordance with the requirements and owner's instructions at site.
- 6- The Quantities contained in the scope of work for each activity are estimated and liable to change (increase, decrease or omitted) when the work is actually executed. The Owner does not expressly or by implication guarantee that actual quantities of work to be performed will correspond to the scope of work submitted with this tender document. The payment to be made to the Contractor shall be based on the actual quantity of work performed.
- 7- The Contractor shall be responsible for carrying out all work, complete in all respects, according to the scope of work. Any item of work required for completion but not expressly indicated in the scope shall be deemed to have been included in the unit rates quoted by the Contractor.
- 8- The successful contractor will be required to submit detailed procedures for undertaking shutdown jobs especially repair works and modification jobs for Owner's approval.
- 9- The Contractor shall be responsible for ventilation and getting the vessels fit for entry and working environment. All other works required for equipment / piping repair works, e.g. removal / installation of internals, temporary supports, lighting, ventilation, insulation etc., shall be the Contractor's responsibility.
- 10- Contractor shall undertake welding procedures qualification & welder qualification and all welding shall be performed by qualified Welders. The brand of electrode used for Qualification shall not be changed for Production Welding. (Contractor shall use electrodes/filler wires of reputable brands of European Origin e.g. ESAB, LINCON, etc.)
- 11- The works are to be carried out on a fast track basis and it is, therefore, essential that the Contractor shall be prepared to execute the work on a round the clock basis (day & night shift) including on holidays.
- 12- Unit rates quoted by bidder shall be firm. No extra payments on account of escalation in prices due to any reason shall be admissible.
- 13- Contractor must quote unit rate per dia. inch of pipe welding (separate rate for CS & SS material) & per Kg of structure welding that will also be applicable for any additional job during ATA.
- 14- The Contractor shall be paid only for the work duly approved by Owner's representative. Any rework due to poor quality, demonstrated by NDT results & inspection by OGDCL shall be on Contractor's account.
- In case the contractor fails to arrange resources (tools, tackles, consumables, skilled manpower etc.) for execution of any job mentioned in scope of work, OGDCL will arrange/provide its resources to execute the job then the cost double the amount quoted by contractor against that specific job/equipment/area/group will be deducted from final invoice of the contractor.

- 16- The work is being executed within the plant during shutdown and the Contractor shall, therefore, abide by all safety rules and regulations required to be followed by the Owner.
- 17- The Contractor shall ensure deployment of skilled painters for painting jobs and proper surface preparation and application of primer and top coat, as per applicable industrial standards.
- 18- Removal/Re-installation of insulation where required/applicable shall be the responsibility of Contractor.
- 19- The contractor will arrange cranes and all other lifting/rigging gears for all activities to be carried out during ATA.
- 20- The Owner for any job will not provide any tools to contractor. Otherwise owner's representative will be liable to deduct the charges accordingly.
- 21- The contractor manpower should be well experienced/skilled in their respective crafts.
- 22- HSEQ Rules & Regulations will be strictly observed.
- 23- All the participating companies/contractors should have at least 5 years of similar experience especially in turnaround of Oil & Gas, Petrochemical & Fertilizers Plant.

#### 24- **REFRACTORY WORK:**

The contractor will arrange the material required for the refractory repair work of Incinerators (UCH-I & UCH-II), Boilers (UCH-I) & Hot Oil Heaters (UCH-II). The rough estimated material required for repair work is given as below:

(i)- Cow/Ceramic Wool (2'x 16' x 1" thk. Roll)	Qty: 04 Rolls
(ii)- Fire Cement (25 Kg Bag)	Qty: 20 Nos.
(iii)-Castable (25 kg Bag)	Qty: 60 N0s.
(iv)-Anchors with lock (SS)	Qty: 25 Doz.

The actual quantities of material should be confirmed after initial inspection of equipments and it is the responsibility of contractor to arrange the material accordingly.

#### 25- Stress Relieving for modification jobs piping and strippers

- All repair welds shall be stress relieved.
- Stress Relieving of existing welds shall be undertaken where weld quality is acceptable as per NDT results.
- Local Heat Treatment may be carried out using electric heaters (Bands) covered by insulation. Temperature shall be noted by thermocouples and recorded by automatic recorders. Detailed procedures shall be prepared and submitted by the Contractor for Owner's approval.
- Following procedure may be adopted for stress relieving of welds:
  - $\triangleright$  Heat up to 600 620 °C @ 100 °C per hour
  - ► Hold at 600 610 °C for 1-hour minimum.

- $\triangleright$  Slow cool @ 100  $^{\circ}$ C per hour from 600 to 300  $^{\circ}$ C.
- > Still air cool by removing insulation, from 300 °C to atm. temp.
- Take hardness profile of each weld to check if it is < 22 HRC.</p>
- The above procedures have only been provided as guidelines. Contractor shall develop and submit detailed procedures for Owner's approval for mod job and stripper repair work.

#### 26- INSPECTION/REPAIR/TESTING OF VALVES:

- The Contractor shall guote separate rates for each/individual valve.
- Individual tags (include Asset Tag & Sr. # as per SOW) shall be installed on each valve for identification of location before dismantling of valve from site.
- Contractor shall submit the method statement for testing of valves with respect to the standards specified in the references below.
- For repair and build up of seats of valves contractor shall use electrodes/filler wires of reputable brands of European Origin e.g. ESAB, LINCON, etc.
- All gate valves will be tested from both sides i.e. front and back.
- Pressure testing of valves will be carried out as per applicable ASME Code.
- Lapping of valve seats shall be carried out on high-level precision machine.
- 27- Work methodologies of Jobs (modification jobs, valve testing/repairing, Cleaning of vessels, Columns, heat exchangers and repair work of leakages in piping and pressure vessels and PWHT) will be developed by keeping in view of under-mentioned references and requirements. Furthermore contractor shall submit the welding procedure specifications with supporting PQR, method statement of repair jobs of Amine Stripper, hydro testing of mechanical valves, hydro testing of piping involved in modification jobs at least two weeks before the commencement of ATA for Owner's approval.

#### Note:

- Bid bond of **PKR 800,000/- (Pak Rupees Eight Hundred Thousand Only)** must be submitted with the technical bid. Please see tender documents for further detail.
- Following documents must be submitted with the technical bid (bid bond, bidding form, Integrity & ethics undertaking, Affidavit (duly signed & stamped by Notary Public), Data Summary Sheet, Unpriced draft contract, Unpriced financial rate format and certificate of incorporation.

# **Contractor Qualification Criteria (MARKS)**

Sr. No.	Evaluation Item	Description of Criteria	Max. Marks / Calculations	Maximum Marks	Minimum Qualifying Marks	Remarks
1.	Contractor strength to execute Mechanical, Electrical, Instrument & Telemetry works	Contractor to fully comply the execution of complete SOW provided, Explanatory Notes and OGDCL T&C's	Full Compliance (mandatory)	15	15	Contractor should submit the signed/ stamped copy of SOW, Explanatory Notes and T&C's to prove the execution of all Mechanical, Electrical, Instrument& Telemetry activities during ATA in full spirit.
2.	Specific experience of Annual Turn Around (ATA)	Contractor's experience of ATAs	Contractor shall earn 06 marks against each ATA up to maximum of 30 marks	30	18	In order to get 06 Marks for each ATA, the value/ worth of each previous ATA performed by contractor should be at least 10 Million (PKR) each.
3.	Certifications.	Contractor should provide following valid certificates; 1. ISO 9000 certification: 2. ASME U/R/S-Stamp 3. PEC Registration	1. 04 Marks  2. 03/02/02Mar ks 3. 04 Marks	15	9	Contractor should submit the valid copy of certificates. If the certificate status is in progress no marks will be given.
4.	Offices, Workshop, Tools, Equipment, Machinery, Infrastructure.	Contractor should have following facilities within Pakistan.  1. Workshop & office,  2. Tools to execute the ATA activities (Mechanical, Instrument, Electrical).  3. Equipment / Machinery (Valve test bench, hydro jetting machines, welding machines/ Generators).  4. Cranes, fork lifters.	1. 03Marks(02+01 ) 2. 08     Marks(04+02+0 2)  3. 03 Marks  4. 06 Marks (04 +	30	25	01 Mark for each main equipment / Machinery.  Crane (Min 25 tons),
		5. Relevant professional CVs & site deployment Organogram for Mechanical, Instrument & Electrical works.	02) 5. 10 Marks.			fork lifters (Min 3 Tons)  Organogram: 02 Mark.  Mechanical CVs: 04  Mark  Electrical CVs: 02Mark  Instrument CVs:  02Mark

Sr. No.	Evaluation Item	Description of Criteria	Max. Marks / Calculations	Maximum Marks	Minimum Qualifying Marks	Remarks
5.	Safety & HSE Policy	1. Contractor's documentary evidence of HSE policy with commitment to provide PPE, Helmet, Ear plugs and safety shoes to the skilled labour at work.  2. Well defined HSE policy with commitment and to provide 1 Million Safe Man hours' record.  3. Deployment of first aid boxes	1. 04 Marks for full compliance, partial compliance zero Marks.  2. 04 Marks  3. 02 Marks for full	10	08	The Contractor who will provide 1 Million safe man hours record will be awarded 04 marks while the Contractor who will provide 0.5 Million safe man hours record will be awarded 02 Marks.
		& medical team for the labour at site.	compliance, partial compliance zero Marks.			

**Minimum Qualifying Marks = 75** 

**Total Marks= 100** 

#### **FINANCIAL BID FORMAT/EVALUATION CRITERIA**

### **UCH-I Plant ATA-2021**

Sr.	Description	Price in PKR
01.	Cost of Services for ATA jobs, activity wise breakdown should	
	be providedas per enclosed document / scope of work (the	
	cost must be inclusive of all types of equipments, tools,	
	manpower, machinery, consumables and PPE) for	
	I. Mechanical works	
	II. Electrical works	
	III. Instrument works	
	IV. T&I works	
02.	Mob. / De-mob. Cost	
03.	Total cost	

#### Note:

- a) Total Price should be inclusive of all taxes (except Provincial Sales Tax/ ICT Tax on services in Pakistan), duties, levies, charges etc.
- b) Bidders are requested to quote the above mentioned rates separately for each activity of the jobs at Sr. No. 01. & provide the activity wise break down.
- c) OGDCL reserves the right to delete / cancel any activity mentioned in the scope of work at any stage of the ATA. Payment will be made as per actual job done against verified invoices in PKR.
- d) Contract will be awarded to technically responsive and financially lowest evaluated bidder on complete package basis.

		OIL & G UCH-1 GAS PROCESSI	AS DEVELOPMENT			F WORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Pomarks		Unit Rate	Total Cost
SWITC	HGEAR ROOM	M:			Location			
1	10-P-200A	LV(380V) Modules	Amine Booster			1		
2	10-P-200B	Inspection, Servicing,	P.M. Modules,			1		
3	20-P-200A	Cleaning, Testing of Contactors, Thermal	380v, 138A, 100hp Amine Booster P.	1		1		
		Relays, Aux. Contactors,	M. Modules, 380v,					
4	20-P-200B	Power Points & tightening	138A, 100hp			1		
5	10-P-202A	of all connections.	Amine S. Reflux			1		
6	10-P-202B		P.M. Modules, 380v, 15.5A, 10hp			1		
7	20-P-202A		Amine S. Reflux P.			1		
8	20-P-202B		Motor, 380v, 15.5A, 10hp			1		
9	90-X-903A		13.5A, 1011p	1		1		
10	90-X-903B		Cooling Tower Fan			1		
11	90-X-903C		Motor , 380v,			1		
12	90-X-903D		210A, 150hp			1		
13	90-P-911A			1		1		
14	90-P-911B		Raw Water P. Motor 380v,			1		
15	90-P-911C		138A, 100hp			1		
	90-P-911C 90-P-902A		L.P Boiler Feed	1				
16			Water P. Motor			1		
17	90-P-902B		380v, 66.4A, 50hp			1		
18	Siemens Pond 1		Siemens Pond			1		
19	Siemens Pond 2		water motor modules, 380 V, 40			1		
20	Siemens		HP		LV & EGTs	4		
20	Pond 3			_	MCC Modules	1		
21	HP Bolier Switchgear		H.P Boiler Switch gear			1		
22	HP Boiler Feed Water Switchgear		HP Boiler Feed Water Switchgear			1		
23	90-X-904A		Incinerator F.D Fan			1		
24	90-X-904B		Motor , 380v, 22A, 15kw			1		
25	10-P-200A		Glycol Circulation	1		1		
26	10-P-200B		P. Motor 25kw, 380v, 52amps			1		
27	20-P-200A		Glycol Circulation	1		1		
			P. Motor					
28	20-P-200B		25kw, 380v, 52amps			1		
29	UCH2-BL-ST		UCH-2 Black Start Panel	]		1		
30	1A		ADI 00			1		
31	2A		ABLOC Fan Motor 380v, 25.8A, 9.5			1		
32	3A		Kw			1		
33	4A			]		1		
34	1A					1		
35	2A		Enclosure Vent Fan Motor 380v, 55A,			1		
36	3A		30kw			1		
37	4A					1		

Page 11 of 66 OGDCL Tender Enquiry No. PROC-SERVICES/CB/P&P-5076/2021

	1						1	,
38	1A					1		
39	1B					1		
40	2A					1		
41	2B		Gen: CACA Fan			1		
42	3A		Motor 380v. 8.7A,			1		
43	3B		4kw			1		
					-			
44	4A					1		
45	4B					1		
46	1A					1		
47	2A		VGV Motor 380v,			1		
48	3A		3.6A, 1.5kw			1		
49	4A					1		
50	1A					1		
51	2A		Starter Motor,			1		
52	3A		380v, 75kw			1		
53	4A		·			1		
33	44		LV incomer of trafo					
54	Incomer Tafo		1 & 2, ACB, 3200		LV incomer of	2		
	1 & 2		Amp,TERASAKI		Trafo 1 & 2			
			ACBs installed on		LV Bus 181 &			
55	LV Bus ACBs		LV Bus 2000 Amp,		176 ACBs	2		
			TERASAKI ACBs installed on					
	Essential Bus		Essentia bus 1200		Essential Bus			
56	ACBs		Amp & 800 Amp,		ACBs	2		
			Merlin Gerin					
		LV(380V) Bus Bar						
57	LV Bus	Inspection, Cleaning,	LV Bus Bar 176,181		LV Bus Bar	2		
		Tightening, Maggar of Bus Bars						
58	10-P-201A	5413	Amine Circulation			1		
			P. Motor, 6.6kv,		-			
59	10-P-201B		117A, 1500hp			1		
60	20-P-201A		Amine Circulation			1		
61	20 D 201D		P. Motor 20-P-201, 6.6 Kv, 117A,			1		
61	20-P-201B		1500hp			1		
62	90-P-900A	MV(6.6KV) Modules	Cooling Water			1		
63	90-P-900B	Inspection, Servicing,	Circulation			1		
64	90-P-900C	Cleaning, Testing of	P. Motor, 6.6kv,		ŀ	1		
		Contactors, Thermal	67A, 700hp L. P. Boiler F. D.					
65	90-X-902A	Relays, Aux. Contactors,	Fan Motor, 6.6kv,		-	1		
66	90-X-902B	Power Points, & Tightening of all	20A, 250hp		MV Modules	1		
67	52-A	connections. <b>Measurement</b>	Main Incoming		IVI V IVIOUUIES	1		
68	52-B	of VCB closing time and	Vacuum Circuit			1		
		opening time for EGTs	Breaker 52 A/B/Tie, 6.6kv,					
69	52-T	VCBs ( 04 Nos, 630 Amps,	1200A			1		
		make: ABB) with help of proper, calibrated tools	Vacuum Circuit					
70	Transformer	and equipments	Breaker of			2		
, ,	MV Modules		Transformer 1 & 2,			_		
		25	2500 KVA, 6.6KV Vacuum Circuit		-			
			Breaker of EGTs					
71	EGT VCBs	CBs and Unit		5				
	EGI VCBS		Transformer,					
			6.6KV					

						I	1
72	Transformers	Inspection, cleaning of transformers, BTD and tightening of power & control connections.	Transformer 1 and 2, Unit Transformer, UCH- 2 Black Start Transformer	Transformers	4		
73	MV Bus	MV(6.6KV) Bus Bar Inspection, Cleaning, and Tightening of Bus Bars	MV Bus Bar	MV Bus Bar	1		
74	1	Battery Charger and Battery Bank			1		
75	2	Inspection, Cleaning, Checking And Tightening of			1		
76	3	connections, Chargers & Battery Cabinets. Batteries	Battery Chargers and Battery Banks	Battery Room	1		
77	4	Inspection, load testing, tightening, greasing of connections & Servicing. Replacement of bank if required after inspection.	1				
78	1	Inspection, Tightening of connections, Preventive maintenance on by pass	30 KVA UPS		1		
79	1	mode and general cleaning. Batteries Inspection, load testing, tightening, greasing of connections & Servicing. Replacement of bank if required after inspection.	30 KVA UPS (Stand by)	UPS	1		
80	X-200A	- 1 - 1 - 1 - 1 - 1	Inst. Air Comp.		1		
81	X-200B	LV(380V) Modules		1			
82	X-200C	Cleaning, Testing of	Quincy Inst. Air	Instrument	1		
83	X-200D	Contactors, Thermal Relays, Aux. Contactors,	Comp. Motor, 380v, 67A, 50hp	Air Compressors	1		
84	X-201A(181)	Power Points, Tightening of	Inert Gas Comp.		1		
85	X-201B(176)	all connections.	Motor, 380v, 44A, 30hp		1		
86	1	<b>EGT Generators</b> Checking of Generators'			1		
87	2	connections, Exciters, PMGs,Diode Assembly.	Main Generator,		1		
88	3	Inspection and removal of dust and webs. Cleaning &	PMG & Exciter Units.	EGTs	1		
89	4	Washing of Generator's outer body.			1		
90	LP3-MCC	LV(380V) Modules Inspection, Servicing, Cleaning, Testing of Contactors, Thermal Relays, Aux. Contactors, Power Points, Tightening of all	MCC Panel of LP Boiler 3	LP boiler 3	5		
91		Allied Services for Electric Supply At Different Locations of Plant.	Allied Services				
92		Cleaning, testing and resistivity measurement of Earth pits at UCH-1 and Colony	Earth Resistance Measurement	Whole Plant	35		
93		Maintenance, cleaning, refurbishement, replacement (if required) of skid(2x36W) and	Job on Skid and Pole lights	Amine, Dehydration , EGTs, Utility Systems,	200		

		ploelights ( 250W, 400W)			Colony			
		at UCH-1 and Colony			Cololly			
		,	LT Switch Gear &		11/ 5			
94	1 job		Transformer		LV Switch Gear,	1		
34	1 100		Installed in		Transformer	-		
		Inspection, Cleaning Of	Residential Colony					
		Switch Gear, Transformer,	LT Switch Gear					
		DBs, tightening of control and power cables.	having MCCs & Transformer		Gear,	LV Switch		
95	1 job	and power cables.	installed at Pat		Transformer	1		
			Feeder Water		and MCCs			
			Pumping Station					
		Inspection, servicing						
		cleaning, tightness of DBs	Maintenance of					
96		Installed in plant area,	DBs		LT DBs	20		
		workshops, offices and	-					
		admin building of UCH-1						
		Inspection, servicing cleaning, tightness of DBs						
		Installed in different Areas	Maintenance of					
97		of UCH Colony and colony	DBs		LT DBs	15		
		water supply motor						
		modules						
		Preventive maintenance						
		job on heater and						
		superheater installed with fuel gas skid of EGTs. Job	Inpection of heater		EGTs fueld			
98	1 job	will include inspection and	and superheater		Gas Skid	1		
		replacement if required for	· ·		Gus Siliu			
		bundle of heater and super						
		heater						
		Inspection, Servicing,						
		Cleaning, Testing of	Maintananas af		LCD Coultab			
99	1 job	Contactors, Thermal Relays, Aux. Contactors,	Maintenance of LCB Switchgear		LCB Switch Gear	1		
		Power Points, Tightening of			Geai			
		all						
		Excavation/Conctruction of						
		earth pits, boring job,	_					
		copper rod insertion and	Construction of					
100		earthing cable	earth pits and connection with		Plant Area	16		
100		laying/termination to connect it with main	main earthing		Plant Area	10		
		earthing system of plant.	system					
		Job complete in all	.,					
		respects.						
H2S R	EMOVAL PLAI	NT AREA MOTORS			Location			
1	10-P-201A	MV (6.6KV) MOTORS	Amine Circulation			1		
	10-L-701H	Cleaning of motor and heat exchanger, Meggering Of	P. Motor,		Train – 10	_		
	10	Windings, Inspection,	6.6kv, 117A,		110111 – 10			
2	10-P-201B	Tightening Of Connections	1500hp			1		
3	20-P-201A	In JBs, And Earth Testing.	Amine Circulation			1		
	201 ZUIA	Bearings clearance check.	P. Motor,					
	20.5.2015	Replacement Of Bearings	6.6kv, 117A,		Train – 20	_		
4	20-P-201B	(If Required after Inspection)	1500hp			1		
_	10 D 2004		Amine Booster P.			1		
5	10-P-200A	LV (380V) MOTORS Cleaning, Greasing &	Motor,		Train – 10	1		
6	10-P-200B	Replacement Of Bearings	380v, 138A, 100hp			1		
7	20-P-200A	and Paint Job (If Required),	Amine Booster P.			1		
8	20-P-200B	Meggering Of Windings,	Motor,		Train – 20	1		
		Inspection, Tightening Of	380v, 138A, 100hp					
9	10-P-202A	Connections In JBs and	Amine S. Reflux P.		Train – 10	1		

					1		ı	1
10	10-P-202B	Earth Testing	Motor, 380v,			1		
11	20-P-202A		15.5A, 10hp Amine S. Reflux P.			1		
			Motor,		Train – 20			
12	20-P-202B		380v, 15.5A, 10hp			1		
UTILIT	Y AREA MOT	ORS			Location			
		MV (6.6KV) MOTORS						
13	90-P-900A	Cleaning, Greasing				1		
		,Meggering Of Windings,	Cooling Water					
1.4	00 D 000D	Inspection, Tightening Of Connections In JBs, Earth	Circulation P.		Cooling			
14	90-P-900B	Testing and Paint Job.	Motor,		Tower	1		
		Replacement of Bearings	6.6kv, 67A, 700hp					
15	90-P-900C	(If Required after						
		Inspection)						
16	90-X-903A	LV (380V) MOTORS				1		
10	30 X 303X	Cleaning, Greasing &						
17	90-X-903B	Replacement Of Bearings	Cooling Tower Fan		Top Of	1		
		and Paint Job (If Required), Meggering Of Windings,	Motor,		Cooling			
18	90-X-903C	Inspection, Tightening Of	380v, 210A, 150hp		Tower	1		
		Connections In JBs, And			-			
19	90-X-903D	Earth Testing.				1		
UTILIT	Y AREA MOT	ORS			Location			
20	90-P-901A	LV (380V) MOTORS	Treated Water P.			1		
21	90-P-901B	Cleaning, Greasing &	Motor,			1		
22	90-P-901C	Replacement Of Bearings	380v, 14.5A, 10hp		Diametra Da	1		
23	90-P-902A	and Paint Job (If Required), Meggering Of Windings,			Blow The De- Rater Tank.	1		
24	90-P-902B	Inspection, Tightening Of	L.P.B. Feed Water		Rater rank.	1		
25	90-P-902C	Connections In JBs, And	P. Motor, 380v, 66.4A, 50hp			1		
26	90-P-902D	Earth Testing.	300V, 00.4A, 30Hp			1		
		LV (380V)						
27	90-P-903B	MOTORSCleaning,				1		
		Greasing & Replacement	H.P.B. Feed Water		Below The			
28	90-P-903C	Of Bearings and Paint Job	P Motor 380V		De-Rater	1		
		(If Required), Meggering Of Windings, Inspection,	40HP, 53A		Tank.			
29	90-P-903D	Tightening Of Connections				1		
29	90-2-9030	In JBs, And Earth Testing.				1		
	00.11.000.1	MV (6.6KV) MOTORS						
30	90-X-902A	Cleaning, Greasing, &				1		
		Replacement Of Bearings,						
		Paint Job (If Required)	F. D. Fan Motor		L.P. Boiler			
31	90-X-902B	Meggering Of Windings,	6.6kv, 20A, 250hp		"A" & "B"	1		
		Inspection, Tightening Of Connections In Jbs, And						
		Earth Testing.						
			H.P. Boiler Air					
32	HP-1	LV (380V) MOTORS	Blower Motor			1		
		Cleaning, Greasing &	380v, 4.5A, 2.2kw					
		Replacement Of Bearings, Paint Job (If Required),	H.P. Boiler FD Fan		[			
33	HP-1	Meggering Of Windings,	Motor		H.P Boiler	1		
		Inspection, Tightening Of	380v, 22A, 15kw					
24	110.3	Connections In Jbs, And	H.P. Boiler Air			4		
34	HP-2	Earth Testing.	Blower Motor 380v, 22A, 11kw			1		
		LV (380V) MOTORS	3001, 221, 11KW					
		Cleaning, Greasing &						
		Replacement Of Bearings,	Boiler Air Blower					
35	90-X-902C	Paint Job (If Required),	Motor	L.P.3 Boiler	1			
, ,	30 A 302C	Meggering Of Windings,	400V,271A,160KW,		-			
		Inspection, Tightening Of	- , : =: ,200,					
		Connections In Jbs, And Earth Testing.						
		Laitii i Cotiiig.			I		l	

36	L.P.3-A	LT (380V) MOTORS			1		
37	L.P.3-B	Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.	L.P.3 B. Feed Water P. Motor 400V, 92.9A, 55KW	L.P.3 Boiler	1		
	I	ON (TURBINE) AREA MOTOR	<u>S</u>	Location			
38	1A	LV (380V) MOTORS	ABLOC Fan Motor	-	1		
39	2A	Cleaning, Greasing &	380v, 25.8A, 9.5	-	1	<del>                                     </del>	
40	3A 4A	Replacement Of	Kw	F 622	1 1		
42	1A	Bearings,Paint Job (If Required), Meggering Of		European Gas Turbines	1		
43	2A	Windings, Inspection,	Enclosure Vent Fan	Turbines	1		
44	3A	Tightening Of Connections	Motor	-	1		
45	4A	In Jbs, And Earth Testing.	380v, 55A, 30kw		1		
46	1A				1		
47	1B				1		
48	2A				1		
49	2B	LV (380V) MOTORS	Gen: CACA Fan	European Gas	1		
50	3A	Cleaning, Greasing &	Motor	Turbines	1		
51	3B	Paint Job (If Required), Meggering Of Windings,	380v. 8.7A, 4kw		1		
52	4A			-	1		
53	4B	Inspection, Tightening Of		-	1		
54	1A	Connections In Jbs, And			1	+	
55	2A	Earth Testing.			1		
			VGV Motor	European Gas Turbines		-	
56	3A		380v, 3.6A, 1.5kw	Turbines	1	-	
57	4A	MOTORS		l a sation	1		
INCIN	ERATOR AREA	LV (380V) MOTORS	Г	Location			
58	90-X-904A	Cleaning, Greasing & Replacement Of Bearings and Paint job (If Required), Meggering Of Windings,	Incinerator F.D Fan Motor,	Incinerator	1		
59	90-X-904B	Inspection, Tightening Of	380v, 22A, 15kw				
		Connections In Jbs, And Earth Testing.			1		
AMIN		Earth Testing.  ANK AREA MOTORS		Location	1		
<b>AMIN</b> 60		Earth Testing.  ANK AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings, Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections	Amine Sump Motor 380v, 6A, 4kw	Amine Storage Tank Area	1		
60	<b>E STORAGE TA</b> 90-P-905A	Earth Testing.  ANK AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing &  Replacement Of  Bearings, Paint Job (If  Required), Meggering Of  Windings, Inspection,	Motor	Amine Storage Tank			
60	<b>E STORAGE TA</b> 90-P-905A	Earth Testing.  ANK AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings, Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.  AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing &	Motor	Amine Storage Tank Area			
60 RAW !	90-P-905A	Earth Testing.  ANK AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings, Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.  AREA MOTORS  LV (380V) MOTORS	Motor 380v, 6A, 4kw Raw Water P. Motor	Amine Storage Tank Area	1		
60 RAW 1	90-P-905A  WATER PUMP 90-P-911A	Earth Testing.  ANK AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings, Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.  AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required),	Motor 380v, 6A, 4kw	Amine Storage Tank Area  Location  Pond Water	1		
60 RAW 1 61 62 63	90-P-911A 90-P-911B	Earth Testing.  ANK AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings, Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.  AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.	Motor 380v, 6A, 4kw Raw Water P. Motor	Amine Storage Tank Area  Location  Pond Water	1 1		
60 RAW 1 61 62 63	90-P-911B 90-P-911C	Earth Testing.  ANK AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings, Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.  AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.	Motor 380v, 6A, 4kw Raw Water P. Motor	Amine Storage Tank Area  Location  Pond Water Area	1 1		
60  RAW 1 61 62 63  COMP	90-P-911A 90-P-911C PRESSOR AREA	Earth Testing.  ANK AREA MOTORS  LV (380V) MOTORS  Cleaning, Greasing & Replacement Of Bearings, Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.  AREA MOTORS  LV (380V) MOTORS Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.	Motor 380v, 6A, 4kw Raw Water P. Motor 380v, 138A, 100hp	Amine Storage Tank Area  Location  Pond Water Area	1 1 1		

66	X-200A	Required), Meggering Of	Inst. Air Comp.			1			
00	X-200A	Windings, Inspection,	Condenser Fan		-				
67	X-200B	Tightening Of Connections	Motor (Caps),			1			
07	X-200B	In Jbs, And Earth Testing.	380v, 22A, 15HP			-			
68	X-200C	,	Quincy Inst. Air			1			
			Comp. Motor,						
69	X-200D		380v, 67A, 50hp			1			
70	X-201A(181)		Inert Gas Comp.			1			
			Motor, 380v, 44A,						
71	X-201B(176)		30hp			1			
FIRE V	VATER STORA	GE TANK AREA MOTORS			Location				
		LV (380V) MOTORS							
72	160-P-101A	Cleaning, Greasing &				1			
		Replacement Of Bearings	Fire Water P.		l				
		(If Required), Meggering Of	Motor (Jockey)		Fire Water				
73	160-P-101B	Windings, Inspection,	, 380v, 21.2A, 15hp		Storage Tank	1			
/3	100-P-101B	Tightening Of Connections					1		
		In JBs, And Earth Testing							
	40 5 2004	11/ /2001/\ MOTORC	Glycol Circulation						
74	10-P-200A	LV (380V) MOTORS Cleaning, Greasing &	P. Motor		Train-10	1			
75	10-P-200B	Replacement Of Bearings	25kw, 380v,		114111 10	1			
/5	10-P-200B	and Paint Job (If Required),	52amps						
76	20-P-200A	Meggering Of Windings,	Glycol Circulation			1			
		Inspection, Tightening Of	P. Motor,		Train-20				
77	20-P-200B	Connections In JBs, And	25KW, 380V,			1			
		Earth Testing	52Amps						
	005 :	Replacement of Bearings if	Glycol Sump P.		Dehydration	1			
78	GSP A	Required	Motor		Area	1			
-		11//2001/\ 1107070	380v, 6A, 4kw						
		LV (380V) MOTORS							
79	170-P-101A	Cleaning, Greasing &				1			
		Replacement Of Bearings	ETD Cump D. Motor						
		and Paint Job (If Required), Meggering Of Windings,	380v, 15kw		ETP Area				
		Inspection, Tightening Of	JOUV, TJKW						
80	170-P-101B	Connections In JBs, And				1			
		Earth Testing							
	1		Cost (Electrical SOV	۸/۱	ı		I		
		TOTAL	Cost (Electrical 301	v )					

#### OIL & GAS DEVELOPMENT COMPANY LIMITED

#### UCH-I GAS PROCESSING PLANT - ATA 2021 (INSTRUMENT SCOPE OF WORK)

Act#	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Linia Det	Tatal
		H2S Removal Plant T	•		Location		Unit Rate	Total cost
1	10-PCV-1280		Size: 10" CL 150 Fisher Control Valve	Screw Driver Set,	REFLUX DRUM	1		
2	10-TCV-1112	To record as found calibration data. Site calibration and integrity checks of actuator,	Size: 4" CL 150 Fisher Control Valve	Terminal Screw Drivers, Spanner Set mm/Inch,	STEAM TO INLET GAS	1		
3	10-PCV-1106	positioner, I/P converter. Loop calibration through DCS.	Size: 6" CL 600 Fisher Control Valve	Multimeter, mA Current	CONTAC TOR OUTLET	1		
4	10-TCV-1254		Size: 8" CL 150 Fisher Control Valve	Communicator , consumables	BYPASS OF STRIP EX.	1		
5	10-PCV-1103		Size: 12" CL 600 AES(ROBOTARM)		MAIN INLET	1		
6	10-LCV-1140		Size: 1" CL 600 Fisher Control Valve		CONTAC TOR OUTLET	1		
7	10-LCV-1203		Size: 8" CL 150 Fisher Control Valve		FLASH DRUM O/L TO STRP.	1		
8	10-PCV-1200		Size: 4" CL 150 Fisher Control Valve	Valve Lifting and shifting equipment, Scrwe Driver	FLASH DRUM	1		
9			Size: 6" CL 600 Fisher Control Valve		CIR PUMP TO CONTAC TOR	1		
10	10-LCV-1136	inspection, lapping of plug/seat (if reqd.), hydro testing, replacement of kits, actuator integrity	Size: 6" CL 600 Fisher Control Valve		FLASH DRUM O-LET TO STR	1		
11	10-LCV-1276	testing and calibration, service of pneumatic regulator, I/P converter &	Size: 2" CL 150 Control Valve Fisher	mm/Inch,	REFLUX DRUM LEVEL	1		
12	10-LCV-102	positioner. Inspection/testing of SOVs (if required). Loop testing with DCS. Replacement of Poritioner if required	Size: 1" CL 600 Fisher Control Valve	Source, HART Communicator	P/W INLET GAS SEPARAT OR	1		
13	10-LCV-104	S F V S F V S F V	Size: 1" CL 600 Fisher Control Valve		HC INLET GAS SEPARAT OR	1		
14	10-LCV-9314		Size: 3" CL 150 Fisher Control Valve		STEAM CONDAN SATE POT	1		
15	10-FCV-9315		Size: 1- 1/2" CL 150 Fisher Control Valve		STEAM TO STRIPPER	1		
16	10-PCV-1217		Size: 2" Regulator, Make: Fisher		Surge Drum	1		
17	10-PCV-1218		Size: 2" Regulator, Make: Fisher		BLANKET ING	1		

					REGULAT OR		
18	10-SDV-101	Greasing, testing of loop & on/off position, verification of position	Size: 1" CL 600 EL- O-MATIC	Grease Gun, all	INLET GAS SEPT	1	
19	10-SDV-102	switches, service of all local pneumatic regulators, loop testing, testing/overhauling of SOVs	Size: 1" CL 600 EL- O-MATIC	necessarytools for the job		1	
20	10-XSV-1101	Greasing, testing of loop & on/off position, verification of position	SIZE:12" CL 600 Rotork		TREATED GAS OUTLET	1	
21	10-XSV-1102	switches, service of all local pneumatic regulators, loop testing,	SIZE:12'' CL 600 Rotork			1	
22	10-XSV-1144	testing/overhauling of SOVs.	SIZE:10'' CL 600 Rotork		AMINE CONTAC TOR O/L	1	
23	10-PT-1103	Onsite pressure calibration, leak test of	Pressure		MAIN INLET	1	
24	10-PT-1106	connectors, checking of isolating valves, loop verification.	Transmitter Rosemount		FLARE INLET	1	
25	10-FT-1133	Dismantling, shifting to W/S, Record as fond calibration data, Sensor		Screw Driver Set,	CIR PUMP TO CONT	1	
26	10-FT-1269	and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.	Flow Transmitter Rosemount	,	REF PMP TO STRPP	1	
27	10-FT-1107	Onsite calibration, leak test of connectors, checking of isolating valves, loop verification.	Flow Transmitter Rosemount	mA Current Source, Resistance box, Pressure	MAIN GAS INLET	1	
28	10-FT-9311	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning, Calibration,		Calibrators	STEAM TO REBOILE R	1	
29	10-FT-9315	re-installation, leak test of connectors, checking of isolating valves, loop verification.	Rosemount	Ranges.HART Communicator , consumables.	STEAM TO STRIPPER	1	
30	10-DPT-1151	Onsite calibration, leak test of connectors, checking of isolating	DP Transmitter		ACROSS CONTAC TOR	1	
31	10-DPT-1292	valves, loop verification. Dismanteling and overhauling if required	Rosemount		ACROSS STRIPPER	1	
32	10-LT-102			Spanners Set	INLET SEPERAT OR P/W	1	
33	10-LT-104	Level troll internal cleaning, Sensor inspection and setting,		(In/mm) Screw Drivers Set Hex Key set.	HINLEI	1	
34	10-LT-1140	field signal electric connection checking, onsite calibration, verification and loop	Masoneilan Pir Masoneilan 1 Tr. nyl	er Pipe Wrench 18", 12" <sup>2</sup> . Transparent nylon tube of 1" dia. 10	OVERHE AD SCRUBBE R	1	
35	10-LT-1203	testing.			FLASH DRUM	1	
36	10-LT-1219			meter leligili.	SURG DRUM	1	

ĺ	1	I	I		DEELLING		1	I
37	10-LT-1276				REFLUX DRUM	1		
38	10-LT-9314				STEAM CONDEN SATE POT	1		
39	10-LT-1136	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning, Calibration,	Level Transmitter Rosemount		CONTAC TOR	1		
40	10-LT-1250	re-installation, leak test of connectors, checking of isolating valves, loop verification.		Communicator	STRIPPER	1		
41	10-TT-1139	Integrity testing of sensor,		Spanners Set(In/mm)	CONT.FL ASH DRUM	1		
42	10-TT-1253	onsite calibration of transmitters, checking of	RTDs	Set Multi-	STRIPPER TO XHE	1		
43	10-TT-1254	electric signals and verification of complete		meter Temperature	XHE TO STRIPPER	1		
44	10-TT-1264	loop.		Bath (500DegF)	STRIPPER TOP	1		
45	DPI-10	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.	Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, Resistance box, Pressure Calibrators Low Pressure and High Pressure Ranges.HART Communicator	H2S Train 10 (Coaleser Filters Train 10/)	1		
	151 .5			consumables.				
46	emoval Plant 1 20-PCV-2280	To record as found	Size: 10" CL 150 Fisher Control Valve	Screw Driver Set,	REFLUX DRUM	1		
47	20-TCV-2112	calibration data. Site calibration and integrity checks of actuator,	Size: 4" CL 150 Fisher Control Valve	Terminal Screw Drivers, Spanner Set mm/Inch,	STEAM TO INLET GAS	1		
48	20-TCV-2254	Loop calibration through DCS. Provide soft and hard		Multimeter, mA Current Source, HART	BYPASS OF STRIP EX.	1		
49	20-PCV-2106	copies of assignments.	Size: 8" CL 150 Fisher Control Valve	Communicator , consumables	CONTAC TOR OUTLET	1		
50	20-PCV-2103	Dismantling, shifting to W/S, body & trim	Size: 12" CL 600 AES(ROBOTARM)		MAIN INLET	1		
51	20-LCV-2140	inspection, lapping of plug/seat (if reqd.), hydro testing, replacement of	Size: 1" CL 600 Fisher Control Valve	equipment, Scrwe Driver Set, Terminal	CONTAC TOR OUTLET	1		
52	20-LCV-2203	kits, actuator integrity testing and calibration, service of pneumatic regulator, I/P converter &	Size: 8" CL 150 Fisher Control Valve	Spanner Set mm/Inch,	FLASH DRUM O/L TO STRP.	1		

53		positioner. Inspection/testing of SOVs	Size: 4" CL 150 Fisher Control	mA Current	FLASH	1	
		(if required). Loop testing	Valve	Source, HART	DRUM		
54	20-FCV-2133	with DCS, Replacement of Poritioner if required	Size: 6" CL 600 Fisher Control Valve	consumables	CIR PUMP TO CONTAC TOR	1	
55	20-LCV-2136		Size: 6" CL 600 Fisher Control Valve	0	FLASH DRUM O-LET TO STR	1	
56	20-LCV-2276		Size: 2" CL 150 Control Valve Fisher		REFLUX DRUM LEVEL	1	
57	20-LCV-102		Size: 1" CL 600 Fisher Control Valve	   C   S	P/W INLET GAS SEPARAT OR	1	
58	20-LCV-104		Size: 1" CL 600 Fisher Control Valve		HC INLET GAS SEPARAT OR	1	
59	20-LCV-9514		Size: 3" CL 150 Fisher Control Valve		STEAM CONDAN SATE POT		
60	20-FCV-9515	Dismantling, shifting to W/S, body & trim inspection, lapping of	Size: 1- 1/2" CL 150 Fisher Control Valve	Nalva Litting	STEAM TO STRIPPER		
61	20-PCV-2217	plug/seat (if reqd.),	Size: 2" Regulator, Make: Fisher	Scrwe Driver Set, Terminal			
62	20-PCV-2218	actuator integrity testing and calibration, service of pneumatic regulator, I/P converter &	Make: Fisher	mA Current	BLANKET ING REGULAT OR	1	
63	20-SDV-101	Greasing, testing of loop & on/off position, verification of position	Size: 1" CL 600 EL- O-MATIC	Grease Gun, all	INLET GAS SEPT	1	
64	20-SDV-102	switches, service of all local pneumatic regulators, loop testing, testing/overhauling of SOVs.	Size: 1" CL 600 EL- O-MATIC	necessarytools	INLET GAS SEPT	1	
65	20-XSV-2101	Greasing, testing of loop & on/off position,	SIZE:12'' CL 600 Rotork		TREATED GAS OUTLET	1	
66	20-XSV-2102	verification of position switches, service of all local pneumatic regulators, loop testing,	SIZE:12'' CL 600 Rotork	Grease Gun, all necessarytools for the job		1	
67	20-XSV-2144	testing/overhauling of SOVs.	SIZE:10'' CL 600 Rotork		AMINE CONTAC TOR O/L	1	
68	20-PT-2103	Onsite pressure calibration, leak test of connectors, checking of	Pressure Transmitter		MAIN INLET	1	
69	20-PT-2106	isolating valves, loop verification.	Rosemount	Screw Drivers,	FLARE INLET	1	

		Dismanelingand overhauling if required.		mm/Inch, Multimeter,						
70	20-FT-2133	Dismantling, shifting to W/S, Record as fond calibration data, Sensor		mA Current Source, Resistance box, Pressure	CIR PUMP TO CONT	1				
71	20-FT-2269	and cleaning, Calibration, re- installation, leak test of connectors, checking of isolating valves, loop verification.	Flow Transmitter Calib Rosemount Low and I Press Rang	Calibrators Low Pressure and High	Calibrators Low Pressure and High Pressure Ranges.HART	Low Pressure F and High 7 Pressure S	Low Pressure F and High T Pressure S Ranges.HART	REF PMP TO STRPP	1	
72	20-FT-2107	Onsite calibration, leak test of connectors, checking of isolating valves, loop verification. Dimantling, Sensor cleaning or replacement if required.	Flow Transmitter	consumables.	MAIN GAS INLET	1				
73	20-FT-9511	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning, Calibration,	Rosemount		STEAM TO REBOILE R	1				
74	20-FT-9515	re-installation, leak test of connectors, checking of isolating valves, loop verification.			STEAM TO STRIPPER	1				
75	20-DPT-2151	test of connectors,	Diff Pressure Transmitters		ACROSS CONTAC TOR	1				
76	20-DPT-2292	checking of isolating valves, loop verification.	Transmitters Rosemount		ACROSS STRIPPER	1				
77	20-LT-102				INLET SEPERAT OR P/W	1				
78	20-LT-104			Spanners Set	INLET SEPERAT OR H/C	1				
79	20-LT-2140	Level troll internal cleaning, Sensor inspection and setting,		(In/mm) Screw Drivers Set Hex Key set. Multi-meter	OVERHE	1				
80	20-LT-2203	field signal electric connection checking,	Level Transmitter Masoneilan	Pipe Wrench 18", 12" <sup>2</sup> .	FLASH DRUM	1				
81	20-LT-2219	onsite calibration, loop testing.		Transparent nylon tube of 1" dia, 10	SURG DRUM	1				
82	20-LT-2276			meter length.	REFLUX DRUM	1				
83	20-LT-9514	-			STEAM CONDEN SATE POT	1				
84	20-LT-2136	Dismantling, shifting to W/S, Record as fond calibration data, Sensor		Screw Driver Set, Terminal	CONTAC TOR	1				
85	20-LT-2250	and cleaning,	Level Transmitter Rosemount  n	Screw Drivers, Spanner Set	STRIPPER	1				

86	20-LT-9501	Onsite calibration, leak test of connectors, checking of isolating valves, loop verification. Dimantling, Sensor cleaning or replacement if required.		Resistance box, Pressure Calibrators Low Pressure and High Pressure Ranges.HART Communicator		1	
87	20-TT-2139			Spanners	CONT.FL ASH DRUM	1	
88	20-TT-2253	Integrity testing of sensor, onsite calibration of transmitters, checking of		Set(In/mm) Screw Drivers Set Multi-	STRIPPER TO XHE	1	
89	20-TT-2254	electric signals and verification of complete	RTDs r	meter, Temperature	XHE TO STRIPPER	1	
90	20-TT-2264	-loop.		Bath (500DegF)	STRIPPER TOP	1	
91	DPI-20	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.	Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, Resistance box, Pressure Calibrators Low Pressure and High Pressure Ranges.HART Communicator , consumables.	H2S Train Train 20 (Coaleser Filters Train 20)	1	
Dehvd	ration Train -	· <b>10</b>		consumables.	Location		
92	10-PCV-100	To record as found calibration data. Site calibration and integrity	Size: 12" CL 600 Fisher Control Valve		DEHY O/L TO SALE GAS	1	
93	10-PCV-111	checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard	Size: 6" CL 600 Fisher Control Valve		SCRUBBE R OUT TO FLARE	1	
94	10-PCV-215	copies of assignments. Replacement of Poritioner if required	Size: 1" CL 150 Fisher Control Valve	Spanner Set	FLASH DRUM TO FLARE	1	
95	10-LCV-108	Dismantling, shifting to W/S, body & trim inspection, lapping of plug/seat (if reqd.), hydro	Size: 1" CL 600 Fisher Control Valve	mm/Inch, Multimeter, mA Current Source, HART	INTEGRA L SCRUBBE R	1	
96	10-LCV-112	testing, replacement of kits, actuator integrity testing and calibration,	Size: 1- 1/2" CL 600 Fisher Control Valve	Communicator , consumables	GLYCOL CONTAC TOR	1	
97	10-LCV-208	service of pneumatic regulator, I/P converter & positioner.	Size: 1- 1/2" CL 150 Fisher Control Valve		FLASH DRUM	1	
98	10-TCV-200	Inspection/testing of SOVs (if required). Loop testing with DCS.Replacement of	Size: 4" CL 300 Fisher Control Valve		STEAM LINE TO REBOILE	1	

		Poritioner if required			R		
99	10-LCV-108		Size: 1" CL 600 Fisher Control Valve		INTEGRA L SCRUBBE R	1	
100	10-FT-100				DEHY INLET	1	
101	10-FT-101A				DEHY OUTLET	1	
102	10-FT-101B	Onsite calibration, leak			DEHY OUTLET	1	
103	10-FT-200	test of connectors, checking of isolating valves, loop verification. Dismantelling, Sensor		Screw Driver Set,	DEHY REBOILE R	1	
104	10-FT-201	cleaning, replacement if required		Terminal Screw Drivers, Spanner Set mm/Inch,	GLYCOL PUM OUTLET	1	
105	10-LT-206			Multimeter, mA Current	SURGE DRUM	1	
106	10-DPT-107	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.  Onsite calibration, leak test of connectors, checking of isolating	Transmitter	Source, Resistance	CONTAC TOR	1	
107	10-DPT-213		Rosemount	box, Pressure Calibrators Low Pressure	CARTRID GE FILTER	1	
108	10-DPT-214			and High Pressure Ranges.HART Communicator	CHARCO L FILTER	1	
109	10-PT-201			consumables.	REBOILE R PRESSUR E	1	
110	10-PT-203	valves, loop verification.  Dismantelling, Sensor			REBOILE R.INLET	1	
111	10-PT-215	cleaning, replacement if required			FLASH DRUM	1	
112	10-PT-100			Screw Driver Set, Terminal Screw Drivers,	SYSTEM PRESSUR E	1	
113	10-PT-109	Onsite calibration, leak		Spanner Set mm/Inch, Multimeter,	SALE GAS	1	
114	10-PT-212	test of connectors, checking of isolating valves, loop verification. Dismantelling, Sensor cleaning, replacement if required	Transmitter Rosemount	mA Current Source, Resistance box, Pressure Calibrators Low Pressure and High Pressure Ranges.HART Communicator , consumables.	GLYCOL PUMP OUTLET	1	
115	10-LT-108	On Site Level troll internal Cleaning, Sensor cleaning and setting, Field signal	Level Troll		INTEGRA L SCRUBBE R	1	
116	10-LT-112	electric connection checking, Calibration verifications, loop testing.	Masoneilan g.	Multi- meter, C	GLYCOL CONTAC TOR	1	

117	10-LT-116			nylon tube of	O/ HEAD SCRUBBE	1	
118	10-LT-208			1"dia, 10 meter length.	R FLASH DRUM	1	
119	10- SDV-103	Greasing, Testing of loop & On/ Off position,	Size: 10" CL 600 LEDEEN ITALIA	Crane, Spanner	MAIN	1	
120	10- SDV-104	Verification of Position Switches, Testing/Overhauling Of	Size: 2" CL 600 EL- O-MATIC	Set mm/Inch, Screw Driver	CONTAC TOR.OUT LET	1	
121	10- SDV-105	SOVs, service of all local Pneumatic regulators.	Size: 10" CL 600 LEDEEN ITALIA	Set, General Tools.	SALE GAS LINE	1	
Dehyd	Iration Train -	20			Location		
122	20-PCV-100	To record as found calibration data. Site calibration and integrity	Size: 12" CL 600 Fisher Control Valve		DEHY O/L TO SALE GAS	1	
123	20-PCV-111	checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard	Size: 6" CL 600 Fisher Control Valve		SCRUBBE R OUT TO FLARE	1	
124	20-PCV-215	copies of assignments. Replacement of Poritioner if required	Size: 1" CL 150 Fisher Control Valve	Screw Driver Set, Terminal	FLASH DRUM TO FLARE	1	
125	20-LCV-108	Dismantling, shifting to W/S, body & trim	Size: 1" CL 600 Fisher Control Valve	Screw Drivers, Spanner Set mm/Inch, Multimeter,	INTEGRA L SCRUBBE R	1	
126	20-LCV-112	inspection, lapping of plug/seat (if reqd.), hydro testing, replacement of	Size: 1- 1/2" CL 600 Fisher Control Valve		GLYCOL CONTAC TOR	1	
127	20-LCV-208	kits, actuator integrity testing and calibration, service of pneumatic	Size: 1- 1/2" CL 150 Fisher Control Valve	, consumables	FLASH DRUM	1	
128	20-TCV-200	regulator, I/P converter & positioner. Inspection/testing of SOVs (if required). Loop testing	Size: 4" CL 300 Fisher Control Valve		STEAM LINE TO REBOILE R	1	
129	20-LCV-108	with DCS.Replacement of Poritioner if required	Size: 1" CL 600 Fisher Control Valve		INTEGRA L SCRUBBE R	1	
130	20-FT-100			Screw Driver Set,	DEHY INLET	1	
131	20-FT-101A			Terminal Screw Drivers,	DEHY OUTLET	1	
132	20-FT-101B	Onsite calibration, leak		mm/Inch,	DEHY OUTLET	1	
133	20-FT-200	test of connectors, checking of isolating valves, loop verification. Dismantelling, Sensor cleaning, replacement if required	Transmitter	Multimeter, mA Current Source,	DEHY REBOILE R	1	
134	20-FT-201		Rosemount	Resistance box, Pressure Calibrators	GLYCOL PUM OUTLET	1	
135	20-LT-206			and High	SURGE DRUM	1	
136	20-DPT-107			Pressure Ranges.HART	CONTAC TOR	1	
137	20-DPT-213	Dismantling, shifting to W/S, Record as fond calibration data, Sensor		Communicator , consumables.	CARTRID GE FILTER	1	

138	20-DPT-214	and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.			CHARCO L FILTER	1	
139	20-PT-201	Onsite calibration, leak test of connectors, checking of isolating			REBOILE R PRESSUR E	1	
140	20-PT-203	valves, loop verification.  Dismantling, Sensor			REBOILE R.INLET	1	
141	20-PT-215	cleaning, replacement if required			FLASH DRUM	1	
142	20-PT-100	Onsite calibration, leak test of connectors, checking of isolating			SYSTEM PRESSUR E	1	
143	20-PT-109	valves, loop verification.  Dismantling, Sensor	Transmitter Rosemount		SALE GAS	1	
144	20-PT-212	cleaning, replacement if required			GLYCOL PUMP OUTLET	1	
145	20-LT-108	On Site Level troll internal		Drivers Set Hex	INTEGRA L SCRUBBE R	1	
146	20-LT-112	On Site Level troll internal Cleaning, Sensor cleaning and setting, Field signal electric connection checking, Calibration verifications, loop testing.	Level Troll	Multi-meter Pipe Wrench 18", 12" <sup>2</sup> . Transparent nylon tube of 1" dia, 10	GLYCOL CONTAC TOR	1	
147	20-LT-116				O/ HEAD SCRUBBE R	1	
148	20-LT-208			meter length.	FLASH DRUM	1	
149	20- SDV-103	Greasing, Testing of loop & On/ Off position,	Size: 10" CL 600 LEDEEN ITALIA	Crane, Spanner Set mm/Inch, Screw Driver	MAIN INLET	1	
150	20- SDV-104	Verification of Position Switches, Testing/Overhauling Of	Size: 2" CL 600 EL- O-MATIC		CONTAC TOR.OUT LET	1	
	20- SDV-105	Pneumatic regulators.	Size: 10" CL 600 LEDEEN ITALIA	Tools.	SALE GAS LINE	1	
Dehyd	ration Train -	30	T		Location		
152	30-PCV-100		Size: 12" CL 600 Fisher Control Valve		DEHY O/L TO SALE GAS	1	
153	30-PCV-111	To record as found calibration data. Site	Size: 6" CL 600 Fisher Control Valve	Screw Driver Set,	SCRUBBE R OUT TO FLARE	1	
154	30-PCV-215	calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required Siz Fis Va Siz Fis	Size: 1" CL 150 Fisher Control Valve	Screw Drivers, Spanner Set mm/Inch,	FLASH DRUM TO FLARE	1	
155	30-LCV-108		Size: 1" CL 600 Fisher Control Valve	Communicator	INTEGRA L SCRUBBE R	1	
156	30-LCV-112		Size: 1- 1/2" CL 600 Fisher Control Valve		GLYCOL CONTAC TOR	1	
157	30-LCV-208		Size: 1- 1/2" CL 150 Fisher Control Valve	50	FLASH DRUM	1	

158	30-TCV-200		Fisher Valve	" CL 300 Control		STEAM LINE TO REBOILE R INTEGRA	1	
159	30-LCV-108		Fisher Valve	Control		SCRUBBE R	1	
160	30-FT-100					DEHY INLET	1	
161	30-FT-101A				Cot	DEHY OUTLET	1	
162	30-FT-101B				Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, Resistance box, Pressure Calibrators Low Pressure	DEHY OUTLET	1	
163	30-FT-200	Onsite calibration, leak test of connectors,				DEHY REBOILE R	1	
164	30-FT-201	checking of isolating valves, loop verification. Dismantling, Sensor		ansmitter semount		GLYCOL PUM OUTLET	1	
165	30-LT-206	cleaning and replacement if required.		•		SURGE DRUM	1	
166	30-DPT-107				Pressure	CONTAC TOR	1	
167	30-DPT-213	Greasing Testing of Joon Si	Cine 40ll CL COO		Communicator	CARTRID GE FILTER	1	
168	30-DPT-214			consumables.	CHARCO L FILTER	1		
169	30- SDV- 103	Greasing, Testing of loop & On/ Off position,		0" CL 600 N ITALIA	Crane, Spanner Set	MAIN INLET	1	
170	104	Verification of Position Switches, Testing/Overhauling Of	O-MAT		mm/Inch, Screw Driver Set, General	CONTAC TOR.OUT LET	1	
171		SOVs, service of all local Pneumatic regulators.		0" CL 600 N ITALIA	Tools.	SALE GAS LINE	1	
Uch-I [	ocs							
	DCS	On Site Technical/Engineering Services of ABB Lahore for 07 Day. Scope of Work: General Checks for Health Status. Addition of Digital and Analogue Loops.(Only Software Part). Added loops Hard Wiring: Out of Scope. Minor Changes on HMI. Software Backups of Servers and Controller.		nd: Infi-90 ont End:	ABB Software tools	DCS		
LP Boil	ers 1 & 2			l	1	Location		
173	FCV-8062 (Both boilers)	To record as found calibrat data. Site calibration and integrity checks of actuato positioner, I/P converter. Loop calibration through D Provide soft and hard copies of assignments. Replacement Poritioner if required	r, CS.	Size: 6" CL 150 Fisher Control Valve		FUEL GAS BURNER	2	

174	LCV-8048 (Both boilers)	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 3" CL 300 Fisher Control Valve	All necessarytools	FEED WATER IN LET	2	
175	PCV-8063	Dismantling, shifting to W/S, Inspection of Trim and cleaning, reassembling and testing.	Size: 6" Fisher Regulator	Screw Driver Set, Spanner Set mm/Inch, Hex Key Set, Consumables	GAS FUEL TRAIN	2	
176	LGP			Spanners Set	SWITCH, LOW GAS PRESSUR E	2	
177	HGP	Inspection & Calibration of	Pressure Switches	Hex Key Set Multi-meter	SWITCH HIGH GAS PRESS.	2	
178	НБР	-ISwitch Veritication of Flectrical 1		( -	Pressure Calibrator/Dea d Weight Tester (300 Psi).	SWITCH HIGH FURNAC E PRESS	2
179	AS				SWITCH LOW COMB. Air Press.	2	
180	IAP			Spanners Set (In/mm) Screw	SWITCH LOW INST. AIR PRESS.	2	
181		Inspection & Calibration of Switch, Verification of Electrical	Pressure Switches	Drivers Set, Hex Key Set Multi-meter	SWITCH, HIGH STEM PRESS	2	
182	EHSP	Connections, inspection of loop	Switches	Calibrator/Dea d Weight Tester (300 Psi).	SWITCH, EXCESS high steam press	2	
183	(Both boilers)					2	
184	(Both boilers)	Dismantling, shifting to W/S, cleaning of float and internal body, re-	Float type level switch	Screw Driver Set, Spanner Set, Hex Key Set, Consumables	SWITCH, WATER LEVEL	2	
185	Low Alarm,	of isolating valves, loop verification.	Conductive Probe type Level Detector	Screw Driver Set, Spanner Set, Hex Key Set, Consumables	DRUM LEVEL	2	
186	PCV-9802	The loop test and Calibration, at location is required only. With I/P converter & Positioner	Size: 16" CL 150 Fisher Control Valve	General Calibration Tools	LP STEAM HEADER	1	
187	II I	Dismantling, shifting to W/S, Record as fond calibration data,	Level Transmitter	General Calibration	DRUM LEVEL	2	

1	ı		1	1	1		i.	ı
		Sensor and cleaning, Calibration,		Tools				
		re-installation, leak test of						
		connectors, checking of isolating valves, loop verification.		General				
188	FT	valves, loop vermeation.	Flow	Calibration	FUEL	2		
			Transmitter	Tools	GAS LINE			
		On Site setting, Calibration, Field		General	LP			
189	PT-9802		Press	Calibration	STEAM	1		
		test of connectors. Checking of	Transmitter	Tools	HEADER	_		
I D D o	ilara ?	isolating valves, Loop verification			Location	_		
LP Bo	liers 3		Size: 4" CL	ı	LEVEL			
190	LCV-101		300 ARCA		CONTRO	1		
130	101		REGLER		L VALVE	-		
		Record of as found calibration		1	GAS			
191	FCV-301	data, site calibration, Actuator,	Size: 8" CL		FLOW	1		
191	FCV-301	Positioner,	150 PARCOL		CONTRO	1		
		I/P Converter testing and		Calibration	L VALVE			
		replacement if required. Loop Test with HMI at Local and Boiler		Tools	GAS			
		operator room.	Size: 6" CL		PRESSUR E			
192	PCV-301	operator room.	150 PARCOL		CONTRO	1		
					L			
					VALVE			
					BOILER			
					DRUM			
					VERY HIGH			
193	PSH-101				PRESSUR	1		
133	311 101				E	_		
					(PRESSU			
				Caralli Drivar	RE			
				Screw Driver Set, Terminal	SWITCH)			
				Screw Drivers,	BOILER			
				Spanner Set	DRUM VERY			
194	LSLL-101			mm/Inch,	LOW	1		
		Inspection & Calibration of		Pressure	LEVEL			
		Switch, Verification of Electrical Connections, inspection of loop,	Switches	Calibrators Low Pressure	(LEVEL			
		- Connections, inspection of loop,		and High	SWITCH)			
				Pressure	BOILER			
				Ranges.HART	DRUM LOW			
195	LSL-101			Communicator	LEVEL	1		
				, consumables.	(LEVEL			
					SWITCH)			
					BOILER			
					DRUM			
196	LSH-101				HIGH LEVEL	1		
					(LEVEL			
L					SWITCH)			
				Screw Driver	INSTRU			
				Set, Terminal	MENT			
				Screw Drivers,	AIR VERY			
197	PSL-202			Spanner Set	LOW PRESSUR	1		
		Inspection & Calibration of		mm/Inch, Pressure	E(PRESS			
		Switch, Verification of Electrical	Switches	Calibrators	URE			
		Connections, inspection of loop,		Low Pressure	SWITCH)		<u> </u>	
				and High Pressure	GAS			
			P R C		VERY			
198	PSLL-301	SLL-301			LOW	1		
					1			
	1		<u> </u>	, consumables.	L(LUL)			

i	ı	ı	i	ı			i	ı	
					URE SWITCH)				
199	PSHH-301				GAS VERY HIGH PRESSUR E(PRESS URE SWITCH)	1			
200	PSL-101				PRESSUR E SWITCH	1			
201	LT-101	Dismantling, shifting to W/S, Record as fond calibration data,	Level Transmitter	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Pressure	UPPER STEAM DRUM LEVEL TRANSMI TTER	1			
202	FT-101	•	Flow Transmitter	Calibrators Low Pressure and High	Calibrators Low Pressure and High	FLOW TRANSMI TTER	1		
203	FT-102		Flow	Communicator	STEAM FLOW TRANSMI TTER	1			
204	PT-101				UPPER STEAM DRUM PRESSUR E TRANSMI	1			
205	PT-201				TTER PRESSUR E TRANSMI	1			
206	FT-201			Spanner Set mm/Inch,	COMBUS TION AIR FLOW TRANSMI TTER	1			
207	AT-201	On Site setting, Calibration, Field signal electric connection, Leak	Transmitters	Multimeter, mA Current Source,	OXYGEN TRANSMI TTER	1			
208	PT-301	test of connectors. Checking of isolating valves, Loop verification	Transmitters	box, Pressure Calibrators Low Pressure and High Pressure	GAS PRESSUR E TRANSMI TTER	1			
209	PT-302			Ranges.HART Communicator , consumables.	GAS PRESSUR E TRANSMI TTER	1			
210	FT-301				GAS FLOW TRANSMI TTER	1			
211	TT-301				GAS TEMPER ATURE TRANSMI TTER	1			

223	PCV-9601	To record as found calibration data. Site calibration and	Size: 3" CL 600 Fisher		RAW GAS TO	1	
ruel G	ias Skid	To record as found calibration	Sizo: 2" Cl	Scrow Driver	Location		
222 Evol 6	TT-9101	Inspection of sensor, Hydro test of thermo well. Calibration of Transmitters,. Checking of electric signals and verification of complete loop.	Temp Transmitter Rosemount	General Tools for TT Calibration, Temp Bath 500 Deg F		1	
221	PT-9101	On Site setting, Calibration, Field signal electric connection, Leak test of connectors. Checking of isolating valves, Loop verification	Press Transmitter Rosemount	General Tools for PT Calibrations.	DEAERAT OR PRESSUR E	1	
220	LT-9110	On Site Level troll internal Cleaning, Sensor cleaning and setting, Field signal electric connection checking, Calibration verifications, loop testing.	Level Troll Magnitroll	General Tools for LT Calibrations.	DEAERAT OR LEVEL	1	
219	PV-9101	converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 1-1/2" CL 150 SPIRAX SARCO	Multimeter	SATURAT ED STEAM I/ LET	1	
Deaer 218	LV-9110	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P	Size: 1-1/2" CL 150 SPIRAX SARCO	Scrwe Driver Set, Terminal Screw Drivers, Spanner Set	SOFT WATER TO DEAERAT OR	1	
217	XV-306	Inspection Eurotional Testing &	SOV	Scrwe Driver Set, Multimeter, Consumables	SHUT- OFF VALVE (SOV)	1	
216	XV-305		SOV		PILOT GAS VENT VALVE (SOV) PILOT GAS	1	
215	XV-304		SOV		PILOT GAS VENT VALVE (SOV)	1	
214	SDV-303		Size: 8" CL 150 VALBIA		BURNER GAS SHUT- OFF- VALVE (SDV)	1	
213	SDV-302		Size: 2" CL 150 ADLER		MAIN GAS VENT VALVE (SDV)	1	
212	SDV-301		Size: 8" CL 150 VALBIA		MAIN GAS SHUT- OFF VALVE (SDV)	1	

Page 31 of 66 OGDCL Tender Enquiry No. PROC-SERVICES/CB/P&P-5076/2021

1	I	: at a suite a sha salar of a standard	Cambral	Canavi Duivana	LID		İ	
		integrity checks of actuator, positioner, I/P converter.	Control Valve	Screw Drivers, Spanner Set	HP SCRUBBE			
		Loop calibration through DCS.		mm/Inch,	R			
		Provide soft and hard copies of	Size: 4" CL	Multimeter,	HP.			
224	PCV-9603	assignments. Replacement of	600 Fisher	mA Current	SCRUBBE	1		
	10000	Poritioner if required	Control	Source, HART	R INLET	-		
			Valve	Communicator , consumables				
			Size: 4" CL 300 Fisher	, consumables	LP.			
225	PCV-9615		Control		SCRUBBE	1		
			Valve		R INLET			
				Screw Driver	RAW			
226	PT-9601			Set, Terminal	GAS TO	1		
				Screw Drivers,	HPSCRU	_		
				Spanner Set mm/Inch,	BBER HP.			
227	PT-9603			Multimeter,	SCRUBBE	1		
		Sensor cleaning and setting,		mA Current	R INLET	_		
		Calibration, Field signal electric	Press.	Source,				
		<u> </u>	Transmitter	Resistance				
		connectors. Checking of isolating valves, Loop verification	Rosemount	box, Pressure Calibrators				
		valves, Loop vermeation		Low Pressure	LP.			
228	PT-9615			and High	SCRUBBE	1		
				Pressure	R INLET			
				Ranges.HART				
				Communicator , consumables.				
		Inspection of sensor, Calibration		, consumables.	ТО НР			
229	TE-9613	of	Temp.	Taman Dath	BOILER	1		
		Transmitters, Checking of electric	Transmitter	Temp Bath, General Tools	TO LP			
230	TE-9616	signals and verification of	Rosemount	General 10013	FUEL	1		
		complete loop.						
					HP. OUTLET			
231	FT-9612	On Site setting, Calibration, Field			TO HP	1		
		signal electric connection, Leak	Flow Transmitter	Pressure Calibrator,	BOILER			
		test of connectors. Checking of		General Tools	LP.			
232	FT -9617	isolating valves, Loop verification			OUTLET	1		
					TO UTILITIES			
		Greasing, Testing of loop & On/						
		Off	CIZE.OU CI		MAIN			
233	XSV-9602	position, Verification of Position	SIZE:8" CL 600 Rotork	General Tools	INLET TO FUEL	1		
		Switches, Testing/Overhauling Of	OOO NOTOIK		GAS SKID			
		SOVs, To record as found calibration	Size: 1" CL					
234	90-LCV-9609	data. Site calibration and	300 Fisher	General Tools	НР	1		
	30 200 3003	integrity checks of	Dump Valve	- C C. G. 1 0013	Scrubber	_		
		actuator, positioner, I/P						
		converter. Loop calibration	Size: 1" CL					
235	90-LCV-9622	through DCS. Provide soft and hard copies of assignments.	150 Fisher	General Tools	LP	1		
		Replacement of Poritioner if	Dump Valve		Scrubber			
		required						
НР Во	iler				Location			
236	PSL- N/A				FUEL	1		
	. 52 14/10				GAS LINE			
237	PSH- N/A	Inspection of sensor, tubing/	Dunnari	Pressure	FUEL	1		
		electric connections. Calibration	Pressure Switch	Calibrator,	GAS LINE COOLING			
238	PSL-1045	of switch, Inspection of loop		General Tools	AIR	1		
220	DCIIII NI/A				STEAM	1		
239	PSHH- N/A				PRESS	1		

240	Control Valve	On site calibration of positioner / Convertor and valve Calibration, Loop Calibration/ Test	Size: 3" CL 150 Valtek Valve	General Tools	FUEL GAS LINE (VALTEK)	1	
241	FT-911	Sensor cleaning, inspection of electric signal and connections.  Verification of operating			STEAM FLOW	1	
242	LT-910	parameters and calibration, loop T test. Replacement of damaged and choked tubes. Leak test of joints and connectors.	Transmitters	Equipment/To ols	DRUM LEVEL	1	
243	IP1-910	On Site Calibration,Checking of isolating valves, Loop verification	Transmitters	General calibrtion Equipment/To ols	STEAM PRESSUR E	1	
244		Inspection & Cleaning of Float, Verification of Security.	Level Switch	General Tools	DRUM LEVEL	1	
245	LCV (Feed Water)	Onsite Calibration	Size: 1-1/2" CL 300 Melso Control Valve				
Incine	rator		T		Location		
246		INSPECTION, CALIBRATION &	PDSLL-9951	General calibrtion	AIR DAMPER	1	
247	PDSLL- 9950	MAINTENAINCE JOB (If Reqd)	PDSLL- 9950	Equipment/To ols	S	1	
248	TCV- 9917	INSPECTION, CALIBRATION & MAINTENAINCE JOB (If Reqd) Body Hydro test in Workshop	SIZE: 4" CL 150 WORCESTER	General calibrtion Equipment/To ols	GAS FUEL LINE	1	
249	111-991/	INSPECTION, CALIBRATION & MAINTENAINCE (If Reqd)		General Tools	CONTRO L CABINET	1	
250	XSV- 9933	Dismantling, Shifting To W/S, Body & Trim inspection, Lapping of Plug/Seat (If Reqd.) Replacement	SIZE: 1-1/2'' CL 150 MAXON		FLASHGA STO INCINER ATOR	1	
251	XSV- 9935	of kits, Actuator integrity, Hydro test, Calibration, Shifting to location, Re- Installation, loop test, service of all local Pneumatic regulators, I/P Converters & Positioner. Painting Body as actual color arranged by Contractor.	SIZE: 1-1/2'' CL 150 MAXON	Grease Gun, General Tools.	FLASHGA STO INCINER ATOR	1	
252		Inspection / Testing / Position Verification Any Maintenance Job If Required	Actuators & Positioner	General Tools	DAMPER S	1	
253	PSLL-9912	Inspection & Calibration Of Switch, Verification of Electrical	PSLL-9912	General calibrtion	FUEL GAS TO INCINER ATOR	1	
254	PSHH-9918	Connections, inspection of loop,	PSHH-9918	Equipment/To ols	FUEL GAS TO INCINER ATOR	1	
Coolin	g Tower				Location		

266 267	KV-9005-A KV-9006-A	Cleaning/overhauling of Manual Override, Shifting to location, Re- Installation, On/Off Testing		Key Set	PRESS.FI LTERS A PRESS.FI	1	
	KV-9004-A	= = =			DRESS EI		
265	KV-9004-A	Inspection and cleaning of respective SOVs, Body, Disc and Seal Inspection, Checking the integrity of actuator, Cleaning/overhauling of Manual	Valves	mm/Inch, Hex	LTERS A	1	
264 265	KV-9003-A				LTERS A PRESS.FI	1	
	KV-9002-A			Screw Driver Set, Terminal	LTERS A PRESS.FI	1	
262 263		Dismantling, Shifting to W/S			LTERS A PRESS.FI		
	KV-9001-A				PRESS.FI	1	
Wate	r Treatment Pl			<u> </u>	Location		
261	PT-9813	Sonsor clooping and sotting Field	Press. Transmitter Rosemount	General calibrtion Equipment/To ols	COOLING TOWER SUPPLY	1	
		On Site Level troll internal Cleaning,			SUPPLY		
260	FT-9809	valves			COOLING TOWER	1	
259	FT-9805	signal electric connection checking, Calibration verifications, loop testing. Checking of isolating	Flow Transmitter Rosemount	General calibrtion Equipment/To ols	COOLING WATER MAKE- UP	1	
258	FT- 9803	Sensor cleaning and setting, Field			COOLING TOWER BLOW DOWN	1	
257	LCV-9801	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 6" CL 150 Fisher Control Valve	Scrwe Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, HART Communicator , consumables	COOLING WATER MAKE- UP	1	
256	LT-9801	Onsite calibration, leak test of connectors, checking of isolating valves, loop verification.	Level Transmitter Masoneilan	Spanners Set (In/mm) Screw Drivers Set Hex Key set. Multi-meter Pipe Wrench 18", 12" <sup>2</sup> . Transparent nylon tube of 1" dia, 10 meter length.	COOLING WATER MAKE- UP (BASIN)	1	
255	FCV- 9803	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 4" CL 150 Fisher Control Valve	Scrwe Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, HART Communicator , consumables	COOLING TOWER BLOW DOWN	1	

288	PCV-1	all local Pneumatic regulators. The calibrations Tools of the	CL 600 Valtek Valve	Calibrator, General Tools	Fuel gas skid	1	
202	DC) / 1	•		Pressure	EGT's		
EGTs :	1,2,3 & 4 Fu	el GAS Skid/Turbine Skid/TCM			Location		
286 287	KV-9031-C	Cleaning/overhauling of Manual Override, Shifting to location, Re- Installation, On/Off Testing		mm/Inch, Hex Key Set	C.	1	
286	KV-9030-C	respective SOVs, Body, Disc and Seal Inspection, Checking the integrity of actuator,	Butterfly Valves	Screw Drivers, Spanner Set	SIDE STREAM FILTERS	1	
285	KV-9029-C		Size: 6"	Set, Terminal		1	
284	KV-9028-C	Dismantling, Shifting to W/S Inspection and cleaning of		Screw Driver		1	
283	KV-9031-B	Inspection, Checking the integrity			SIDE STREAM FILTERS B	1	
282	KV-9030-B		Valves	Spanner Set mm/Inch, Hex Key Set	SIDE STREAM FILTERS B	1	
281	KV-9029-B		Size: 6"	Screw Driver Set, Terminal Screw Drivers,	SIDE STREAM FILTERS B	1	
280	KV-9028-B				SIDE STREAM FILTERS B	1	
279	KV-9034-A	Inspection, Checking the integrity	-		SIDE STREAM FILTERS A	1	
278	KV-9033-A			Key Set	SIDE STREAM FILTERS A	1	
277	KV-9030-A		Size: 6" Butterfly Valves	Set, Terminal Screw Drivers, Spanner Set mm/Inch, Hex	SIDE STREAM FILTERS A	1	
276	KV-9029-A			Screw Driver	SIDE STREAM FILTERS A	1	
275	KV-9028-A				SIDE STREAM FILTERS A	1	
274	KV-9005-B	Installation, On/Off Testing			PRESS.FI LTERS B	1	
273	KV-9004-B	Cleaning/overhauling of Manual Override, Shifting to location, Re-		mm/Inch, Hex Key Set	PRESS.FI LTERS B	1	
272	KV-9003-B	Inspection, Checking the integrity	Butterfly Valves	Screw Drivers, Spanner Set	PRESS.FI LTERS B	1	
271	KV-9002-B		Size: 6"	Screw Driver Set, Terminal	PRESS.FI LTERS B	1	
270	KV-9001-B				PRESS.FI LTERS B	1	
269	KV-9027-A				PRESS.FI LTERS A	1	
268	KV-9009-A				PRESS.FI LTERS A	1	

289	PCV-1A	vender must be certified by some recognized institution.	Size: 1-1/2" CL 600 Valtek Valve			1	
290	PSV-1		Size 4"x6"	Crane, Screw Driver Set, Terminal	EGT's Fuel gas skid	1	
291	PSV-2	Removing from location, testing in workshop/bench and record "as found set" value (Psig/Bar),	Size 1"x1"	Spanner Set mm/Inch, Hex	EGT's Fuel gas skid	1	
292	PSV-3	disassembling for Lapping trim and overhauling completely(if required), assembling, setting (provided by OGDCL) cold set points and reinstallation	Size I"x1"	Key Set, Pressure Source 2000PSI, Other calibration equipment. PSV Test Bench. Consumables	EGT's Fuel gas skid	1	
293	NYA	Dismantling, Shifting To W/S, Body & Trim inspection, Lapping of Plug/Seat (If Reqd.) Replacement of kits, Actuator integrity, Hydro test, Calibration, Shifting to location, Re- Installation, loop test, service of all local Pneumatic regulators.	Dump Valve 1" 600CL	General Tools	Horizont al K/O Vessel at EGT's Area.	4	
294		Inspection/ cleaning of all SOV's and Diaphragm Valves.	Pneumatic purging Cleaning by pulse controller	General Tools	Enclosur e and Ventilati on Purging and ventilati on system.	48	
295	04 Turbines	Dismantling of valves from location, shifting to workshop, inspection and maintenance, changing of repair kit, reinstallation and verification of operation, on-off position		General Tools	BLOW OFF VALVE (01 No. Each Unit)	4	
296	04 Turbines	Pressure Switches On Site Calibration Check	Hand Pump Pneumatic Pressure Calibrator, General Tools	General Tools	Pressure Switches (05 Nos. Each Unit)	12	
297	04 turbines	Pressure Tx On Site Calibration Check	Hand Pump Pneumatic Pressure Calibration General Tools.	General Tools	Transmit ters (06 Nos. Each Unit)	12	
	SURE SAFETY V						
Boiler	/Utilities Area LP1-PSV-	I		C	Location LP1		
298 299	8001 LP1-PSV-	Removing from location, testing in workshop/bench and record "as found set" value (Psig/Bar),	Size: 4" x 6" Size: 6" x 6"	Crane, Screw Driver Set, Terminal	BOILER LP1-	1	
300	8002 LP2-PSV- 8001	disassembling for Lapping trim and overhauling completely(if	Size: 4" x 6"	Screw Drivers, Spanner Set mm/Inch, Hex	BOILER LP2- BOILER	1	
301	LP2-PSV- 8002	required), assembling, setting (provided by OGDCL) cold set	Size: 6" x 6"	Key Set, Pressure	LP2- BOILER	1	
302	LID4 DCV 045	points and reinstallation.	Size: 1" x 1",	Source 2000PSI, Other		1	

			Make: ESER	calibration equipment.	BOILER		
303	HP1-PSV-916		Size: 1" x 1", Make: ESER	PSV Test	HP1- BOILER	1	
304	HP1-PSV-917		Size: 1" x 1", Make: ESER	Consumables.	HP1- BOILER	1	
305	HP2-PSV-A		Size: 2" x 3", Make: FARRIS		HP2-A	1	
306	HP2-PSV-B		Size: 2" x 3", Make: FARRIS		HP2-B	1	
307	HP2-PSV-C		Size: 2" x 3", Make: FARRIS	Crane, Screw	HP2-C	1	
308		Removing from location, testing	Make: TELEDYNE	Driver Set, Terminal Screw Drivers,	DE- AREATO R	1	
309	LP3-PSV-A	in workshop/bench and record "as found set" value (Psig/Bar), disassembling for Lapping trim and overhauling completely(if	Make: CROSBY	Spanner Set mm/Inch, Hex Key Set, Pressure	LP3 Boiler	1	
310	I D2 DCV/ D	required), assembling, setting (provided by OGDCL) cold set points and	Size: 6" x 8", Make: CROSBY	Source 2000PSI, Other calibration	LP3 Boiler	1	
311	LP3-PSV-C	reinstallation.	Make: CROSBY	equipment. PSV Test Bench	LP3 Boiler	1	
312	PSV-9606		Size: 6" x 8", Make: TELEDYNE	Consumables.	Fuel Gas Skid	1	
313	PSV-9619		Size: 6" x 8", Make: TELEDYNE		Fuel Gas Skid	1	
H2S R	emoval Plant T	rain-10	T	T	Location		
314	10-PSV-1201- A		Size: 8" x 10", Make: TELEDYNE		Amine Flash Drum Train-10	1	
315	10-PSV-1201- B		Size: 8" x 10", Make: TELEDYNE	Crane, Screw	Amine Flash Drum Train-10	1	
316		Removing from location, testing in workshop/bench and record	Size: 3" x 4", Make: TELEDYNE	Screw Drivers, Spanner Set	Amine Surge Drum Train-10	1	
317	10-PSV-1255	"as found set" value (Psig/Bar), disassembling for Lapping trim and overhauling completely(if required), assembling, setting	Size: 6" x 8", Make: TELEDYNE	Pressure Source	Amine Stripper Top Train-10	1	
318	110_D\$\/_1120	(provided by OGDCL) cold set points and reinstallation.	Size: 6" x 8", Make: TELEDYNE	2000PSI, Other calibration equipment. PSV Test	Over Head Scrubber	1	
319	10-PSV-1211		Size: 3" x 4", Make: TELEDYNE	Bench. Consumables.	Amine Cooler	1	
320	10-PSV-1212		Size: 1" x 2", Make: TELEDYNE		Amine Cartridge Filter	1	
321	10-PSV-1213		Size: 1" x 2", Make: TELEDYNE		Amine Cartridge Filter	1	

í	İ	1		1	,		Ī	I
222	10-PSV-1214		Size: 1" x 2", Make:		Amine	1		
322	10-PSV-1214		TELEDYNE		Charcoal Filter	1		
			Size: 3" x 4",	+	Amine			
323	10-PSV-1215		Make:		Surge	1		
323	10-734-1213		TELEDYNE		Drum	1		
			Size: 1" x 2",		Drain			
324	10-PSV-1216		Make:		ACP Out	1		
324	10-134-1210		TELEDYNE	Crane, Screw	Let	1		
			Size: 3/4" x	Driver Set,				
325	10-PSV-9316		1", Make:	Terminal	Condens	1		
323	10137 3310	Removing from location, testing	TELEDYNE	Screw Drivers,	ate Pot	-		
		in workshop/bench and record	Size: 3" x 4",	Spanner Set	Gas Inlet			
326	10-PSV-9401	"as found set" value (Psig/Bar),	Make:	mm/Inch, Hex	Cooler	1		
320	10 1 3 7 3 101	disassembling for Lapping trim	TELEDYNE	Key Set,	/Heater	-		
		and overhauling completely(if	Size: 3" x 4",	Pressure	Amine			
327	10-PSV-9410	required), assembling, setting	Make:	Source	Solution	1		
327	10 13 7 3 4 10	(provided by OGDCL) cold set	TELEDYNE	2000PSI, Other	Cooler	-		
		points and	Size: 3/4",	calibration	COOICI			
328	10-PSV-9413	reinstallation.	Make:	equipment.	Cartridge	1		
5_5			TELEDYNE	PSV Test	Filter	-		
			Size: 3/4" x	Bench.	Reflux			
329	10-PSV-9421		1", Make:	Consumables.	Condens	1		
323	10137 3421		TELEDYNE		er	-		
H2S R	emoval Plant 1	rain-20	11222 1112		Location			
				I	Amine			
	20-PSV-1201-		Size: 8" x		Flash			
330	A 1201		10", Make:		Drum	1		
	( )		TELEDYNE		Train-10			
				1	Amine			
	20-PSV-1201-		Size: 8" x		Flash			
331	В		10", Make:		Drum	1		
			TELEDYNE		Train-10			
					Amine			
			Size: 3" x 4",		Surge	_		
332	20-PSV-1215		Make:	Crane, Screw	Drum	1		
			TELEDYNE	Driver Set,	Train-10			
		Removing from location, testing	c: c!! c!!	Terminal	Amine			
222		in workshop/bench and record	Size: 6" x 8",	Screw Drivers,	Stripper			
333	20-PSV-1255	"as found set" value (Psig/Bar),	Make:	Spanner Set	Тор	1		
		disassembling for Lapping trim	TELEDYNE	mm/Inch, Hex	Train-10			
		and	Size: 6" x 8",	Key Set,	Over			
334	20-PSV-1130	overhauling completely(if	Make:	Pressure	Head	1		
		required), assembling, setting	TELEDYNE	Source	Scrubber			
		(provided by OGDCL) cold set	Size: 3" x 4",	2000PSI, Other calibration	Amina			
335	20-PSV-1211	points and	Make:		Amine	1		
	<u> </u>	reinstallation.	TELEDYNE	equipment. PSV Test	Cooler			
			Size: 1" x 2",	Bench.	Amine			
336	20-PSV-1212		Make:	Consumables.	Cartridge	1		
L	<u>                                     </u>		TELEDYNE	Consumables.	Filter			
			Size: 1" x 2",		Amine			
337	20-PSV-1213		Make:		Cartridge	1		
			TELEDYNE		Filter			
			Size: 1" x 2",	]	Amine			
338	20-PSV-1214		Make:		Charcoal	1		
			TELEDYNE		Filter			
			Size: 3" x 4",	1	Amine			
339	20-PSV-1215		Make:		Surge	1		
			TELEDYNE		Drum			
		Removing from location, testing		Crane, Screw				
340	20-PSV-1216	in workshop/bench and record	Make:	Driver Set,	ACP Out	1		
		"as found set" value (Psig/Bar),	TELEDYNE	Terminal	Let			
		, , , , , , , , , , , , , , , , , , , ,						

341		disassembling for Lapping trim and overhauling completely(if required), assembling, setting	Size: 3/4" x 1", Make: TELEDYNE	Screw Drivers, Spanner Set mm/Inch, Hex	Condens ate Pot	1		
342	20-PSV-9401	(provided by OGDCL) cold set points and reinstallation.	Size: 3" x 4", Make: TELEDYNE	Pressure Source	Gas Inlet Cooler /Heater	1		
343	20-PSV-9410		Make: TELEDYNE	calibration equipment.	Amine Solution Cooler	1		
344	20-PSV-9413		Size: 3/4", Make: TELEDYNE	PSV Test Bench. Consumables.	Cartridge Filter	1		
345	20-PSV-9421		Size: 3/4" x 1", Make: TELEDYNE		Reflux Condens er	1		
Dehyd	ration Train-1	0	T	T	Location		T	
346	10-PSV-201		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharg e Train- 10			
347	10-PSV-202		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharg e Train- 10			
348	10-PSV-201	Removing from location, testing in workshop/bench and record	Size: 2"x 3/4", Make: HYDROSEAL	Crane, Screw Driver Set, Terminal Screw Drivers,	Glycol Pump Discharg e Train- 10			
349	10-PSV-202	"as found set" value (Psig/Bar), disassembling for Lapping trim and overhauling completely(if required),	Size: 2"x 3/4", Make: HYDROSEAL	Spanner Set mm/Inch, Hex Key Set, Pressure Source	Glycol Pump Discharg e Train- 10			
350		assembling, setting (provided by OGDCL) cold set points and reinstallation	Size: 6" x 8", Make: TELEDYNE	2000PSI, Other calibration equipment. PSV Test Bench. Consumables	OVER HEAD SUCRUB BER Train-10			
351	10-PSV-104		Size: 3" x 3", Make: TELEDYNE	consumusies	GLY COAL REBOILE R Train- 10			
352	10-PSV-200		Size: 4" x 6", Make: TELEDYNE		SURGE DRUM Train-10			
353	10-PSV-203		Size: 1/2" x 2", Make: TELEDYNE		FLASH DRUM Train-10			
Dehyd	ration Train-2				Location			
354	12U-P5V-2U1	Removing from location, testing in	Size: 2"x 3/4", Make: HYDROSEAL	Crane, Screw Driver Set,	Glycol Pump Discharg e Train- 20	1		
355	20-PSV-202	workshop/bench and record "as found set" value (Psig/Bar), disassembling for Lapping trim and overhauling completely(if required),		Spanner Set	Glycol Pump Discharg e Train- 20	1		

356	20-PSV-103	assembling, setting (provided by OGDCL) cold set points and reinstallation.	Size: 6" x 8", Make: TELEDYNE	Pressure Source 2000PSI, Other calibration equipment.	OVER HEAD SUCRUB BER Train-20	1	
357	20-PSV-104		Size: 3" x 3", Make: TELEDYNE		GLY COAL REBOILE R Train- 20	1	
358	20-PSV-200		Size: 4" x 6", Make: TELEDYNE		SURGE DRUM Train-20	1	
359	20-PSV-203		Size: 1/2" x 2", Make: TELEDYNE		FLASH DRUM Train-20	1	
Dehyo	dration Train-3	30	1		Location		
360	30-PSV-201		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharg e Train- 30	1	
361	30-PSV-202	Removing from location, testing	Size: 2"x 3/4", Make: HYDROSEAL	Crane, Screw Driver Set, Terminal Screw Drivers,	Glycol Pump Discharg e Train- 30	1	
362	30-PSV-103	in workshop/bench and record "as found set" value (Psig/Bar), disassembling for Lapping trim and overhauling completely(if required),	Size: 6" x 8", Make: TELEDYNE	Spanner Set mm/Inch, Hex Key Set, Pressure Source	OVER HEAD SUCRUB BER Train-30	1	
363	30-PSV-104	-assembling, setting (provided by OGDCL) cold set points and reinstallation.	Size: 3" x 3", Make: TELEDYNE	2000PSI, Other calibration equipment. PSV Test Bench.	GLY COAL REBOILE R Train- 30	1	
364	30-PSV-200		Size: 4" x 6", Make: TELEDYNE	-Consumables.	SURGE DRUM Train-30	1	
365	30-PSV-203		Size: 1/2" x 2", Make: TELEDYNE		FLASH DRUM Train-30	1	
Coale	scer Filters Tra	nin 10/20	T	,	Location		
266	PSV-1	Removing from location, testing	Size: 2"x 4", Make: LESER	Crane, Screw Driver Set, Terminal Screw Drivers,	H2S	1	
367	PSV-2		Size: 2"x 4", Make: LESER	Spanner Set mm/Inch, Hex Key Set, Pressure Source 2000PSI, Other calibration equipment. PSV Test Bench. Consumables	Train 10 & Train 20 (Coaleser Filters Train 10/20)	1	
		Total Cost (II	nstrument SC	ow)			

## **OIL & GAS DEVELOPMENT COMPANY LIMITED** UCH-I GAS PROCESSING PLANT - ATA 2021 (MECHANICAL SCOPE OF WORK) Specificati Unite **Tools Required Remarks** Act # Tag #. **Job Description** Qty **Total Cost** Rate H2S REMOVAL PLANT (TRAIN-10 & 20) - 02 UNITS:-Pre-shutdown Activities 1 Connection for N2 Pumper 2 Depressurising and N2 purging 3 Blinding of battery limits Installation of scaffoldings as 4 per each equipment job access requirement Che Cleaning mical (Chemical/Mechanical) of will be 5 availble Amine X-Heat provid Exchanger Plates set (431 Nos.) ed by and Gaskets Installation **OGDCL** Post-shutdown Activities 1 Deblinding of battery limits 2 Leak Testing and N<sub>2</sub> purging 3 Removal of all scaffoldings Overall housekeeping/Area 4 Cleaning **GROUP-A: COLUMNS:-**10C200 MA1 Amine Stripper (01 No.) 1 Height of Strik.Sp: 65 1 Blinding Stripper = 90 ft I.D. of Comb.Sp.14 Opening of manways Stripper mm (Trays) = 132 in. No. of 3 Ventilation / Safety clearance trays = Socket Set, 18 I.D. of Scaffolding 4 **Initial Inspection** Manway Material = 20 in. Adjustable 5 Inplace Cleaning of all trays Spanner Cleaning of Column Shell internal, vortex breaker, 6 distributor/Seal Pan, LG's/Lt's etc. Straightening/repair of 7 damaged trays by removing, if Internal inspection of Column Shell for errosion/ corrosion 8 and repair/buildup, if any required. Inspection/DPT of Bottom Shell 9 S.S. Linning and repair/rebuild if required.

10		Reinforcement/replacement of existing linning plates, if required.				
11		Final inspection				
12		Boxup				
13		Deblinding				
MA2	20C200	Amine Stripper (01 No.)			1	
IVIAL	200200	Annie Stripper (OT No.)	Height		-	
1		Blinding	of Stripper = 90 ft	Strik.Sp: 65 mm		
2		Opening of manways	I.D. of Stripper = 132 in.	Comb.Sp.14 mm (Trays)		
3		Ventilation / Safety clearance	No. of trays = 18	Socket Set,		
4		Initial Inspection	I.D. of Manway = 20 in.	Scaffolding Material		
5		Inplace Cleaning of all trays	Empty Weight = 70 Tons	Adjustable Spanner		
6		Cleaning of Column Shell internal, vortex breaker, distributor/Seal Pan, LG's & LTs etc.				
7		Straightening/repair of damaged trays by removing, if any				
9		Final inspection				
10		Boxup				
11		Deblinding				
MA3	10C100	Amine Contactor (02 Nos.)			2	
1	&	Blinding	Height of Contacto r=30 ft	Strik.Spanne r: 65 mm		
2	20C100	Opening of manways	I.D. of Contacto r = 114 in.	Comb.Sp.14 mm (Trays)		
3		Ventilation / Safety clearance	No. of trays = 06	Socket Set,		
4		Initial Inspection	I.D. of Manway = 20 in.	Scaffolding Material		
5		Dismantling/removal of demisters cleaning & installation		Adjustable Spanner		
6		Inplace complete Cleaning of trays				
7		Mech.Cleaning of Column Shell internal, vortex breaker, distributor/Seal Pan, LG's & LTs etc.				
9		Final inspection				
10		Вохир				
11		Deblinding				

MA4	10C100	Glycol Contactor c/w Integral			2	
		Scrubber V101 (02 Nos.)	Hoight			
1	20C100	Blinding	Height of Column = 37 ft	Strik.Sp: 65,50,32 mm		
2		Opening of top & bottom manways	I.D. of Column = 72 in.	Hammers & Bars		
3		Inplace cleaning of packing, LG's & demisters	Materi al: S.S.(Dupl ex)			
4		Boxup				
5		Deblinding				
		GRO	OUP-B: VESS	ELS:-		
MB1	M200	Slug Catcher (01 No.)			1	
1		Blinding	Horizo ntal Vessel	Strik.Span:4 1,46,75 mm		
2		Opening of manways	Size: 78" ID x 204" LG	Comb.Span.: 27,32mm		
3		Ventilation/Safety clearance	I.D. of Manway = 20 in.	Adjustable Spanner		
4		Internal Inspection of vessel and demister		Scaffoldin g		
5		Cleaning of complete vessel,Demister& LG's.				
7		Final inspection				
8		Boxup				
9		Deblinding				
MB2	V-100	LP Separator (01 No.)			1	
1		Blinding	Horizo ntal Vessel	St.Sp.:24,27, 50,65 mm		
2		Opening of manways	Size: 78" ID x 204" LG	Comb.Sp.: 24,27mm		
3		Ventilation/Safety clearance	I.D. of Manway = 20 in.	Adjustable Spanner		
4		Internal Inspection of vessel				
5		Cleaning of vessel, demisters & LG's. Repair if any				
6		Final inspection				
7		Boxup				
8		Deblinding				
МВ3	10V202	Amine Reflux Drum (02 Nos.)			2	
1	&	Blinding	I.D.=7 ft	Striking Spanner:32 mm		
2	20V202	Opening of manways	Length = 10 ft	General Tool Box		
3		Ventilation/Safety clearance	Manw ay = 20 in.	Internal Scaffolding		
4		Internal Inspection of vessel		_		

_		Dismantling/removal of				
5		demisters & repair if any				
6		Cleaning of vessel, demisters & LG/LT				
7		Re-installation of demisters				
8		Final inspection				
9		Вохир				
10		Deblinding				
MB4	10V200	Amine Flash Drum (02 Nos.)			2	
1	&	Blinding	I.D of Vessel = 126 in.	Str.Spanner: 36, 41 mm		
2	20V200	Opening of top dome & bottom manway	Length of Vessel = 28ft S-S			
3		Ventilation/safety clearance	Top Dome= 30 in OD x 33 in LG	Crane		
4		Initial Inspection of vessel	Botto m manway = 20in I.D.			
5		Dismantling/removal of demisters & repair if any				
6		Internal cleaning of complete Vessel, LG/LT				
7		Cleaning of demisters & re- installation				
8		Final Inspection				
9		Box up				
10		Deblinding				
MB5	10V201	Amine Surge Drum (02 Nos.)			2	
1	&	Blinding	I.D of Surge Drum = 108 in	Strik.Span: 36, 41 mm		
2	20V201	Opening of manways	Length of Vessel = 30 ft S- S			
3		Ventilation/safety clearance	I.D of manway = 20 in			
4		Internal cleaning of complete Vessel & LG's.				
5		Inspection				
6		Box up				
7		Deblinding				
МВ6	90X903	Incinerator K.O Vessel (01 No.)			1	
1		Blinding	Vessel size: O.D. 60" x 28' LONG			
2		Opening of manways	Manw ay: 20"X150 CL			

3		Ventilation/safety clearance				
4		Internal cleaning of complete				
7		vessel. Cleaning of LG's/LT's of K.O.				
5		vessel				
6		Inspection				
7		Box up				
8		Deblinding				
МВ7	90V100A/B	Flare Knock Out Vessel (02 Nos.)			2	
		,	I.D of			
1		Blinding	Surge Drum = 135 in			
2		Opening of manway	Length of Vessel = 288 in S-S			
3		Ventilation/Safety clearance	I.D of manway = 20 in			
4		Internal Inspection of vessel				
5		Cleaning of vessel & LG's (repair if any)				
6		Final inspection				
7		Boxup				
8		Deblinding				
MB8	90V902	Amine Sump (01 No.)			1	
1		Decanting of Sump	Vessel size: I.D. 84" x 127"T/T	Crane		
2		Opening of manway/removal of A.Sump Pump	Manw ay: 20"			
3		Inspection of Pump and rectification if any				
4		Internal/extrernal cleaning of Sump				
5		Box up after inspection				
MB9	50V100	Glycol Sump (01 No.)			1	
1		Decanting of Sump	Vessel size: I.D. 40" x 120"T/T			
2		Opening of manway/Removal of Sump Pump	Manw ay: 20"			
3		Inspection of Pump and rectification if any	-			
4		Internal/extrernal cleaning of Sump				
5		Inspection of Vessel				
6		Box up				
MB10	10V100	Inlet Separator (02 Nos.)			2	
1	&	Blinding	I.D: 3 ft 6 inch,O.D : 4 ft	Str. Spanner: 50,65 mm		
2	20V100	Opening of manways	Length : 10 ft	General Tool Box		

		ī	1	1	1 1	1	ı	1 1
3		Ventilation/Safety clearance	Inlet Nozzle = 12 in.	Crow bar				
4		Internal Inspection of vessel	Outlet Nozzle =12 in.					
5		Cleaning of vessel & LG's.	Manw ay=20 in					
6		Inspection/cleaning of Vane Pack & Liner						
7		Final inspection						
8		Вохир						
9		Deblinding						
MB11	V-600 A/B	Instrument Air Receiver (02 Nos.)				2		
1		Blinding	I.D. = 1829 X 7110 T/T					
2		Opening of manways						
3		Ventilation/safety clearance						
4		Internal cleaning of complete Vessel & Sand Blasting						
5		Internal Protective Coating/Painting of vessel						
6		Inspection						
7		Box up						
8		Deblinding						
MB12	10S202	Filter Coalescer (02 Nos.)				2		
1	&	Blinding	ASME U-Stamp Vertical Vessel	Strik.Span: 36, 41 mm				
2	20\$202	Opening of top cover	Size: 1016 (OD) x 4996 (HT) x 34.5 (THK.)					
3		Removal of Filters	Materi al: SA- 240M 304L					
4		Internal cleaning of Vessel/Shell/LG's etc.	Rating : ANSI 900#					
5		Reinstallation/Replacement of Filter Elements	Quick Opening Top Manway.					
6		Inspection						
7		Box up						
8		Deblinding						
			: HEAT EXCH	IANGERS:-				
MC1	10E100	Inlet Gas Cooler Heater (02 Nos.)				2		
1	&	Blinding/Isolation	Type: Utube,N o.of tubes=27	Crane, Chain Blocks,				

			8				
			278 U-				
2	20E100	Opening of Channel Head Cover	Tubes x				
2	205100	Opening of Channel Head Cover	1"(OD) x				
			0.065" (AW)x				
			222" LG				
3		Removal of bundle	1.25				
			square				
		los a satis a satis a satis a satis	pitch				
4		Inspection of bundle Cleaning of tubes & tube					
5		bundles by Water jetting					
6		Cleaning & Painting of Shell and					
U		channel internal					
7		Insertion of Bundle / Replacement of One Bundle					
8		Pressure Testing					
9		Final Inspection					
10		Box Up					
11		Deblinding					
MC2	10E200A/B	X-Heat Exchanger (04 Nos.)				4	
IVICE	1012007,0	A fieut Exchanger (04 1405.)	Plate				
			Туре		Arrange		
1	&	Opening of Inlet/Outlet nozzles	Heat		ment for		
			Exchange r		chem.		
		D ( (	No. of		circulatio		
2	20E200A/B	Provision of connection for chemical cleaning	Plates =		n is		
			431		available		
3		In place chemical cleaning of plates.			at site.		
4		Replacement of 01 No. Plate					
		Pack 200B Cleaning of dismantled Amine					
5		X-Heat Exchanger Plate Pack					
		and Gasket Installation					
6		Removal of connections					
7		Cleaning/Repair of Strainers					
8		Box up			<u> </u>		
9		Area cleaning					
мсз	10E201	Amine Stripper Reboiler (02 Nos.)				2	
		-	Type:I-				
	•	Opening of Channel Head	Singlepas	Sling,			
1	&	Covers	s,No.of tubes=21	Shackles			
			62				
			Size=1				
2	20E201	Cleaning of tubes by	"(OD)x.0 65"(AW)	Strik.Span:			
	200201	Hydrojetting	x24'-	27,30 mm			
			0"(LG)				
			Chann	Hammers,			
		Inspection of Channel head /	el Head Cover :	Crow bar			
3		Tube sheet welding joints and	69-1/8"				
		repair (if req.)	OD				
			x 2-7/8"				
4		Hydro Pressure testing	THK Over				
4		riyuro Pressure testing	Over				

			all				I	
			Length = 33ft & 9					
			in.					
5		Final Inspection		Scaffolding material				
6		Box up		Crane.				
7		Area cleaning						
MC4	10E202	Amine Reflux Condenser (02				2		
WIC4	101202	Nos.)	Type:I-			2		
1	&	Opening of Channel Head Covers	Doublep ass,No.of tubes =753	Sling				
2	20E202	Inspection of Channel head / Tube sheet welding joints and repair (if req.)	Size=1 "(O.D)x.0 65"(A.W. )x24'- 0"(LG.)					
3		Cleaning of tubes Mechanicallly& with Aquablaster	Chann el head size:O.D. =49¼"	Hammers,				
4		Hydro Pressure testing	B .C. =47 5/8 "	Crow bar,				
5		Final Inspection	Over all Length = 29 ft& 4 in.	Scaffolding material				
6		Box up of Channel Head Covers		Crane				
7		Area cleaning						
MC5	10E203	mine Solution Cooler (02 Nos.)	No. of		Arrange	2		
1	&	Opening of Channel Head Covers	tubes = 1184	Chain Block: 10 ton	ment for chem.			
2	20E203	Cleaning of tubes with Aquablaster machine.	Tube O .D. = 1 in.	Strik.Span: 27,30,32mm	circulatio n is available			
3		Chemical Cleaning of Shell Side	1.250	Comb. Span: 27,32mm	at site.			
4		Hydropressure testing	M.W.T hickness =0.075	Crow bar, Pipe Wrench				
5		Final Inspection	Length = 576 in. or 48 ft	Crane				
6		Box up of Channel Head Covers	No. of passes= One					
7		Area cleaning (house keeping)	Chann el cover O.D.= 53 5/8 "					
мс6	10E201	lycol Reboiler (02 Nos.)				2		
1	20E201	Opening of Channel &Manway	Shell Size: 30.5"O.D .x26' Length	Strik.Span: 32 mm				

2		Initial Inspection	Chann el Size: 12.75"O.	General Tool			
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	D.x27" LG	Box			
3		Removal of U-Tube buddle, if required (optional)	Tube Size: 3/4"OD- 34nos U- tubes	Crow bar, Crane			
4		Cleaning of tubes with Aquablaster, if required	U- Bunddle Size:12" ODx20' LG				
5		Cleaning of Shell & LG's/LT's	No. of passes=				
6		Inspection & Cleaning of Strainers at X-HE's	Shell & Tube U- type H.E.				
7		Inspection of Steam Traps on steam circuit	Manw ay Size: 20"x150 CL				
8		Pressure/leak testing					
9		Final Inspection					
10		Box up					
			D: ROTARY E	QUIPMENTS:-		ı	
MD1	10P201A/B	Amine Circulation Pump (04 Nos)			4		
1	&	Decoupling of Pump & Motor	6- stage Centrifug al M type pump				
2	20P201A/B	Initial Alignment check	Capaci ty=1800 gpm.	50 mm.			
3			OI <sup>-</sup>			1	
		Dismantling of bearing housings	Dis.Pr essure= 930 psig	General Tool Box			
4			Dis.Pr essure= 930 psig Suc.xD isch. = 8 x 6 in				
5		housings  Removal of bearings for	Dis.Pr essure= 930 psig Suc.xD isch. = 8				
		housings  Removal of bearings for inspection  Cleaning/Repair/repl. of	Dis.Pr essure= 930 psig Suc.xD isch. = 8 x 6 in Make: Union Pumps				
5		housings  Removal of bearings for inspection  Cleaning/Repair/repl. of damage parts, if any  Service of Mechanical Seal (Dismantling, cleaning/lapping & re-assembly)  Assembling of bearing housing	Dis.Pr essure= 930 psig Suc.xD isch. = 8 x 6 in Make: Union Pumps				
5		housings  Removal of bearings for inspection  Cleaning/Repair/repl. of damage parts, if any  Service of Mechanical Seal (Dismantling, cleaning/lapping & re-assembly)  Assembling of bearing housing  Painting of Pump Body/Casing & Skid	Dis.Pr essure= 930 psig Suc.xD isch. = 8 x 6 in Make: Union Pumps				
5 6 7		housings  Removal of bearings for inspection  Cleaning/Repair/repl. of damage parts, if any  Service of Mechanical Seal (Dismantling, cleaning/lapping & re-assembly)  Assembling of bearing housing  Painting of Pump Body/Casing	Dis.Pr essure= 930 psig Suc.xD isch. = 8 x 6 in Make: Union Pumps				
5 6 7 8		housings  Removal of bearings for inspection  Cleaning/Repair/repl. of damage parts, if any  Service of Mechanical Seal (Dismantling, cleaning/lapping & re-assembly)  Assembling of bearing housing  Painting of Pump Body/Casing & Skid  Cleaning of suction & seal flush	Dis.Pr essure= 930 psig Suc.xD isch. = 8 x 6 in Make: Union Pumps				
5 6 7 8 9		housings  Removal of bearings for inspection  Cleaning/Repair/repl. of damage parts, if any  Service of Mechanical Seal (Dismantling, cleaning/lapping & re-assembly)  Assembling of bearing housing  Painting of Pump Body/Casing & Skid  Cleaning of suction & seal flush line strainers	Dis.Pr essure= 930 psig Suc.xD isch. = 8 x 6 in Make: Union Pumps				
5 6 7 8 9	10P200A/B	housings  Removal of bearings for inspection  Cleaning/Repair/repl. of damage parts, if any  Service of Mechanical Seal (Dismantling, cleaning/lapping & re-assembly)  Assembling of bearing housing  Painting of Pump Body/Casing & Skid  Cleaning of suction & seal flush line strainers  Alignment	Dis.Pr essure= 930 psig Suc.xD isch. = 8 x 6 in Make: Union Pumps		4		

1 1		1	Centrifug	l i	I	1	l
			al pump				
			Capaci	Camb Caana			
2	20P200A/B	Dismantling of pump casing	ty=1980	Comb.Spann er 24mm			
			gpm.				
3		Inspection of casing	Pressu re= 52	General Tool			
		map contain or casing	psig	Box			
		Service of Mechanical Seal if	Suc.xD				
4		any having leakage problem.	isch. = 10 x 8 in				
			Make:				
5		Replacement of bearings if	Union				
)		required.	Pumps				
			Co., USA				
6		Assembling of pump					
7		Painting of Pump Body/Casing & Skid					
8		Alignment					
9		Cleaning of suction & seal flush line strainers					
10		Area cleaning					
MD3	10P202A/B	Amine Reflux Pumps (04 Nos.)			4		
			Single-				
1	&		stage Vertical	General			
1	ς		Centrifugal	Tool Box			
		Dismantling of pump	pump				
2	20D2024/D		Capaci				
	20P202A/B	Inspection of casing	ty=100 gpm.				
			Dis.Pr				
3		Cleaning/Repair/repl. of	essure= 66				
		damage parts/M.Seal etc.	psig Suc.xD				
4			isch. = 3 x 2				
		Assembling of pump	in				
5		Cleaning of suction & seal flush line strainer					
6		Painting of Pump outer					
		body/casing					
7		Area cleaning					
MD4	10-P-200 A/B	Glycol Circulation Pump (04 Nos.)			4		
		- ,	Recipr				
			ocating				
		Inspection of power end, i.e. sleeve bearings, crankshaft,	Capacity = 42.2 US				
1	20-P-200 A/B	crosshead pin & bush for any	GPM	General			
		wear & tear and repalce if	Make:	Tool Box			
		required	Union Pumps Co.,				
			USA				
		Inspection of fluid end, i.e.	Dis.				
		plunger, inlet/outlet valves,	Pressure = 935.1 psia				
2		gland pusher/ bush/packing	Size/type :				
		etc. for any wear & tear and replace if required	2 ½ X 3 TD				
			60				
3		Inspection of sheeves/pulleys & V-belts and replace (if required)					
4		Replacement of lube oil					
5		Alignment					
		•				•	

6		Area claining (House keeping)				
MD5	90X903	Cooling Tower Fan/Gearbox-			4	
5		A/B/C/D (04 Nos.)	AMAR			
1		Dismantling, Cleaning, Repairing & Painting of Fan	ILLO Right	General		
1		Blades & hub	Angle	Tool Box		
			Grear Drive Servic			
2		Dismantling of Gearbox	e Factor:			
			2.0 HP			
3		Shifting of Gearbox to	RPM			
		Workshop	Input: 1750 Ratio:			
4		Inspection / repair of Gearboxes	14:1			
			Reducing			
5		Grey epoxy paint to outer surface of gear box, fan and				
		foundation structure channels.				
6		Re-installation of Gear boxes				
		and Fans				
7		Replacement of Lube Oil				
8		Alignment				
9		Area cleaning				
MD6	LP-1/2/3	FD Fan LP Boiler #1 , 2 & 3 (03 Nos.)			3	
1		Opening of FD Fan inspection		General Tool		
1		windows.		Box		
2		Inspection/cleaning of Fan duct/dampers.				
3		Replacement of bearings of FD Fan				
4		Alignment				
5		Area cleaning				
MD7	EGT-1,2,3,4	Gas Turbine (04 Nos)			4	
		Inspection/Cleaning of EGT's	EURO	General		
1		Fuel Gas Separators.	PEAN GAS TURBINE	Tool Box		
_		Inspection / replacement of	MAKE:			
2		Fuel Gas Skid Filters	SIEMENS, UK			
		Cleaning/Replacement of Air	CAP:			
3		Intake Filters	4.9 MW AT			
		(80 nos.each unit)	15 <sup>o</sup> C MODE			
4		External Cleaning of Lube Oil Coolers	L: SGT-100-			
5		Overall cleaning of Turbine	13			
		enclosure				
6		Area cleaning				
MD8	X-200A-D	Instrument Air & Nitrogen Package Compressors (06 Nos.)			6	
1	X-201A/B	Overall cleaning of enclosure	MAKE: INGERSOLL -RAND &	General Tool Box		
2		Alignment checks and inspection/cleaning of complete packages	QUINC Y			
		h haarrages	Туре:			
3		Cleaning of Oil Cooler/Radiator	Screw			
-		g = 1111.2., 1121.3.00	Compresso			
			<u> </u>			Î

		Inspection/repair of	İ	1 1		
4		Compressor Airend, if req.				
5		Replacement of Filter Elements & Coolant, if required				
6		Area cleaning				
MD9	90P900A	Cooling Water Circulation Pump (01 No.)			1	
1		Dismantling/Removal of pump from site.	Single Stage Vertical Turbine Pump	Striking Spanner 36,41,		
2		Inspection of complete pump casing, strainers etc.	Dis.Ca pacity= 15000 GPM	General Tool Box		
3		Dismantelling/overhauling of pump if any found critical damaged.	Dis.Pr ess.= 60 PSIG			
4		Installation of Pump.				
5		Area cleaning				
MD10		Colony Water Pump (01 No.)			1	
1		Dismantling/Removal of pump from site.	KSB Deep Well Turbine Pump	Striking Spanner		
2		Inspection of complete pump casing, strainers etc.	Model: DWT B7B/2, Q:200 USGPM	General Tool Box		
3		Dismantelling/overhauling of pump if any found critical damaged.	H: 115 FT, BHP: 6.70KW, 2900rpm			
4		Installation of Pump.				
5		Area cleaning				
		GRO	UP-E: UTILI	TIES:-		
ME1	170S101	ETP Sump Pit			1	
1		Internal cleaning i.e.removal of mud/slurry		Scrapper and buckets		
2		Cleaning of Suction Foot Valve		Special mud/slurry decanting		
3		Inspection		submersible Pump		
ME2	90PF910	ressure Filters (02 Nos.)			2	
1	A/B	Scaffolding	Vessel Size: 98"I.D.x 145"HT			
2		Opening of manways.	Manw ay: 20" x 150 CL			
3		Removal, Cleaning & Charging of gravel/sand/resin (optional) i.e. if required				
4		Repairing of Top Distributer of Filter-A If Required				

		1		1	i	ı	
_		Repairing/Fabrication of					
5		Bottom Collector of Filter-A If Required					
6		Painting of Shell Internal and distributor					
7		Inspection					
<b>-</b>		-					
8		Box up					
ME3	90SF910	Side Stream Filters (02 Nos.)			2		
			Vessel				
1			Size: 98"I.D.x				
	B/C	Scaffolding	96 1.D.X 145"HT				
			Manw				
2			ay: 20" x				
		Opening of top manway	150 CL				
3		Removal & charging of gravel/sand/resin (optional) i.e.					
3		if required					
4		Painting of Shell Internal and					
4		distributor					
5		Inspection					
6		Box up					
ME4	90V900	Deaerator			1		
			Manw				
1		Opening of manway	ay:				
			20x150lb				
			Size:2				
			500mm				
2		Dismantling of top Dome	DIA x				
			5800mm LG				
		Internal cleaning of vessel, LG's	LG				
3		LT's					
		Repair of shell internal &					
4		internal distribution pipe,					
		nozzle(s) if required. Internal & External Painting of					
5		complete vessel, structure and					
		all piping under De-aerator					
6		Inspection of nozzles					
7		Box up					
ME5	90X902A	LP BOILER # 1, 2 & 3 (03 Nos)			3		
			Model	Air driven			
1	90X902B	Blinding	# NSX-G-	Grinders			
$\vdash$			100 Make(				
			LP-1&2):				
		Opening of manways of	National	Power			
2	90X902D	Combustion chamber, Mud and	Dynamic	Brushes for			
		Steam drums.	Corporat ion	cleaning			
			Nebraska				
			USA				
	<u></u>	Internal inspection of comb.	W.				
3		Chamber, Mud and Steam	Pressure				
		drums.	= 70 psig. Steam				
		Internal cleaning of	temperat				
4		tubes(Chem./Mech.)	ure=315				
			deg.F				
5		Cleaning of burners & comb.	Max				

ı	Ī	1		ı	1	1	ı	Í
		Chamber	.W.					
			Pressure					
			= 200					
			psig.					
			Steam					
6		Repair of refractory, if any	capacity = 145000					
			= 143000 lbs/hr					
			Tube					
			size=					
		Cleaning of Mud & Steam	02"x					
7		drums	0.095					
			&0.105					
			in.th					
		Dainiting of tubes steem drum	Total					
8		Painiting of tubes, steam drum & mud drum with apexior	nos. of					
0		compound paint.	tubes =					
		compound paint.	1742					
			Materi					
			al of					
9		Hydro/Pressure Test	drums =					1
			SA – 516-					
			70		-	-	1	ļ
		Cleaning of flue gasses	Materi					
10		chimeny, painting internally &	al of					1
		externally including	tubes =					
		structure/platforms	SA-178 A Make				1	
		Painting of Boilers outer	(LP-3):					
11		body/casing/structure.	Descon-					
		body, cashig, structure.	Lahore					
		Inspection by Chief Inspector of	24					
12		Boilers						
13		Gas Fuel line strainer cleaning						
		Inspection/Repair/Replacement						
14		of LP steam traps						
		Repair/Replacement of Exhaust						
15		Stack Flexible Joint at LP-3						
		Boiler only						
16		Box up						
17		Deblinding						
ME6	90X902C	HP BOILER# 1 &2 (02 Nos.)				2		
IVILO	30X302C	11F BOILEN# 1 &2 (02 NOS.)	N 4l - l				1	
4		Diadia	Model # HRNC-	Air driven				
1	&	Blinding	# HKNC- 480	Grinders				
<b>-</b>			Make					1
			(HP-1):					1
		Opening of manways of	WICKERS	Power				1
2	90X902E	Combustion chamber, Mud and	HOSKINS	Brushes for				1
		Steam drums.	(M)SDN.	cleaning				1
			BHD					1
		Internal inspection of comb	W.					
3		Internal inspection of comb. Chamber, Mud and Steam	Pressure					1
		drums.	= 497					1
		didillo.	psig.					
			Steam					1
4		Internal cleaning of tubes	capacity=					1
'		(Chem./Mech.)	10500					
			lbd/hr				1	
			Max					1
1		Cleaning of burners & comb.	.W. Pressure					1
l -			Uroccuro		1		1	ì
5		Chamber						
5			= 568 psig.					

, ,	1	1		ı	1		ı	1
			Test					
6		Repair of refractory, if any	Pressure					
		, , ,	= 852					
			psig. Steam					
		Cleaning of Mud & Steam	temperat					
7		drums	ure= 477					
			deg.F					
8		Damper cleaning/servicing						
		HP-1: Removal of Exhaust Duct						
9		of Kawasaki Turbine and its						
		Blinding						
10		HP-1 FD fan coupling bush						
		removal / reinstallation	C:f					
		Painiting of tubes, steam drum	Size of water					
11		& mud drum with apexior	tube=02					
		compound paint.	in.dia.x0.					
			128"th					
			Total					
			nos. of					
12		Hydro/Pressure Test	finned					
			tubes = 110					
			Materi				1	
40		Inspection by Chief Inspector of	al of					
13		Boilers	tubes=					
			SA- 192					
		Opening of flue gasses	Make					
14		chimenymanway. External	(HP-2):					
		painting of stack/chimney.	HMC, Taxila					
		Painting of Boilers outer	тахна					
15		body/casing/structure.						
10		Inspection /Replacement of HP						
16		Steam traps						
17		Gas Fuel line strainer cleaning						
18		Box up and deblinding						
ME7	90X903	COOLING TOWER				1		
			Туре:					
			Induced					
1		Cleaning of top water deck &	Draft					
		nozzles	Counterfl					
			ow					
			Design					
2		Cleaning of CT basin & pump	Water Circulati					
		suction pit	on:2700					
			0 USGPM					
		Cleaning, Repair and Painting of						
3		suction pit gate	No. of Cell: 04					
		strainers/structure, if any					-	
			Basin					
		Removal/cleaning/Re-	Size(LxW					
4		Installation of drift eliminators	xD): 144x48x					
			4 ft.					
		Inspection/Installation of						
5		damaged/fallen fills,drift						
		eliminator supports etc.						
		Inspection/repair of internal			FRP work			
6		cell walls, walk ways, Side walls,			shall be			
		Louvers, Top Deck, water			carried			
		distribution/nozzle area etc.			out by			

	i	1		i			1	i
		(FRP repairs)			expert			
					firm in			
					field of			
					FRP			
					Cooling			
					Towers			
7		Torque tightening of structure nut/bolts						
		Civil repair of CWP suction pit						
8		(Plaster repair) and Cooling						
		Tower basin (Seepage repair)						
		Cleaning / repair of pump						
9		suction strainers						
ME8	90X904	INCINERATOR				1		
1		Opening of manway	Manw					
			ay: 24" Size:					
			I.D. 4ft,					
2		Initial Inspection	Length:					
			5ft					
		Repair of Burner duct, furnace	Size:				1	
		& exhaust duct and stack	I.D. 10ft,					1
3		refractory & external insulation	Length:					1
		etc.	37.5ft					
4		Cleaning/replacement of flame						
		sight glasses						
5		Cleaning of burner tips  Repair / replacement of						
6		ceramic wool of Combustion						
0		chamber.						
		Cleaning of FD Fans, dampers &						
7								
i		links. (repair if req.)						
8		links. (repair if req.) Inspection						
8								
		Inspection Box up	P-F: MANUA	AL VALVES:-				
		Inspection Box up	P-F: MANUA	AL VALVES:-	Valves			
	H2S T-10	Inspection Box up	P-F: MANUA	AL VALVES:-	Valves list	31		
9	H2S T-10	Inspection  Box up  GROUI	P-F: MANUA	AL VALVES:-		31		
9 <b>MF1</b>	H2S T-10	Inspection  Box up  GROUI	P-F: MANUA	AL VALVES:-	list	31		
9	H2S T-10	Inspection  Box up  GROUI  Manual Valves of H2S T-10	P-F: MANUA	AL VALVES:-	list	31		
9 <b>MF1</b>	H2S T-10	Inspection  Box up  GROUI  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1	H2S T-10	Inspection  Box up  GROUF  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3	H2S T-10	Inspection  Box up  GROUF  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4	H2S T-10	Inspection  Box up  GROUF  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4 5	H2S T-10	Inspection  Box up  GROUT  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4	H2S T-10	Inspection  Box up  GROUF  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with  Silver/Aluminium Paint.	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4 5	H2S T-10	Inspection  Box up  GROUF  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with  Silver/Aluminium Paint.  Shifting / Installation of valves	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4 5 6 7	H2S T-10	Inspection  Box up  GROUF  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with  Silver/Aluminium Paint.  Shifting / Installation of valves at location	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4 5 6	H2S T-10	Inspection  Box up  GROUN  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4 5 6 7	H2S T-10	Inspection  Box up  GROUN  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service &	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4 5 6 7 8	H2S T-10	Inspection  Box up  GROUN  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service & greasing of manual valves of	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4 5 6 7	H2S T-10	Inspection  Box up  GROUN  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service & greasing of manual valves of H2S T-10 as per operation	P-F: MANUA	AL VALVES:-	list	31		
9 MF1 1 2 3 4 5 6 7 8	H2S T-10	Inspection  Box up  GROUN  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service & greasing of manual valves of	P-F: MANUA	AL VALVES:-	list attached	31		
9 MF1 1 2 3 4 5 6 7 8 9		Inspection  Box up  GROUN  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service & greasing of manual valves of H2S T-10 as per operation requirement	P-F: MANUA	AL VALVES:-	list attached			
9 MF1 1 2 3 4 5 6 7 8	H2S T-10	Inspection  Box up  GROUN  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service & greasing of manual valves of H2S T-10 as per operation	P-F: MANUA	AL VALVES:-	list attached	31		
9 MF1  1 2 3 4 5 6 7 8  MF2		Inspection  Box up  GROUF  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service & greasing of manual valves of H2S T-10 as per operation requirement  Manual Valves of H2S T-20	P-F: MANUA	AL VALVES:-	list attached			
9 MF1 1 2 3 4 5 6 7 8 9		Inspection  Box up  GROUN  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service & greasing of manual valves of H2S T-10 as per operation requirement	P-F: MANUA	AL VALVES:-	list attached			
9 MF1  1 2 3 4 5 6 7 8  9  MF2		Inspection  Box up  GROUF  Manual Valves of H2S T-10  Dismantling of Valves from location  Shifting of valves to workshop  Initial Testing/Inspection of valves  Repair of defected valves  Pressure Testing  Painting of Valves with Silver/Aluminium Paint.  Shifting / Installation of valves at location  Replacement of Valves having size 1-1/2" & below  Inplace cleaning/service & greasing of manual valves of H2S T-10 as per operation requirement  Manual Valves of H2S T-20  Dismantling of Valves from	P-F: MANUA	AL VALVES:-	list attached			

3		Testing/Inspection of valves					
4		Repair of defected valves					
5		Pressure Testing					
		Painting of Valves with					
6		Silver/Aluminium Paint.					
7		Shifting / Installation of valves at location					
8		Replacement of Valves having size 1-1/2" & below					
9		Inplace cleaning/service & greasing of all manual valves of H2S T-20					
MF3	Dehy.	Manual Valves of Dehydration			Valves list attached	23	
1	T-10, 20 &30	Dismantling of Valves from location					
2		Shifting of valves to workshop					
3		Testing/Inspection of valves					
4		Repair of defected valves					
5		Pressure Testing					
6		Painting of Valves with					
6		Silver/Aluminium Paint.					
7		Shifting / Installation of valves at location					
8		Inplace cleaning/service & greasing of all manual valves of					
0		Dehy. T-10 & 20					
MF4	UTILITIES &	Manual Valves of Utilities & Gathering Area			Valves list attached	32	
1	GATHERING	Dismantling of Valves from location			attacrica		
2		Shifting of valves to workshop					
3		Testing/Inspection of valves					
4		Repair of defected valves					
5		Pressure Testing					
6		Painting of Valves with Silver/Aluminium Paint.					
7		Shifting / Installation of valves at location					
		Inplace cleaning/service &					
8		greasing of all manual valves of Utilities area					
			: MISCELLAI	NEOUS JOBS:-			
		5.1031	Approx.				
MG1		Insulation Jobs:-	Dimension s				 
		Installation of insulation on	4 " dia,				 
1	HP Condensate Lines	complete HP condensate return header from boiler area upto	2000 ft length				
	LIIIC3	CCR backside	(approx.)				
MG2		UPL END (DERA MURAD JAMALI)- PROD. FACILITIES					
1		Replacement of 02 nos. Gear	24" x			2	
		Operated Ball Valves	600CL				
			42" dia.				
2		Replacement of Sale Gas Filter Elements (27 nos. per Vessel)	Vertical			2	
		Liements (27 nos. per vessel)	Vessel				
			(02 Nos.)				

		GROUP-H: MOD	IFICATION/	FABRICATION JC	DBS:-	
1	10-V-100	Inlet separator H/C Side troll drain valve replacement		3/4 Dia Inch SS Welding		
2	10-E-200A	X-Heat Exchanger Inlet eblow u/s of inlet isolating valve minor repair	Elbow Joint CS 12" x 150#	24 Dia inch CS Welding		
3	10-S-201	Charcoal filter Installation NRV at Amine inlet line	Check Valve 4"x150"	4 Dia Inch CS Welding		
4	20-E-100	Inlet cooler/Heater 1.5" steam line to condensate pot leakage repair at 1 point.	CS line, 1.5"	12 Dia Inch CS Welding		
5	20-V-203	Reboiler condensate pot LCV- 9514 D/S isolating valve flange joint leakage & Vessel Leakage Repair	line	4 Dia Inch CS Welding 10 Inch Linear Welding		
6	90-V-100A	Pin Hole Leakage rectification in Level Troll		Pin Hole Leakage		
7	D10/20-V-101	Integral scrubber open drain valve replacmenet	3/4", 800 lb	1.5 Dia Inch SS Welding		
8	Deaerator Area	Replacement of Gate Valve & 1/2" Line at HP Steam Samlpling Point	1/2" 800lb	4 Dia Inch CS Welding		
9	20-V-100	Replacement of 3/4" Gate Valve of LG Isolation	3/4" 800lb	3 Dia Inch SS Welding		
		Total Cost (Me	echanical SC	ow)		

			UCH-I GA		ESSING PLANT - ATA 2 IAL VALVE LIST)	2021			
S.#	EQUIP. NAME	EQ. TAG. NO	DESCRIPTION / LOCATION	VALVE SPECS	TYPE / SIZE / RATING	QTY	Unit Rate	Total Cost	REMARKS
GAT	HERING AREA VAL	VES (P	F-Prod.):-						•
	WESTERN / CENTRAL HEADER		ISOLATING VALVES	D2BFR	Ball Valve (Flanged), 12"x600lb	2			Replacement
2			ISOLATING VALVES	D2BFR	Ball Valve (Flanged), 10"x600lb	4			Replacement
3			NON-RETURN VALVES	D5RWS	Check Valve (Wafer), 8"x600lb	2			Replacement
4	LP SEPERATOR	V-100	UPSTREAM ISOLATING VALVE OF PSV	B2BFR	Ball Valve (Flanged), 4"x300lb	1			
5		V-101	UPSTREAM ISOLATING VALVE OF PSV	B2BFR	Ball Valve (Flanged), 4"x300lb	1			
						10			
	TRAIN-10 VALVES	o:-	l l		Globe				
6	INLET COOLER / HEATER	10-E- 100	BYPASS OF BATTERY LIMIT VALVE	D4RRS	Valve(Flanged), 2"x600lb	1			
7		10-E- 100	COOLING WATER SUPPLY & RETURN VALVE	A1RRC	Gate Valve(Flanged), 8"x150lb	2			
8		10-E- 100	STEAM INLET NRV	A5RWC	Check Valve(Wafer), 6"x150lb	1			
9			ISOLATION VALVE TCV-1112	A1RRC	Gate Valve(Flanged), 6"x150lb	2			
10	FILTER COALESCER	10-S- 202	PRODUCED WATER COMMON ISOLATION VALVE		Ball Valve (Flanged), 2"x1500	1			Replacement
11	AMINE CONTACTOR		UP STREAM GAS LINE NRV	D5RWS	Check Valve(Wafer), 12"x600lb	1			
12		10-C- 100	AMINE INLET LINE NRV	D5RWS	Check Valve(Wafer), 10"x600lb	1			
13	OVERHEAD SCRUBBER		TEATED GAS OUTLET BY-PASS VALVE		Globe Valve(Flanged), 2"x600lb	1			
14	X-HEAT EXCHANGER		LEAN AMINE ISOLATING VALVES	A1RRC	Gate Valve(Flanged), 12"x150lb	4			
15			RICH AMINE ISOLATING VALVES	A1RRC	Gate Valve(Flanged), 10"x150lb	4			
16	AMINE STRIPPER		STRIPPING STEAM LINE NRV	A5RWC	Check Valve(Wafer), 2"x150lb	1			
17		10-C- 200	REFLUX LINE NRV	A5RWS	Check Valve(Wafer), 3"x150lb	1			
	REBOILER CONDENSATE POT		ISOLATING & BYPASS VALVES OF LCV-9314.	A1RRC	Gate Valve(Flanged), 4"x150lb	2			
19	AMINE BOOSTER PUMP	10-P- 200	DISCHARGE NRV'S	A5RWC	Check Valve(Wafer), 12"x150lb	2			
20		10-P- 200	SUCTION VALVES	A1RRC	Gate Valve(Flanged), 14"x150lb	2			
171	CARTRIDGE FILTER	10-S-	INLET VALVE OF CARTRIDGE FILTERS	A1RRC	Gate Valve(Flanged), 4"x150lb	1			
22			OUTLET VALVE OF CARTRIDGE FILTERS	A1RRC	Gate Valve(Flanged), 4"x150lb	1			
23					Globe Valve(Flanged), 4"x150lb	1			

24	AMINE CIRCULATION PUMP	10-P- 201	DISCHARGE NRV'S	D5RWC	Check Valve(Wafer), 12"x600lb	2			
						31			
H2S-	TRAIN-20 VALVES	S:-	T		Ī		ı	T	
25	INLET COOLER/HEATER	20-E- 100	COOLING WATER SUPPLY & RETURN VALVE	A1RRC	Gate Valve(Flanged), 8"x150lb	2			
26		20-E- 100	STEAM INLET NRV	A5RWC	Check Valve(Wafer), 6"x150lb	1			
27		20-E- 100	ISOLATION VALVE TCV-1112	A1RRC	Gate Valve(Flanged), 6"x150lb	2			
28	FILTER COALESCER	20-S- 202	PRODUCED WATER COMMON ISOLATION VALVE	F2RRC	Ball Valve (Flanged), 2"x1500	1			Replacement
29	AMINE CONTACTOR	20-C- 100	UP STREAM GAS LINE NRV	D5RWS	Check Valve(Wafer), 12"x600lb	1			
30		20-C- 100	AMINE INLET LINE NRV	D5RWS	Check Valve(Wafer), 10"x600lb	1			
31	OVERHEAD SCRUBBER	20-V- 101	TEATED GAS OUTLET BY-PASS VALVE	D4RRD	Globe Valve(Flanged), 2"x600lb	1			
32	X-HEAT EXCHANGER	20-E- 200	LEAN AMINE ISOLATING VALVES	A1RRC	Gate Valve(Flanged), 12"x150lb	4			
31		20-E- 200	RICH AMINE ISOLATING VALVES	A1RRC	Gate Valve(Flanged), 10"x150lb	4			
32	AMINE STRIPPER	20-C- 200	STRIPPING STEAM LINE NRV	A5RWC	Check Valve(Wafer), 2"x150lb	1			
33		20-C- 200	REFLUX LINE NRV	A5RWS	Check Valve(Wafer), 3"x150lb	1			
33	REBOILER CONDENSATE POT	20-V- 203	ISOLATING & BYPASS VALVES OF LCV-9514.	A1RRC	Gate Valve(Flanged), 4"x150lb	2			
33	AMINE BOOSTER PUMP	20-P- 200	DISCHARGE NRV'S	A5RWC	Check Valve(Wafer), 12"x150lb	2			
34		20-P- 200	SUCTION VALVES	A1RRC	Gate Valve(Flanged), 14"x150lb	2			
35	CARTRIDGE FILTER	20-S- 200	INLET VALVE OF CARTRIDGE FILTERS	A1RRC	Gate Valve(Flanged), 4"x150lb	1			
34		20-S- 200	OUTLET VALVE OF CARTRIDGE FILTERS	A1RRC	Gate Valve(Flanged), 4"x150lb	1			
35				A4RRS	Globe Valve(Flanged), 4"x150lb	1			
36	AMINE CIRCULATION PUMP	20-P- 201	DISCHARGE NRV'S	D5RWC	Check Valve(Wafer), 12"x600lb	2			
						30	<u></u>		
DEH	YDRATION-TRAIN-		1		1			T	
37	GLYCOL CONTACTOR	10-C- 100	NRV ON TEG LINE IN 10-C-100	D5RWS	Check Valve(Wafer), 3"x600lb	1			
38	GLYCOL CIRCULATION PUMP	10-P- 200	SUCTION VALVES	D1RRC	Gate Valve(Flanged), 4"x600lb	2			
39		10-P- 200	DISCHARGE VALVES	D1RRC	Gate Valve(Flanged), 3"x600lb	2			
40		10-P- 200	RECYCLE VALVE	D4RRC	Globe Valve(Flanged), 3"x600lb	2			
41	GLYCOL REBOILER	10-E- 201	ISOLATING VALVES OF TCV-200 (STEAM INLET)	B1RRC	Gate Valve(Flanged), 4"x300lb	2			

10-E-	2 11 1 2 2 2 2 11 1 1 1 1 1 1 1 1 1 1 1		
DEHYDRATION-TRAIN-20 VALVES:-   GLYCOL	11 1 2 2 2 2 11 1 1 1 1 1 1 1 1 1 1 1 1		
GLYCOL	1 , 2 , 2 , 2 , 2 , 2 , 11		
A	1 , 2 , 2 , 2 , 2 , 2 , 11		
CIRCULATION   20-P-   200   SUCTION VALVES   D1RRC   Gate Valve(Flanged 4"x600lb   5"x600lb   5"x	2 , 2 , 2 , 2 , 11 1 1 1 1 1		
A5	2 2 , 2 , 2 11 1 1 1 1 1		
According   Cooling   Cooling   Tower   Still   Cooling   Tower   Still   Cooling   Coolin	, 2 , 2 11 1 1		
GLYCOL REBOILER  201 OF TCV-200 (STEAM INLET)  202-E-	2 , , , , , , , , , , , , , , , , , , ,		
A8	1 1		
SURGE DRUM  49  SURGE DRUM  30-V- 200  DOWNSTREAM ISOLATING VALVE OF PSV  A1RRC  Gate Valve (Flanged), 6"x150lb  LITILITIES/BOILER VALVES:-  FUEL GAS LINE  NRV FUEL GAS LINE ON FUEL GAS SKID  HOT WATER DISTRIBUTION VALVES  PO-X- TOWER  90-X- 903  COOLING WATER POST RECYCLE VALVE  903  A4RRC  Gate Valve (Flanged), 6"x150lb  Globe Valve (Flanged), 10"x150l  Gate Valve (Flanged), 10"x150lb  A1RRC  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  A1RRC  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb  Gate Valve (Flanged), 6"x150lb	1 1		
SURGE DRUM  30-V- 200  DOWNSTREAM ISOLATING VALVE OF PSV  A1RRC  Gate Valve (Flanged), 6"x150lb  LINE OF PSV  OF PSV  OF PSV  A1RRC  Gate Valve (Flanged), 6"x150lb  Check Valve(Wafer) 8"X600  COOLING TOWER  PO-X- 903  PO-X- 903  COOLING WATER PO-X- 903  PO-X- S2  PO-X- 903  PO-X- S3  PO-X- PO-	1		
### COP PSV    COOLING	1		
NRV FUEL GAS			
NRV FUEL GAS	T		
COOLING			
COOLING   700	1		
S2   903   RECYCLE VALVE   A4RRC   (Flanged), 10"x150l	8		
903   DRAIN VALVE   ATRRC   (Flanged), 6"x150lb     90-X-	1		
54 903 OF LCV 9801 A1RRC 8"x150lb	1		
Gate Valve	, 2		
INST. AIR COMPRESSOR  B  DISCHARGE VALVE  (Threaded), 40mm PN 25	1		Replacement
INST. AIR RECEIVER VESSEL V-600 A/B ISOLATION VALVE A1RRC Gate Valve (Flanged), 2"x150lb	4		Repair / Replace
BACK WASH 90-P- DISCHARGE VALVE A7RRC Butterfly Valve (Wafer), 6"x150lb	1		
90-P- DISCHARGE NRV A5RWC Check Valve(Wafer) 910B OF PUMP-B 6"X150	1		
90-P- DISCHARGE NRV 910A OF PUMP-A ASRWC Check Valve(Wafer) 6"X150	1		
DEAREATOR90-V- 900HP CONDENSATE LINE AT TOP DOMEA1RRCGate Valve 4"x150			
	1		
Total Cost (Manual Valves)	1 22		

OIL AND GAS DEVELOPMENT COMPANY LIMITED T&I- Section (PE&FD), Production Department								
ATA-2021 - UCH-I								
Sr. No.	Tag No.	Instruments Type /Make	Job Description	Tools/Eqps. Required	Remarks	QTY.	UNIT RATE	Total Cost
GATHERING AREA:-								
WESTERN & CENTRAL LOBE:-								
1	PRV_2001A PRV_2001B	16" Emergency Valve Morin/Emers on	Onsite Testing & Rectification of PRVS Opening / Closing indications(Limit Switch) through CCR HMI Display     Greasing & Cleaning of PRVs	2-Engineering Station 3-Hart Communicator	carried out. 2. OGDCL will	2		
2	ESDV_2001 A ESDV_2001 B		Onsite Testing & Rectification of PRVS Opening / Closing indications(Limit Switch) through CCR HMI Display     Greasing & Cleaning of ESDVs			2		
3	FCV_2001A FCV_2001B		<ul> <li>Onsite Testing,</li> <li>Calibration, integrity checks of actuator,</li> <li>positioner, I/P converter and service verified by CCR HMI</li> <li>Rectify Feedback transmitting signals Open/Close of FCV &amp;etc</li> <li>Rectify faulty indications of all instruments / valves etc (if required)</li> </ul>			2		
4	MVT_2001 AMVT_200	Danamanust	Onsite Testing, Calibration, integrity of	-		2		
1	IB Rosemount	service verified by SCADA CCR HMI			_			
F/	ASTERN LOBI	 E:-	CCK THVII	1	<u> </u>	]		
1	FCV_2001C FCV_2001D	Control Valves 8" / Fisher	Onsite Testing, Calibration, integrity checks of actuator, positioner, I/P converter and service verified by CCR HMI Rectify Feedback transmitting signals Open/ Close of FCV &etc Rectify faulty indications of all instruments / valves etc (if required)	end 1-Multi-meter 2-Engineering Station 3-Hart Communicator	1. OGDCL will deduct from actual cost if any job is not possible to be carried out. 2. OGDCL will deduct in case of non-availability of tools and calibration equipments. 3. mA Source and pressure calibrator	2		
2	ESDV_2001 C ESDV_2001 D ESDV_2001 F ESDV_2001 E	on	Dismantling of Actuator , shifting to W/S, replacement of Gaskit& O Rings and maintenance etc.     Actuator integrity testing and calibration,     Onsite Testing & Rectification of PRVS Opening / Closing indications(Limit Switch) through CCR HMI Display     Greasing & Cleaning of ESDVs	(In/mm) 5-Screw Drivers Set 6-Resistance Box. 7-Pressure Calibrator 8-mA Source 9-Heavy Machinery (if reqd.).	at Contractor end 4. All the procedure as per manual will be provided by OGDCL that must be followed. 5. Site test with SCADA left as per process requirement	4		

3	PRV 2001F	8" ESDV Valve Morin/Emers on	Onsite Testing & Rectification of PRVS Opening / Closing indications(Limit Switch) through CCR HMI Display Greasing & Cleaning of PRVs Onsite Testing, Calibration, integrity of service verified by SCADA CCR HMI			4		
W	ELL SITE:-							
E	ASTERN LOBI	E:-		ı	1		ı	
	FCV _07		<ul> <li>Onsite Testing,</li> <li>Calibration, integrity</li> <li>checks of actuator,</li> </ul>	consumables,	OGDCL will     deduct from actual     cost if any job is not			
	FCV_08		positioner , I/P converter and service verified by CCR	equipments at	possible to be carried out.			
1	FCV_09	Valve , Size 4"	HMI • Rectify Feedback	end 1-Multi-meter	2. OGDCL will deduct in case of non-availability of	4		
	FCV_06B		Close of FCV &etc	assistance software 3-Hart	tools and calibration equipments. 3. mA Source and pressure calibrator			
	ESDV _07		Onsite Testing &		at Contractor end			
	ESDVV_08	TK valve ,	Rectification of PRVS Opening / Closing	5-Screw	4. All the procedure as per manual will			
2	ESDV_09	Shutdown	indications(Limit Switch)		be provided by	4		
	ESDV_06B	Valve Size 4"	through CCR HMI Display • Greasing & Cleaning of ESDVs	6-Resistance Box. 7-Pressure	OGDCL that must be followed.  5. Site test with			
	FT_07		Calibration, servicing and		SCADA left as per process			
3	FT_08 FT_09	MVT / Rosemount	maintenance will be carried out and verification of	9-Heavy Machinery (if reqd.).	requirement	4		
3	FT_6B	3095	reading will be monitored by CCR-HMI			-		
CI	NTRAL LOBI	E:-		<b>.</b>				
	FCV_03		<ul> <li>Onsite Testing,</li> <li>Calibration, integrity</li> </ul>	All tools, consumables,	1. OGDCL will deduct from actual			
	FCV_17		checks of actuator , positioner , I/P converter	calibration equipments at	cost if any job is not			
	FCV_18	Flow Control	and service verified by CCR	contractor's	carried out.			
1	FCV_11	Valve , Size 4" / Mokveld	HMI • Rectify Feedback	1-Multi-meter	2. OGDCL will deduct in case of	5		
		•	transmitting signals Open/ Close of FCV &etc	2-Engineering assistance	non-availability of tools and calibration			
	FCV_14		Rectify faulty indications	software 3-Hart	equipments.  3. mA Source and pressure calibrator			
	ESDV_03		Onsite Testing &	4-Spanners Set	at Contractor end			
	ESDV_17		Rectification of PRVS	(In/mm) 5-Screw	4. All the procedure as per manual will			
2	ESDV_18	Emergency	Opening / Closing indications(Limit Switch)	Drivers Set	be provided by	5		
	ESDV_11	Shutdown	through CCR HMI Display	6-Resistance	OGDCL that must be	-		
	ESDV_14		<ul> <li>Greasing &amp; Cleaning of ESDVs</li> </ul>	Box. 7-Pressure	followed. 5. Site test with			
3	FT_03		Calibration, servicing and	Calibrator	SCADA left as per process			
	FT 17	MVT /	maintenance will be carried	9-Heavy	requirement			
	FT_18	Rosemount	out and verification of	Machinery (if	'	5		
	FT_11		reading will be monitored by CCR-HMI	reqd.).				
	FT_14		-,					

W	ESTERN LOB	E:-						
	FCV_12		I	All tools,	1. OGDCL will			
1		Flow Control	Calibration, integrity	consumables,	deduct from actual			
	FCV_13		checks of actuator , positioner , I/P converter	calibration equipments at	cost if any job is not possible to be			
	FCV_15		and service verified by CCR	contractor's	carried out.			
	501.46	Valve , Size 4"	HMI • Rectify Feedback	end 1-Multi-meter	2. OGDCL will	6		
	FCV_16	/ Mokveld	transmitting signals Open/ Close of FCV &etc • Rectify faulty indications	2-Engineering assistance software	deduct in case of non-availability of tools and calibration equipments. 3. mA Source and			
	FCV_02							
	507.40							
	FCV_10		etc (if required)		pressure calibrator			
	ESDV _12	TK valve , Emergency Shutdown Valve Size 4"	Onsite Testing &		at Contractor end			
	ESDV_13 ESDV 15		Rectification of PRVS	(In/mm) 5-Screw	4. All the procedure as per manual will			
2	ESDV_15 ESDV 16		Opening / Closing indications(Limit Switch)	Drivers Set	be provided by	6		
	ESDV_02		through CCR HMI Display	6-Resistance Box. 7-Pressure	OGDCL that must be followed.  5. Site test with SCADA left as per			
	ESDV_10		Greasing & Cleaning of  CSDVs					
	FT _12		ESDVs					
	FT_13	, <i></i> ,		8-mA Source	process			
3	FT_15		maintenance will be carried out and verification of	Machinery (if	requirement	6		
	FT_16		out and remieution of	reqd.).		0		
	FT_02 FT_10							
LP	_	RS (V-100 & V-	101):-	<u> </u>	1		<u> </u>	<u>                                     </u>
					1. OGDCL will	2		
	LT -3201			calibrationequi pments at	deduct from actual cost if any job is not			
1	LT-3250	LT		contractor's	possible to be			
				end	carried out.			
			• V-100 & V-101 (LCVs,	Spanners Set (In/mm)	2. OGDCL will deduct in case of			
	25-PSV-	PSVs, PCVs ) Inspection,	• Screw	non-availability of				
			Drivers Set	tools and calibration	_			
2	3205 25- PSV-3255		maintenance will be carried out and verification of		equipments. 3. mA Source and	2		
			controlling will be executed					
			by CCR- HMI [operator	set	at Contractor end			
	PCV-3215	PCV , Size=2"	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter.	<ul> <li>Engineering assistance</li> </ul>	4. All the procedure as per manual will	е		
				software	be provided by			
				• Hart	OGDCL that must be			
				Communicator  • Spanners Set	followed. 5. Site test with			
					SCADA left as per			
3	PCV-3271		SCADA	• Screw	process	2		
				<ul><li>Drivers Set</li><li>Multi-meter</li></ul>	requirement			
				Resistance				
			Box.					
				<ul> <li>Pressure</li> <li>Calibrator</li> </ul>				
SL	UG CATCHEI	R (M-200):-	<u> </u>	Canbrator	1		1	
	LT_2025		Rectify following inspection, calibration and maintenance will be carried out and verification of controlling will be executed	• All tools,	1. OGDCL will			
1				consumables,	deduct from actual			
				calibration equipments at	cost if any job is not possible to be			
				contractor's	carried out.	2		
	LT_2020		hy CCR-HMI lonerator	end	2. OGDCL will	_		
			command].	Spanners Set (In/mm)	deduct in case of non-availability of			
			[Boot calibration & Servicing]	• Screw	tools and calibration			
			JC: VICITIE]					

2	FT_2002	MVT / Rosemount	maintenance will be carried out and verification of reading will be monitored	<ul><li>Hart</li><li>Communicator</li><li>&amp;</li><li>Etc</li></ul>	equipments.  3. mA Source and pressure calibrator at Contractor end  4. All the procedure as per manual will	1		
3	25-PSV-	PSV , Size = 4"	by CCR-HMI.	(In/mm) • Screw Drivers Set • Multi-meter • Resistance Box.	be provided by OGDCL that must be followed. 5. Site test with SCADA left as per process requirement	1		
CONDENSATE STORAGE TANKS (T-101 & T-102)								
1	LT_3405 LT_3305	LT- [ T-101 & T-102]	calibrations of the LT- (T- 101 & T- 102 ) will be carried out and verified by CCR – HMI , Operator	Communicator • Spanners Set (In/mm) • Screw Drivers Set • Multi-meter • Resistance Box. • Pressure Calibrator	possible to be carried out.  OGDCL will deduct	2		
2	LS_3310 LS_3410	IC [T 101   9	Rectification of error and calibration job will be executed both LS-(T-101 & T-102); will be verified by CCR-HMI, Operator command.		<ul> <li>All the procedure as per manual will be provided by OGDCL that must be followed.</li> <li>Site test with SCADA left as per process requirement</li> </ul>	2		
Total Cost (T&I SOW)								

## **References:**

- ASME Sec II Part-A (Ferrous material Specifications)
- ASME Sec II Part-C (Specifications for welding rods, electrodes and filler materials)
- ASME VIII Div-I (Rules for Construction of Pressure Vessels)
- ASME Sec IX (Welding and Brazing Qualifications)
- ASME B31.3 (Process Piping)
- ASME Sec V (Non Destructive Examination)
- API-510 (Code for Inspection of pressure vessels repair, alteration and re-rating)
- API-572 (Inspection of Pressure Vessels)
- API-570 (Inspection, Repair, Alteration and re-rating of piping)
- API-598 (Valves Inspection & Testing)
- MSS-SP-61 (Pressure Testing of Steel Valves)
- NACE MR-0175
- OGDCL's Specifications & HSEQ Manual