

## TECHNICAL EVALUATION REPORT

**RFP NO.:**

OGDCL-SCM-FD-CB-MMD-266741385-2024

**DESCRIPTION OF THE RFP:**

**PROCUREMENT OF FORK LIFTERS (05 TON)**

**TECHNICAL BID(S) OPENING DATE:**

**14-11-2024**

S. No.	Name of Bidder	Status (Technically Responsive/ Non- Responsive)	Remarks (Reasons of Rejection)
1	M/s SHS TRADING (SMC-PVT) LTD:	<b>Technically Non-Responsive</b>	<ul style="list-style-type: none"><li>• Remained unable to submit verifiable proof such as unpriced Purchase Orders and Service Orders to prove at least continuous Five (05) years (2017~2022) experience of supply of Fork Lifter of similar or higher capacity in Pakistan along with Service Facilities of (Top End, Major Overhauling and site services etc.)</li><li>• Remained unable to provide proof for well established dedicated workshop facilities (both for parts &amp; spares) with in Pakistan for after sale service &amp; warranty / guarantee. OEM Authorization letter provided for residential address of the local agent instead of the workshop facility. Also remained unable to provide the last three year MOH &amp; TEO history against jobs executed at workshop facility for same capacity of Fork Lifters.</li><li>• Remained unable to Submit List and details of the offices complete address where the visit can be conducted.</li><li>• Remained unable to provide proof of any HSE Audit conducted by 3rd Party or any certification acquired regarding HSE practices.</li></ul>
2	M/s INTERTRADE DISTRIBUTORS PVT. LTD:	<b>Technically Non-Responsive</b>	<ul style="list-style-type: none"><li>• Remained unable to withdraw own quoted T&amp;C's and exhibit clean and complete acceptance to OGDCL TOR's, SOR and Tender Document.</li><li>• Remained unable to provide Information about interlocking system i.e., when fork lit is parked in forward/reverse gear it should not start after switching is missing in your technical bid. Please confirm to provide this system.</li><li>• Remained unable to submit verifiable proof such as unpriced Purchase Orders and Service Orders to prove at least continuous Five (05) years (2017~2022) experience of supply of Fork Lifter of similar or higher capacity in Pakistan along with Service Facilities of (Top End, Major Overhauling and site services etc.)</li><li>• Remained unable to provide proof for well established dedicated workshop facilities (both for parts &amp; spares) with in Pakistan for after sale service &amp; warranty / guarantee. OEM Authorization letter provided for residential address of the local agent instead of the workshop facility. Also remained unable to provide the last three year MOH &amp; TEO history against jobs executed at workshop facility for same capacity of Fork Lifters.</li><li>• Remained unable to Submit List and details of the offices complete address where the visit can be conducted.</li><li>• Remained unable to provide proof of any HSE Audit conducted by 3rd Party or any certification acquired regarding HSE practices.</li><li>• Remained unable to submit complete compliance of TOR's.</li></ul>

**Note:**

1. Bidder may submit grievance within Seven (07) days of announcement of Technical Evaluation Report.
2. The grievance if any shall be sent to [bgrc@ogdcl.com](mailto:bgrc@ogdcl.com) as per format available on OGDCL website.