# **OIL & GAS DEVELOPMENT COMPANY LIMITED**



## TENDER ENQUIRY NO. PROC-SERVICES/CB/P&P-5411/2022 HIRING OF SERVICES FOR EXECUTION OF ANNUAL TURN AROUND (ATA) 2022 OF UCH-I GAS PLANT

#### Note:

Bid bond of **PKR 950,000/- (Pak Rupees Nine Hundred Fifty Thounsand Only)** must be submitted with the technical bid. Please see tender documents for further detail.

The master set of tender documents (services) uploaded on OGDCL website (<u>www.ogdcl.com</u>) is the integral part of this TOR.

# HIRING OF SERVICES FOR EXECUTION OF ANNUAL TURN AROUND (ATA) 2022 OF UCH-I GAS PLANT TERMS & CONDITIONS

### **OGDCL'S RESPONSIBILITIES:**

- 1- OGDCL will provide blind/spades for isolation and pressure testing. However the blinds which are not available in stock, contactor may fabricate with available SS/MS sheets.
- 2- Only lodging (accommodation) will be provided to the Contractor manpower. The arrangement for 300 persons is available at site.
- 3- Only Emergency/First Aid medical coverage will be the responsibility of OGDCL.
- 4- All gaskets and direct material/spare parts will be provided.
- 5- OGDCL will provide paint for jobs wherever mentioned in scope of work.
- 6- OGDCL will provide pumps, tanks and hosepipes for in-place chemical cleaning of plate type heat exchangers, vessels & columns only.
- 7- Although the plant has a safe history however adequate security umbrella as provided to the Company's employees will be extended for Contractor's manpower.

## **CONTRACTOR'S RESPONSIBILITIES:**

- 1- The technical manpower must be qualified/skilled and have at least five years experience in its trade in the field of Oil & Gas/Petrochemical Processing Plants. Contractor skilled manpower will be interviewed by OGDCL professionals in all disciplines (Mechanical, Electrical and Instrument), if deemed necessary and contractor should arrange the interview at their premises. The detailed CV's of direct manpower/supervisors is mandatory.
- 2- Contractor will ensure mobilization of all manpower and resources at least two weeks before commencement of ATA.
- 3- Skilled manpower will be deployed for seven days after completion of shutdown for testing/startup activities. Moreover, Rotary Team shall remain at site until satisfactory operation/testing of all rotary equipment. (Approximately 7-10 days after plant startup).
- 4- Locals should be given preference while hiring of skilled/unskilled manpower.
- 5- The contractor should plan ATA activities (direct/associated) using latest version of Primavera and submit their planned schedule covering all the activities for carrying out ATA of UCH-I Gas Plant successfully with high level quality within stipulated time period. (Soft copy of Primavera Plan is mandatory with summarized plan and a detailed plan indicating critical path activities, equipment wise resource planning and deployment)
- 6- Contractor should prepare/submit daily progress report and percentage Gantt chart (planned vs actual) at end of the day.
- 7- Tools and consumables for the execution of each job including welding / fabrication consumables for all repair and modification jobs.
- 8- Painting job where ever given in the scope including painting equipment/tool like brushes, rollers, spray nozzles/guns, hosepipes etc.

- 9- Pneumatic Ejectors/Blowers for the ventilation of Columns and Vessels as per job scope requirement.
- 10- 24V Lighting arrangement for confined space jobs, i.e. inside the columns and vessels.
- 11- In case of any accident, OGDCL will provide only general first aid whereas any other medical treatment would be the responsibility of contractor.
- 12- Contractor shall arrange the standardized test bench for manual valves, control valves & PSV's pressure testing and interconnecting pipes, tubes, hoses for hydro-test and PSV's bench.
- 13- All tools, consumables and calibration equipment/tools for all instruments, control valves & PSV's should be the responsibility of contractor.
- 14- Site administration personnel with associated resources like computer, printers, photocopiers etc.
- 15- Contractor should arrange the blind flanges for PSV's, control valves and manual valves testing which will not be available at OGDCL store stock.
- 16- Contractor will arrange certified E & I calibration and testing equipments, the certificates will be submitted before execution of ATA. Original 3<sup>rd</sup> party calibration certificates will be verified by OGDCL representative upon arrival of equipment.
- 17- Nitrogen gas for PSV's and Regulators testing will be arranged by contractor.
- 18- Certified Cranes and fork lifters suitable to carry out the activities within stipulated time frame.
- 19- Precision Lathe machines for the repair of manual valves, control valves & PSV's as per work scope requirement.
- 20- Gaskets for pressure testing/bench test of manual valves, control valves & PSV's.
- 21- Water jetting machines with PSV calibration certificate and all other accessories up to 15000psig operating pressure for hydro-jetting of heat exchangers etc. as per job scope requirement.
- 22- Refractory work of Incinerators and Boilers including material is responsibility of contractor and should be carried out through M/S Refra Product, Karachi or any other local expert firm/company in this field (Refer clause # 24 of explanatory notes).
- 23- Scaffolding material and services, as when and where required.
- 24- Electrical Supply Boards/Cables along with earth leakage circuit breaker as per HSE standard.
- 25- Pneumatic/24V tools for confined spaces i.e. grinders/power brushes (Vessel and Columns).
- 26- Contractor will arrange sufficient air compressors in view of complete scope of work (ventilation/filter cleaning/pneumatic tools etc.)
- 27- Shock absorbing safety harness and respirators for contractor employees as per job requirement. Contractor will arrange hoses for water flushing of equipment / vessels / columns. (250-300 psi, 2" dia x 100 ft length / 10 nos. at least)
- 28- Contractor will submit Company HSE Policy manual for implementation of safe execution of each activity with zero-injury target. In case of any accident, OGDCL will not be liable for any claim like insurance etc.
- 29- Provision of PPE'S to their manpower and each worker should display ID card (HSE concern)

- 30- Original certificates of lifting gears, cranes, crane operators, hydro-jetting machines, drivers etc. will be mandatory checked by OGDCL HSE representative. Furthermore, contractor will submit copy of these certificates to HSE representative of OGDCL (HSE Concern)
- 31- The valid certification of welders, scaffolder etc. will be mandatory. Tags should be displayed for certified scaffolding (HSE Concern).
- 32- HSEQ manpower by contractor:
  - i) I/C HSEQ should be B.E Mech/Chemical with Nebosh certification with at least 05 Years of relevant experience.
  - ii) Supervisors should Graduate/D.A.E having Safety Courses certificates with at least 5 Years of relevant experience.
  - iii) HSE assistant should be at least Intermediate having Safety Courses/ certificates with at least 5 Years of relevant experience)
  - iv) Well-equipped First Aider & Rescuers (Trained/Certified at least 02 Nos.) e.g ropes/pulley, tri-pod, stretchers, medicines etc.
  - v) HSEQ crew will be interviewed by OGDCL HSEQ representative before commencement of ATA.
- 33- Contractor shall arrange Decanting pumps for ETP Sump Pit, Cooling Tower basin, Cooling Water Pump suction pit etc. wherever mentioned in SOW.
- 34- Contractor shall submit WPS & PQR for welding jobs prior to execution of job no deviation will be permissible.
- 35- Contractor shall depute qualified quality control Engineer having Level-II, Level-III CSWIP
   3.1, API certification for the supervision of welding/modification jobs.
- 36- DPT of all welding jobs (Repair work/Modifications) shall be the responsibility of main execution contractor including material.
- 37- Submit Total no's of deployed manpower list (designation wise) for the execution of individual job.
- 38- Contractor shall provide adequate meals and laundry services to their employees. Local area Contractor's may be introduced to provide such services.
- 39- Contractor will arrange transport for the pick and drop for their manpower from Colony to Plant and back for the whole period and also from Jacobabad to field & back. Fitness certificate for vehicles and drivers will be mandatory. Vehicles deployed for said purpose will be inspected by OGDCL and will not be allowed to use if found unfit.
- 40- Contractor should ensure the police verification of all manpower direct and indirect and must have bio-data file of each. (Security concern)
- 41- Contractor manpower must have CNIC and Contractor identity card.
- 42- Contractor should ensure his manpower has no any kind of ammunition and narcotics. (Security concern)
- 43- Mobiles and photo camera are prohibited in the plant premises and contractor should be ensured. (Security concern)
- 44- Contractor should deploy his own fully equipped security to control the manpower's in/out movement in plant as well as at colony with the coordination of OGDCL security Incharge. (Security concern)

#### ATA-2022 MAIN EXECUTION CONTRACTOR EXPLANATORY NOTES

- 1- The Owner, **O**il & **G**as **D**evelopment **C**ompany Limited (**OGDCL**) is interested in inviting bids for the provision of services (Mechanical, Electrical & Instrumentation) at their UCH-I Gas Processing Plant for the execution of the Annual Turnaround (ATA) 2022 maintenance activities from reputable companies in this field.
- 2- The tentative schedule of annual shutdown of UCH-I Gas Plant is from 16-10-2022 to 30-10-2022 (15 days), only 12 days should be available for maintenance activities and remaining 01 day will be required for the shutting down and 02 days for startup activities.
- 3- The contractor shall develop and submit a detailed work schedule including mobilization and preparatory works prior to shutdown.
- 4- The Contractor shall quote separate rate in PKR for each activity against the quantities mentioned in the scope of work.
- 5- The items mentioned in the scope of work consist of furnishing all plant, labor, equipment, machinery, scaffolding and materials for completing the work. The work shall be done, complete in all respects in accordance with the requirements and owner's instructions at site.
- 6- The Quantities contained in the scope of work for each activity are estimated and liable to change (increase, decrease or omitted) when the work is actually executed. The Owner does not expressly or by implication guarantee that actual quantities of work to be performed will correspond to the scope of work submitted with this tender document. The payment to be made to the Contractor shall be based on the actual quantity of work performed.
- 7- The Contractor shall be responsible for carrying out all work, complete in all respects, according to the scope of work. Any item of work required for completion but not expressly indicated in the scope shall be deemed to have been included in the unit rates quoted by the Contractor.
- 8- The successful contractor will be required to submit detailed procedures for undertaking shutdown jobs especially repair works and modification jobs for Owner's approval.
- 9- The Contractor shall be responsible for ventilation and getting the vessels fit for entry and working environment. All other works required for equipment / piping repair works, e.g. removal / installation of internals, temporary supports, lighting, ventilation, insulation etc., shall be the Contractor's responsibility.
- 10- Contractor shall undertake welding procedures qualification & welder qualification and all welding shall be performed by qualified Welders. The brand of electrode used for Qualification shall not be changed for Production Welding. (Contractor shall use electrodes/filler wires of reputable brands of European Origin e.g. ESAB, LINCON, etc.)
- 11- The works are to be carried out on a fast track basis and it is, therefore, essential that the Contractor shall be prepared to execute the work on a round the clock basis (day & night shift) including on holidays.
- 12- Unit rates quoted by bidder shall be firm. No extra payments on account of escalation in prices due to any reason shall be admissible.

- 13- Contractor must quote unit rate per dia. inch of pipe welding (separate rate for CS & SS material) & per Kg of structure welding that will also be applicable for any additional job during ATA.
- 14- The Contractor shall be paid only for the work duly approved by Owner's representative. Any rework due to poor quality, demonstrated by NDT results & inspection by OGDCL shall be on Contractor's account.
- 15- In case the contractor fails to arrange resources (tools, tackles, consumables, skilled manpower etc.) for execution of any job mentioned in scope of work, OGDCL will arrange/provide its resources to execute the job then the cost double the amount quoted by contractor against that specific job/equipment/area/group will be deducted from final invoice of the contractor.
- 16- The work is being executed within the plant during shutdown and the Contractor shall, therefore, abide by all safety rules and regulations required to be followed by the Owner.
- 17- The Contractor shall ensure deployment of skilled painters for painting jobs and proper surface preparation and application of primer and top coat, as per applicable industrial standards.
- 18- Removal/Re-installation of insulation where required/applicable shall be the responsibility of Contractor.
- 19- The contractor will arrange cranes and all other lifting/rigging gears for all activities to be carried out during ATA.
- 20- The Owner for any job will not provide any tools to contractor. Otherwise owner's representative will be liable to deduct the charges accordingly.
- 21- The contractor manpower should be well experienced/skilled in their respective crafts.
- 22- HSEQ Rules & Regulations will be strictly observed.
- 23- All the participating companies/contractors should have at least 5 years of similar experience especially in turnaround of Oil & Gas, Petrochemical & Fertilizers Plant.

#### 24- **REFRACTORY WORK:**

Refractory Work should be carried out through M/S Refra Product, Karachi or any other local expert firm/company in this field. The contractor will arrange the material required for the refractory repair work of Incinerator and Boilers. The rough estimated material required for repair work is given as below:

(i)- Cow/Ceramic Wool (2'x 16' x 1" thk. Roll)	Qty: 04	Rolls
(ii)- Fire Cement (25 Kg Bag)	Qty: 20	Nos.
(iii)-Castable (25 kg Bag)	Qty: 40	NOs.
(iv)-Anchors with lock (SS)	Qty: 20	Doz.

The actual quantities of material should be confirmed after initial inspection of equipments and it is the responsibility of contractor to arrange the material accordingly.

#### 25- Stress Relieving for modification jobs piping and strippers

- All repair welds shall be stress relieved.
- Stress Relieving of existing welds shall be undertaken where weld quality is acceptable as per NDT results.
- Local Heat Treatment may be carried out using electric heaters (Bands) covered by insulation. Temperature shall be noted by thermocouples and recorded by

automatic recorders. Detailed procedures shall be prepared and submitted by the Contractor for Owner's approval.

- Following procedure may be adopted for stress relieving of welds:
  - Heat up to 600 620 °C @ 100 °C per hour
  - > Hold at  $600 610^{\circ}$ C for 1-hour minimum.
  - > Slow cool @ 100  $^{\circ}$ C per hour from 600 to 300  $^{\circ}$ C.
  - Still air cool by removing insulation, from 300 <sup>O</sup>C to atm. temp.
- Take hardness profile of each weld to check if it is < 22 HRC.
- The above procedures have only been provided as guidelines. Contractor shall develop and submit detailed procedures for Owner's approval for mod job and stripper repair work.

#### 26- INSPECTION/REPAIR/TESTING OF VALVES:

- The Contractor shall quote separate rates for each/individual valve.
- Individual tags (include Asset Tag & Sr. # as per SOW) shall be installed on each valve for identification of location before dismantling of valve from site.
- Contractor shall submit the method statement for testing of valves with respect to the standards specified in the references below.
- For repair and build up of seats of valves contractor shall use electrodes/filler wires of reputable brands of European Origin e.g. ESAB, LINCON, etc.
- All gate valves will be tested from both sides i.e. front and back.
- Pressure testing of valves will be carried out as per applicable ASME Code.
   Lapping of valve seats shall be carried out on high-level precision machine.

#### 27- FRP WORK OF COOLING TOWER :

- The contractor shall arrange expert company/firm in the field of FRP Work as listed below.
  - 1- Fiber Craft Industries, Lahore (Tel: 042-36545346-46)
  - 2- Pak Fiber Glass Industry, Lahore (Tel:0302-4110665)
  - 3- AR Fiberglass Products Lahore (Tel: 42-35691050)
  - 4- Any other Equivalent (Mandatory experience of 05 years and above of Oil &Gas industry/ Fertilizer plant)
- FRP Works Company shall be responsible for the supply of material & services required for Cooling Tower Repairing as mentioned in SOW.
- 28- Work methodologies of Jobs (modification jobs, valve testing/repairing, Cleaning of vessels, Columns, heat exchangers and repair work of leakages in piping and pressure vessels and PWHT) will be developed by keeping in view of under-mentioned references and requirements. Furthermore contractor shall submit the welding procedure specifications with supporting PQR, method statement of repair jobs of Amine Stripper, hydro testing of mechanical valves, hydro testing of piping involved in modification jobs at least two weeks before the commencement of ATA for Owner's approval.

# Contractor Qualification Criteria (MARKS)

Sr. #	Evaluation Item	Description of Criteria	Max. Marks/ Calculations	Max Marks	Min Qualifying Marks	Remarks
1.	Contractor strength to execute Mechanical, Electrical, Instrument & Telemetry works	Contractor to fully comply the execution of complete SOW provided, Explanatory Notes and OGDCL T&C's	Full Compliance (mandatory)	15	15	Contractor should submit the signed/ stamped copy of SOW, Explanatory Notes and T&C's to prove the execution of all Mechanical, Electrical, Instrument & Telemetry activities during ATA in full spirit.
2.	Specific experience of Annual Turn Around (ATA)	Contractor's experience of ATAs	Contractor shall earn 06 marks against each ATA up to maximum of 30 marks	30	18	In order to get 06 Marks for each ATA, the value/ worth of each previous ATA performed by contractor should be at least 10 Million (PKR) each.
3.	Certifications.	Contractor should provide following valid certificates; 1. ISO 9000 certification: 2. ASME U/R/S- Stamp 3. PEC Registration	<ol> <li>04 Marks</li> <li>03/02/02</li> <li>Marks</li> <li>04 Marks</li> </ol>	15	9	Contractor should submit the valid copy of certificates. If the certificate status is in progress no marks will be given.
4.	Offices, Workshop, Tools, Equipment, Machinery, Infrastructur e.	Contractor should have following facilities within Pakistan. 1. Workshop & office, 2. Tools to execute the ATA activities (Mechanical, Instrument, Electrical).	<ol> <li>03Marks (02+01)</li> <li>08 Marks (04+02+02)</li> </ol>	30	25	
		<ol> <li>Equipment / Machinery (Valve test bench, hydro jetting machines, welding machines/ Generators).</li> </ol>	3. 03 Marks			01 Mark for each main equipment / Machinery.
		<ol> <li>Cranes, fork lifters.</li> <li>Relevant</li> </ol>	<ol> <li>4. 06 Marks (04 + 02)</li> <li>5. 10 Marks.</li> </ol>			Crane (Min 25 tons), fork lifters (Min 3 Tons) Organogram: 02 Mark.
		professional CVs & site deployment Organogram	5. 10 WIGHAS.			Mechanical CVs: 04 Mark Electrical CVs: 02Mark Instrument CVs: 02Mark

Sr. #	Evaluation Item	Description of Criteria	Max. Marks/ Calculations	Max Marks	Min Qualifying Marks	Remarks
		for Mechanical, Instrument & Electrical works.				
5.	Safety & HSE Policy	<ol> <li>Contractor's documentary evidence of HSE policy with commitment to provide PPE, Helmet, Ear plugs and safety shoes to the skilled labour at work.</li> </ol>	<ol> <li>04 Marks for full compliance , partial compliance zero Marks.</li> </ol>	10	08	The Contractor who will provide 1 Million safe man hours record will be awarded 04 marks while the Contractor who will provide 0.5 Million safe man hours record will be awarded 02 Marks.
		2. Well defined HSE policy with commitment and to provide 1 Million Safe Man hours' record.	2. 04 Marks			
		<ol> <li>Deployment of first aid boxes &amp; medical team for the labour at site.</li> </ol>	<ol> <li>02 Marks for full compliance , partial compliance zero Marks.</li> </ol>			
Total	Obtained Marks	5				

Minimum Qualifying Marks = 75

Total Marks= 100

### **FINANCIAL BID FORMAT/EVALUATION CRITERIA**

## UCH-II Plant ATA-2022

Sr. #	Desc	ription	Price in PKR
	Cost of Services for ATA jobs,	Mechanical works	
	activity wise breakdown should be provided as per enclosed	Electrical works	
01.	document / scope of work (the cost must be inclusive of all	Instrument works	
	types of equipments, tools, manpower, machinery,		
	consumables and PPE) for:	T&I works	
02.	Mob. / De-mob. Cost		
Total	cost		
Note:			
a) To	tal Price should be inclusive of all	taxes (except Provincial Sales Tax/ IC	CT Tax on services in
Ра	kistan), duties, levies, charges etc.		
•		above mentioned rates separately	for each activity of
	e jobs at Sr. No. 01. & provide the	-	
•	-	cancel any activity mentioned in t     ill be made as per actual job done.	he scope of work at

d) Contract will be awarded to technically responsive & financially lowest evaluated bidder on complete package basis.

### NOTE:

- Bid bond of **PKR 950,000/- (Pak Rupees Nine Hundred Fifty Thounsand Only)** must be submitted with the technical bid. Please see tender documents for further detail.
- Following documents must be submitted with the technical bid (bid bond, bidding form, Integrity & ethics undertaking, Affidavit (duly signed & stamped by Notary Public), Data Summary Sheet, Unpriced draft contract, Unpriced financial rate format and certificate of incorporation.

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
H2S RFN	-	(TRAIN-10 & 20) - 02 UNITS:-	· ·	I ·I				1
	lown Activities							
1		Connection for N2 Pumper						
2		Depressurising and N2 purging						
3		Blinding of battery limits						
4		Installation of scaffoldings as per each equipment job access requirement						
Post-shut	down Activities							
1		Deblinding of battery limits						
2		Leak Testing and N <sub>2</sub> purging						
3		Removal of all scaffoldings						
4		Overall housekeeping/Area Cleaning						
GROUP-	A: COLUMNS	:-	1					
MA1	10C200	Amine Stripper (01 No.)				1		
1		Blinding	Height of Stripper = 90 ft	Strik.Sp: 65 mm				
2		Opening of manways	I.D. of Stripper = 132 in.	Comb.Sp.14mm (Trays)				
3		Ventilation / Safety clearance	No. of trays = 18	Socket Set,				
4		Initial Inspection	I.D. of Manway = 20 in.	Scaffolding Material				
5		Inplace Cleaning of all trays		Adjustable Spanner				
6		Cleaning of Column Shell internal, vortex breaker, distributor/Seal Pan, LG's/LT's etc.						
7		Replacement of LG glasses						
8		Straightening/repair of damaged trays by removing, if any						
9		Internal inspection of Column Shell for errosion/ corrosion and repair/buildup, if any required.						
10		Inspection/DPT of Bottom Shell S.S. Linning and repair/rebuild if required.						

		OGDCL UCH-I GAS PROCES			SCOPE OF V	VORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
11		Reinforcement/replacement of existing linning plates, if required.						
12		Final inspection						
13		Вохир						
14		Deblinding						
MA2	20C200	Amine Stripper (01 No.)				1		
1		Blinding	Height of Stripper = 90 ft	Strik.Sp: 65 mm				
2		Opening of manways	I.D. of Stripper = 132 in.	Comb.Sp.14mm (Trays)				
3		Ventilation / Safety clearance	No. of trays = 18	Socket Set,				
4		Initial Inspection	I.D. of Manway = 20 in.	Scaffolding Material				
5		Inplace Cleaning of all trays	Empty Weight = 70 Tons	Adjustable Spanner				
6		Cleaning of Column Shell internal, vortex breaker, distributor/Seal Pan, LG's & LTs etc.						
7		Straightening/repair of damaged trays by removing, if any						
8		Final inspection						
9		Вохир						
10		Deblinding						
MA3	10C100	Amine Contactor (02 Nos.)				2		
1	&	Blinding	Height of Contactor=30 ft	Strik.Spanner: 65 mm				
2	20C100	Opening of manways	I.D. of Contactor = 114 in.	Comb.Sp.14mm (Trays)				
3		Ventilation / Safety clearance	No. of trays = 06	Socket Set,				
4		Initial Inspection	I.D. of Manway = 20 in.	Scaffolding Material				
5		Dismantling/removal of demisters cleaning & installation		Adjustable Spanner				
6		Inplace complete Cleaning of trays						
7		Mech.Cleaning of Column Shell internal, vortex breaker, distributor/Seal Pan, LG's & LTs etc.						
9		Final inspection						

		OGDCL UCH-I GAS PROCES	SING PLANT - ATA 20	22 (MECHANICAL	SCOPE OF V	VORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
10		Вохир						
11		Deblinding						
MA4	10C100	Glycol Contactor c/w Integral Scrubber V101 (02 Nos.)				2		
1	20C100	Blinding	Height of Column = 37 ft	Strik.Sp: 65,50,32 mm				
2		Opening of top & bottom manways	I.D. of Column = 72 in.	Hammers & Bars				
3		Inplace cleaning of packing, LG's/LT & demisters	Material: S.S.(Duplex)					
4		Вохир						
5		Deblinding						
GROUP	-B: VESSELS:-							
MB1	M200	Slug Catcher (01 No.)				1		
1		Blinding	Horizontal Vessel	Strik.Span:41,46,75 mm				
2		Opening of manways	Size: 78" ID x 204" LG	Comb.Span.:27,32mm				
3		Ventilation/Safety clearance	I.D. of Manway = 20 in.	Adjustable Spanner				
4		Internal Inspection of vessel and demister		Scaffolding				
5		Cleaning of complete vessel, Demister & LG's/LT's'						
6		Final inspection						
7		Вохир						
8		Deblinding						
MB2	V-100	LP Separator (01 No.)				1		
1		Blinding	Horizontal Vessel	St.Sp.:24,27,50,65 mm				
2		Opening of manways	Size: 78" ID x 204" LG	Comb.Sp.: 24,27mm				
3		Ventilation/Safety clearance	I.D. of Manway = 20 in.	Adjustable Spanner				
4		Internal Inspection of vessel						
5		Cleaning of vessel, demisters & LG's. Repair if any						

Act #	Tog #	OGDCL UCH-I GAS PROCES		Tools Required	Remarks	-	Unit Rate	Total Cost
	Tag #.	Job Description Final inspection	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
6								
7		Boxup				_		
8		Deblinding						
MB3	10V202	Amine Reflux Drum (02 Nos.)				2		
1	&	Blinding	I.D.=7 ft	Striking Spanner:32 mm				
2	20V202	Opening of manways	Length= 10 ft	General Tool Box				
3		Ventilation/Safety clearance	Manway = 20 in.	Internal Scaffolding				
4		Internal Inspection of vessel						
5		Dismantling/removal of demisters & repair if any						
6		Cleaning of vessel, demisters & LG/LT						
7		Re-installation of demisters						
8		Final inspection						
9		Вохир						
10		Deblinding						
MB4	10V200	Amine Flash Drum (02 Nos.)				2		
1	&	Blinding	I.D of Vessel = 126 in.	Str.Spanner: 36, 41 mm				
2	20V200	Opening of top dome & bottom manway	Length of Vessel = 28ft S-S	Open/Ring Sp: 27mm				
3		Ventilation/safety clearance	Top Dome= 30 in OD x 33 in LG	Crane				
4		Initial Inspection of vessel	Bottom manway = 20in I.D.					
5		Dismantling/removal of demisters & repair if any						
6		Internal cleaning of complete Vessel, LG/LT						
7		Cleaning of demisters & re-installation						
8		Final Inspection						
9		Box up						
10		Deblinding						
MB5	10V201	Amine Surge Drum (02 Nos.)				2		1

		OGDCL UCH-I GAS PROCI	ESSING PLANT - ATA 202	2 (MECHANICAL	SCOPE OF V	VORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
1	&	Blinding	I.D of Surge Drum = 108 in	Strik.Span: 36, 41 mm				
2	20V201	Opening of manways	Length of Vessel = 30 ft S-S					
3		Ventilation/safety clearance	I.D of manway = 20 in					
4		Internal cleaning of complete Vessel & LG's/LTS's						
5		Inspection						
6		Box up						
7		Deblinding						
MB6	90X903	Incinerator K.O Vessel (01 No.)				1		
1		Blinding	Vessel size: O.D. 60" x 28' LONG					
2		Opening of manways	Manway: 20"X150CL					
3		Ventilation/safety clearance						
4		Internal cleaning of complete vessel.						
5		Cleaning of LG's/LT's of K.O. vessel						
6		Inspection						
7		Box up						
8		Deblinding						
MB7	90V100A/B	Flare Knock Out Vessel (02 Nos.)				2		
1		Blinding	I.D of Surge Drum = 135 in					
2		Opening of manway	Length of Vessel = 288 in S-S					
3		Ventilation/Safety clearance	I.D of manway = 20 in					
4		Internal Inspection of vessel						
5		Cleaning of vessel & LG's / LT's						
6		Final inspection						
7		Вохир						
8		Deblinding						
MB8	90V902	Amine Sump (01 No.)				1		
1		Decanting of Sump	Vessel size: I.D. 84" x 127"T/T	Crane				1

		OGDCL UCH-I GAS PROCES	SING PLANT - ATA 202	2 (MECHANICAL	SCOPE OF V	VORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
2		Opening of manway/removal of A.Sump Pump	Manway: 20"					
3		Inspection of Pump and rectification if any						
4		Internal/extrernal cleaning of Sump						
5		Box up after inspection						
MB9	50V100	Glycol Sump (01 No.)				1		
1		Decanting of Sump	Vessel size: I.D. 40" x 120"T/T					
2		Opening of manway/Removal of Sump Pump	Manway: 20"					
3		Inspection of Pump and rectification if any						
4		Internal/extrernal cleaning of Sump						
5		Inspection of Vessel						
6		Box up						
MB10	10V100	Inlet Separator (02 Nos.)				2		
1	&	Blinding	I.D : 3 ft 6 inch,O.D : 4 ft	Str. Spanner: 50,65 mm				
2	20V100	Opening of manways	Length : 10 ft	General Tool Box				
3		Ventilation/Safety clearance	Inlet Nozzle = 12 in.	Crow bar				
4		Internal Inspection of vessel	Outlet Nozzle =12 in.					
5		Cleaning of vessel, LT's& LG's.	Manway=20 in					
6		Inspection/cleaning of Vane Pack & Liner						
7		Final inspection						
8		Вохир						
9		Deblinding						
GROU	P-C: HEAT EXCH	IANGERS:-						•
MC1	10E100	Inlet Gas Cooler Heater (02 Nos.)				2		
1	&	Blinding/Isolation	Type:U tube,No.of tubes=278	Crane, Chain Blocks,				
2	20E100	Opening of Channel Head Cover	278 U-Tubes x 1"(OD) x 0.065"					
3		Removal of bundle	(AW)x222" LG 1.25 square pitch					
4		Inspection of bundle						

Act #	Tag #.	OGDCL UCH-I GAS PROCES	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
5	145 #1	Cleaning of tubes & tube bundles by Water	Specifications	Tools Required	Remarks	QLY	Onicitate	Total Cost
5		jetting						
6		Cleaning & Painting of Shell and channel internal						
7		Insertion of Bundle						
8		Pressure Testing						
9		Final Inspection						
10		Box Up						
11		Deblinding						
MC2	10E200A/B	X-Heat Exchanger (04 Nos.)				4		
1	&	Opening of Inlet/Outlet nozzles	Plate Type Heat Exchanger		Arrangement for chem.			
2	20E200A/B	Provision of connection for chemical cleaning	No. of Plates = 431		circulation is available			
3		In place chemical cleaning of plates.			at site.			
4		Replacement of 01 No. Plate Pack						
5		Cleaning of dismantled Amine X-Heat Exchanger Plate Pack (01 no.) and Gasket Installation (if replaced)						
6		Removal of connections						
7		Cleaning/Repair of Strainers						
8		Box up						
9		Area cleaning						
MC3	10E201	Amine Stripper Reboiler (02 Nos.)				2		
1	&	Opening of Channel Head Covers	Type:I-Single pass,No.of tubes=2162	Sling, Shackles				
2	20E201	Cleaning of tubes by Hydrojetting	Size=1"(OD)x.065"(AW)x24'-0"(LG)	Strik.Span: 27,30 mm				
3		Inspection of Channel head / Tube sheet welding joints and repair (if req.)	Channel Head Cover : 69-1/8" OD x 2-7/8" THK	Hammers, Crow bar				
4		Hydro Pressure testing	Over all Length = 33ft & 9 in.					
5		Final Inspection		Scaffolding material				
6		Box up		Crane.				

		OGDCL UCH-I GAS PROCES	SING PLANT - ATA 202	22 (MECHANICAL	SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
7		Area cleaning						
MC4	10E202	Amine Reflux Condenser (02 Nos.)				2		
1	&	Opening of Channel Head Covers	Type:I-Double pass,No.of tubes =753	Sling				
2	20E202	Inspection of Channel head / Tube sheet welding joints and repair (if req.)	Size=1"(O.D)x.065"(A.W.)x24'- 0"(LG.)	Strik.Span: 27,30 mm				
3		Cleaning of tubes Mechanicallly & with Aquablaster	Channel head size:O.D.=49¼"	Hammers,				
4		Hydro Pressure testing	B .C. =47 5/8 "	Crow bar,				
5		Final Inspection	Over all Length = 29 ft& 4 in.	Scaffolding material				
6		Box up of Channel Head Covers		Crane				
7		Area cleaning						
MC5	10E203	Amine Solution Cooler (02 Nos.)				2		
1	&	Opening of Channel Head Covers	No. of tubes = 1184	Chain Block: 10 ton	Arrangement for chem.			
2	20E203	Cleaning of tubes with Aquablaster machine.	Tube O .D. = 1 in.	Strik.Span: 27,30,32mm	circulation is available			
3		Chemical Cleaning of Shell Side	Triangle pitch= 1.250	Comb. Span: 27,32mm	at site.			
4		Hydropressure testing	M.W.Thickness=0.075	Crow bar, Pipe Wrench				
5		Final Inspection	Length= 576 in. or 48 ft	Crane				
6		Box up of Channel Head Covers	No. of passes= One					
7		Area cleaning (house keeping)	Channel cover O.D.= 53 5/8 "					
GROU	P - D: ROTARY E	QUIPMENTS:-						
MD1	10P201A/B	Amine Circulation Pump (04 Nos)				4		
1	&	Decoupling of Pump & Motor	6-stage Centrifugal M type pump	Striking Spanner 36,41,				
2	20P201A/B	Initial Alignment check	Capacity=1800 gpm.	50 mm.				
3		Dismantling of bearing housings	Dis.Pressure= 930 psig	General Tool Box	l			
4		Removal of bearings for inspection	Suc.x Disch. = 8 x 6 in					
5		Cleaning/Repair/repl. of damage parts, if any	Make: Union Pumps Co., USA					

Act #	Tag #.	OGDCL UCH-I GAS PROCES	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
6	Tag #.	Service of Mechanical Seal (Dismantling, cleaning/lapping & re-assembly)	Specifications		Nemarks	Qiy	Onit Nate	
7		Assembling of bearing housing						+
8		Painting of Pump Body/Casing & Skid						+
9		Cleaning of suction & seal flush line strainers						
10		Alignment						+
10		Area cleaning						
MD2	10P200A/B	Amine Booster Pump (04 Nos.)				-		
	-	••••				4		
1	&	Decoupling of Pump & Motor	Single-stage Centrifugal pump	Strik.Span. 32,36,41mm				
2	20P200A/B	Dismantling of pump casing	Capacity=1980 gpm.	Comb.Spanner 24mm				
3		Inspection of casing	Pressure= 52 psig	General Tool Box				
4		Service of Mechanical Seal if any having leakage problem.	Suc.x Disch. = 10 x 8 in					
5		Replacement of bearings if required.	Make: Union Pumps Co., USA					-
6		Assembling of pump						
7		Painting of Pump Body/Casing & Skid						-
8		Alignment						
9		Cleaning of suction & seal flush line strainers						
10		Area cleaning						
MD3	10P202A/B	Amine Reflux Pumps (04 Nos.)				4		
1	&	Dismantling of pump	Single-stage Vertical Centrifugal pump	General Tool Box				
2	20P202A/B	Inspection of casing	Capacity=100 gpm.					
3		Cleaning/Repair/repl. of damage parts/M.Seal etc.	Dis.Pressure= 66 psig					
4		Assembling of pump	Suc.x Disch. = 3 x 2 in					
5		Cleaning of suction & seal flush line strainer						
6		Painting of Pump outer body/casing						
7		Area cleaning						
MD4	10-P-200 A/B	Glycol Circulation Pump (04 Nos.)				4		

		OGDCL UCH-I GAS PROCES	SING PLANT - ATA 202	22 (MECHANICAL	SCOPE OF V	VORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
1	20-P-200 A/B	Inspection of power end, i.e. sleeve bearings, crankshaft, crosshead pin & bush for any wear & tear and repalce if required	Reciprocating Capacity = 42.2 US GPM Make: Union Pumps Co., USA	General Tool Box				
2		Inspection of fluid end, i.e. plunger, inlet/outlet valves, gland pusher/ bush/packing etc. for any wear & tear and replace if required	Dis. Pressure = 935.1 psia Size/type : 2 ½ X 3 TD 60					
3		Inspection of sheeves/pulleys & V-belts and replace (if required)						
4		Replacement of lube oil						
5		Alignment						
6		Area claining (House keeping)						
MD5	90X903	Cooling Tower Fan/Gearbox-A/B/C/D (04 Nos.)				4		
1		Dismantling, Cleaning, Repairing & Painting of Fan Blades & hub	AMARILLO Right Angle Grear Drive	General Tool Box				
2		Dismantling of Gearbox	Service Factor: 2.0 HP					
3		Shifting of Gearbox to Workshop	RPM Input: 1750					
4		Inspection / repair of Gearboxes	Ratio: 14:1 Reducing					
5		Grey epoxy paint to outer surface of gear box, fan and foundation structure channels.						
6		Re-installation of Gear boxes and Fans						
7		Replacement of Lube Oil						
8		Alignment						
9		Area cleaning						
MD6	LP-1/2/3	FD Fan LP Boiler #1 , 2 & 3 (03 Nos.)				3		
1		Opening of FD Fan inspection windows.		General Tool Box				
2		Inspection/cleaning of Fan duct/dampers.						
3		Replacement of bearings of FD Fan						
4		Alignment						
5		Area cleaning						

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
MD7	EGT-1,2,3,4	Gas Turbine (04 Nos)		-		4		
1		Inspection/Cleaning of EGT's Fuel Gas Separators.	EUROPEAN GAS TURBINE	General Tool Box				
2		Inspection / replacement of Fuel Gas Skid Filters	MAKE: SIEMENS, UK					
3		Cleaning/Replacement of Air Intake Filters (80 nos.each unit)	CAP: 4.9 MW AT 15 <sup>0</sup> C					
4		External Cleaning of Lube Oil Coolers	MODEL: SGT-100-1S					
5		Overall cleaning of Turbine enclosure						
6		Area cleaning						
MD8	X-200A-D	Instrument Air & Nitrogen Package Compressors (06 Nos.)				6		
1	X-201A/B	Overall cleaning of enclosure	MAKE: INGERSOLL-RAND &	General Tool Box				
2		Alignment checks and inspection/cleaning of complete packages	QUINCY					
3		Cleaning of Oil Cooler/Radiator	Type: Screw Compressor					
4		Inspection/repair of Compressor Airend, if req.						
5		Replacement of Filter Elements & Coolant, if required						
6		Area cleaning						
MD9	90P900A	Cooling Water Circulation Pump (01 No.)				1		
1		Dismantling/Removal of pump from site.	Single Stage Vertical Turbine Pump	Striking Spanner 36,41,				
2		Inspection of complete pump casing, strainers etc.	Dis.Capacity= 15000 GPM	General Tool Box				
3		Dismantelling/overhauling of pump if any found critical damaged.	Dis.Press.= 60 PSIG					
4		Installation of Pump.						
5		Area cleaning						
GROUP	-E: UTILITIES:-	•	•					
ME1	1705101	ETP Sump Pit				1		

		OGDCL UCH-I GAS PROCES	SING PLANT - ATA 202	2 (MECHANICAL	SCOPE OF V	VORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
1		Internal cleaning i.e.removal of mud/slurry	Size :4.0 M X 3.0 M X 3.6 M	Scrapper and buckets				
2		Cleaning of Suction Foot Valve		Special mud/slurry decanting				
3		Inspection		submersible Pump				
ME2	90PF910	Pressure Filters (02 Nos.)				2		
1	A/B	Scaffolding	Vessel Size: 98"I.D.x 145"HT					
2		Opening of manways.	Manway: 20" x 150 CL					
3		Removal, Cleaning & Charging of gravel/sand/resin (optional) i.e. if required						
4		Repair/Painting of Shell Internal and distributor						
5		Inspection						
6		Box up						
ME3	90SF910	Side Stream Filters (02 Nos.)				2		
1	B/C	Scaffolding	Vessel Size: 98"I.D.x 145"HT					
2		Opening of top manway	Manway: 20" x 150 CL					
3		Removal & charging of gravel/sand/resin (optional) i.e. if required						
4		Repair/Painting of Shell Internal and distributor						
5		Inspection						
6		Box up						
ME4	90V900	Deaerator				1		
1		Opening of manway	Manway: 20x150lb"					
2		Dismantling of top Dome	Size:2500mm DIA x 5800mm LG					
3		Internal cleaning of vessel, LG's LT's						
4		Repair of shell internal & internal distribution pipe, nozzle(s) if required.						
5		External Painting of complete vessel						
6		Inspection of nozzles						
7		Box up						

A	To - #	OGDCL UCH-I GAS PROCES				-	Linit Data	Total Cast
Act #	Tag #. 90X902A	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
ME5		LP BOILER # 1, 2 & 3 (03 Nos)				3		
1	90X902B	Blinding	Model # NSX-G-100	Air driven Grinders				
2	90X902D	Opening of manways of Combustion chamber, Mud and Steam drums.	Make(LP-1&2): National Dynamic Corporation Nebraska USA	Power Brushes for cleaning				
3		Internal inspection of comb. Chamber, Mud and Steam drums.	W. Pressure = 70 psig.					
4		Internal cleaning of tubes(Chem./Mech.)	Steam temperature=315 deg.F					
5		Cleaning of burners & comb. Chamber and sight glasses	Max .W. Pressure = 200 psig.					
6		Repair of refractory, if any	Steam capacity = 145000 lbs/hr					
7		Cleaning of Mud & Steam drums	Tube size= 02"x 0.095 &0.105 in.th					
8		Painiting of tubes, steam drum & mud drum with apexior compound paint.	Total nos. of tubes = 1742					
9		Hydro/Pressure Test	Material of drums = SA – 516- 70					
10		Cleaning of flue gasses chimeny, painting internally & externally including structure/platforms	Material of tubes = SA-178 A					
11		Painting of Boilers outer body/casing/structure.	Make (LP-3): Descon-Lahore					
12		Inspection by Chief Inspector of Boilers						
13		Gas Fuel line strainer cleaning						
14		Inspection/Repair/Replacement of LP steam traps						
15		Box up						
16		Deblinding						
ME6	90X902C	HP BOILER# 1 & 2 (02 Nos.)				2		
1	&	Blinding	Model # HRNC-480	Air driven Grinders				
2	90X902E	Opening of manways of Combustion chamber, Mud and Steam drums.	Make (HP-1): WICKERS HOSKINS(M)SDN. BHD	Power Brushes for cleaning				
3		Internal inspection of comb. Chamber, Mud and Steam drums.	W. Pressure = 497 psig.					

Act #	Tag #.	Job Description	Specifications	<b>Tools Required</b>	Remarks	Qty	Unit Rate	Total Cost
4		Internal cleaning of tubes (Chem./Mech.)	Steam capacity= 10500 lbd/hr	· · ·				
5		Cleaning of burners & comb. Chamber and sight glasses	Max .W. Pressure = 568 psig.					
6		Repair of refractory, if any	Test Pressure = 852 psig.					
7		Cleaning of Mud & Steam drums	Steam temperature= 477 deg.F					
8		Damper cleaning/servicing						
9		Painiting of tubes, steam drum & mud drum with apexior compound paint.	Size of water tube=02 in.dia.x0.128"th					
10		Hydro/Pressure Test	Total nos. of finned tubes = 110					
11		Inspection by Chief Inspector of Boilers	Material of tubes= SA- 192					
12		Opening of flue gasses chimeny manway. External painting of stack/chimney.	Make (HP-2): HMC, Taxila					
13		Painting of Boilers outer body/casing/structure.						
14		Inspection /Replacement of HP Steam traps						
15		Gas Fuel line strainer cleaning						
16		Box up and deblinding						
ME7	90X903	COOLING TOWER				1		
1		Cleaning of top water deck & nozzles	Type: Induced Draft Counterflow					
2		Cleaning of CT basin & pump suction pit	Design Water Circulation:27000 USGPM					
3		Cleaning, Repair and Painting of suction pit gate strainers/structure, if any	No. of Cell: 04					
4		Removal/cleaning/Re-Installation of drift eliminators	Basin Size(LxWxD): 144x48x4 ft.					
5		Inspection/Installation of damaged/fallen fills,drift eliminator & fill supports/hangers etc.						
6		Inspection/repair of internal cell walls, walk ways, Side walls, Louvers, Top Deck, water distribution/nozzle area etc. (FRP repairs)			FRP work shall be carried out by expert firm in field of FRP Cooling Towers			
7		Torque tightening of structure nut/bolts						1

		OGDCL UCH-I GAS PROCES	SING PLANT - ATA 202	22 (MECHANICAL	SCOPE OF W	/ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
8		Civil repair of CWP suction pit (Plaster repair) and Cooling Tower basin (Seepage repair)						
9		Cleaning / repair of pump suction strainers						
ME8	90X904	INCINERATOR				1		
1		Opening of manway	Manway: 24"					
2		Initial Inspection	Size: I.D. 4ft, Length: 5ft					
3		Repair of Burner duct, furnace & exhaust duct and stack refractory & external insulation etc.	Size: I.D. 10ft, Length: 37.5ft					
4		Cleaning/replacement of flame sight glasses						
5		Cleaning of burner tips						
6		Repair / replacement of ceramic wool of Combustion chamber.						
7		Cleaning of FD Fans, dampers & links. (repair if req.)						
8		Inspection						
9		Box up						
GROU	P-F: MANUAL V	ALVES:-						
MF1	H2S T-10	Manual Valves of H2S T-10			Valves list attached	36		
1		Dismantling of Valves from location						
2		Shifting of valves to workshop						
3		Initial Testing/Inspection of valves						
4		Repair of defected valves						
5		Pressure Testing						
6		Painting of Valves with Silver/Aluminium Paint.						
7		Shifting / Installation of valves at location						
8		Replacement of Valves having size 1-1/2" & below						
9		Inplace cleaning/service & greasing of manual valves of H2S T-10 as per operation requirement						

		OGDCL UCH-I GAS PROCESSIN						1 .
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
MF2	H2S T-20	Manual Valves of H2S T-20			Valves list	33		
1		Dismantling of Valves from location			attached			
2		Shifting of valves to workshop						
3		Testing/Inspection of valves						
4		Repair of defected valves						
5		Pressure Testing						
6		Painting of Valves with Silver/Aluminium Paint.						
7		Shifting / Installation of valves at location						
8		Replacement of Valves having size 1-1/2" & below						
9		Inplace cleaning/service & greasing of all manual valves of H2S T-20						
MF3	Dehy.	Manual Valves of Dehydration			Valves list attached	26		
1	T-10, 20 &30	Dismantling of Valves from location						
2		Shifting of valves to workshop						
3		Testing/Inspection of valves						
4		Repair of defected valves						
5		Pressure Testing						
6		Painting of Valves with Silver/Aluminium Paint.						
7		Shifting / Installation of valves at location						
8		Inplace cleaning/service & greasing of all manual valves of Dehy. T-10 & 20						
MF4	UTILITIES &	Manual Valves of Utilities & Gathering Area			Valves list attached	24		
1	GATHERING	Dismantling of Valves from location						1
2		Shifting of valves to workshop						
3		Testing/Inspection of valves						
4		Repair of defected valves						-

Act #	Tag #.	OGDCL UCH-I GAS PROCES Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
5	105 #.	Pressure Testing		Tools Required	Remarks	Qty	Onicitate	
6		Painting of Valves with Silver/Aluminium Paint.						
7		Shifting / Installation of valves at location						
8		Inplace cleaning/service & greasing of all manual valves of Utilities area						
MF5		Manual Valves Onsite Service/Greasing			Valves list attached	32		
1		Onsite service, greasing and gland replacement (if required)						
GROUP	-G: MISCELLAN	NEOUS JOBS:-						
MG1	Flare Stack	Inspection of main flare stack diode seal						
MG2	10/20-S-202	LG's / LT's cleaning of filter coalescer						
MG3		Insulation Jobs:- To remove/install insulation at Misc. Piping of Plant	XHE H2S Trains: [12", 5' long] X 4 Booster Pumps: [6", 25' long] X 2 Condensate Pot: [4", 10' long] X 2 Steam Cir. Dehy : [3", 10' long] X 2 Other Minor Patches					
Paint Jo	bs:-		Approx. Dimensions					
MG4		Flare header from gas turbines fuel gas to boilers fuel gas skid.	[8", 250' long]	Work at Height				
MG5		EGT's gas 2" vent header from EGT-1 to turbines fuel gas skid	[2", 250' long]	Work at Height				
MG6		EGTs gas 2" line from slug catcher area to incinerator	[2", 150' long]	Work at Height				
MG7	10/20-V-201	Surge drums PSV downstream line to flare header in H2S area	[4", 35' long] X 2	Work at Height				
MG8		Amine booster pump recycle line to surge drum in H2S area	[6", 25' long] X 2	Work at Height				
MG9		Cooling Water return header 30" from CW blow down to upward Cell A-D.	[30", 60' long] + [20", 85' long]					

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
MG10		Pressure Filters & Side Stream Filter Piping Segments	[8", 15' long] x 10					
MG11		Pressure Filters & Side Stream Filter Common Drain	[8", 35' long]					
MG12		LP-3 BFWP suction/discharge lines + header	[8", 6' long]x2 + [8"x15' long]					
MG13		HP BFWP (A/B) suction/discharge lines	[2.5", 15' long]x2 + [1.5"x30' long]					
MG14		HP BFWP (C/D) suction/discharge lines	[3", 15' long]x2 + [2"x30' long]					
MG15		LP BFWP recycle line	[2"x60' long]					
GROU	P-H: MODIFICATI	ON/FABRICATION JOBS:-						
MH1	10/20-E-200	Leakage rectification lean/rich amine nozzles/lines from stripper to 10/20-E-200 A/B (XHE)	12" joint, CS			4 joints		
MH2	90X903	Incinerator K.O Vessel Acid gases bypass line spool replacement (Pre-Fab job)	18" dia CS Line	12 ft spool change req		2 joints		
MH3	HP Steam Circuit	Provision of two drain points on HP steam condensate return header in order to depressurize and drain the header (With double drain valves on each point).	CS, 3/4" (12 joints) x 2		01 Point at Dehy Area & 01 Point at Boiler Area	24 joints		
MH4	Deaerator	De-areator blow-down line (2"), highly corroded need replacement	CS, 2" Joints			2 joints		
MH5	Valves Replac	ement (Welding/Fabrication Jobs):-	I					
1	INLET SEPARATOR (10- V-100)	ISOLATION VALVES OF 10-LT-104 (HC SIDE)	Gate Valve (SW),1-1/2", 800 lb		SS	2 valves		
2		DRAIN VALVE OF HC SIDE LEVEL TROLL	Gate Valve (SW) 3/4" x 800 lb		SS	1 valve		
3		DRAIN VALVE OF P/W SIDE LEVEL TROLL	Gate Valve (SW) 3/4" x 800 lb		SS	1 valve		

Act #	Tag #.	Job Description	Specifications	<b>Tools Required</b>	Remarks	Qty	Unit Rate	Total Cost
4	AMINE STRIPPER REFLUX DRUM (10-V- 202)	NITROGEN VALVE (N2) TO REFLUX DRUM	Gate Valve (Threaded), 3/4"X800		CS	1 valve		
5	INLET SEPARATOR (20- V-100)	DRAIN VALVE P/W SIDE LEVEL SWITCH 20-LSLL-101	Gate Valve(SW)1/2"X800,		CS	1 valve		
6	INTEGRAL SCRUBBER (30-C-100/v-100)	OPEN DRAIN VALVE OF INTEGRAL SCRUBBER	Gate Valve (SW), 3/4x800lb		SS	1 valve		
7	BOILER AREA	HP HEADER DRAIN VALVE	Gate Valve (SW), 3/4x800lb		CS	1 valve		
8		LP HEADER DRAIN VALVE	Gate Valve (SW), 3/4x800lb		CS	1 valve		
9		LP-3 STEAM SAMPLE POINT VALVE	Gate Valve (SW), 1/2"x800lb		CS	1 valve		
10	DEAREATOR	LCV (TOP PLATEFORM) BY-PASS VALVE	Globe Valve (SW), 1- 1/2"x800lb		CS	1 valve		
11	SOFT WATER PUMPS	RECYCLE VALVES	Gate Valve (SW), 1"x800lb		CS	4 valves		
12	Gas Turbines	AUTO-DRAIN VALVE: AD-140 OF F-100A	Ball/Plug Valve (SW), 1" 600 Ib		SS, (Black-out Activity)	1 valve		
13	AMINE STRIPPER (10-C-200)	DRAIN VALVE REPLACEMENT OF STRIPPER TROLL	Gate Valve (Threaded), 3/4"X800		CS	1 valve		

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
SWITC	HGEAR ROOM:			Required	Location			
1	10-P-200A	LV(380V) Modules	Amine Booster P.M. Modules, 380v, 138A,		LV & EGTs MCC	1		
2	10-P-200B	Inspection, Servicing, Cleaning, Testing	100hp		Modules	1		
3	20-P-200A	of Contactors, Thermal Relays, Aux.	Amine Booster P. M. Modules, 380v, 138A,			1		
4	20-P-200B	Contactors, Power Points & tightening of all connections. Thermography of all	100hp			1		
5	10-P-202A	modules.	Amine S. Reflux P.M. Modules, 380v, 15.5A,			1		
6	10-P-202B		10hp			1		
7	20-P-202A		Amine S. Reflux P. Motor, 380v, 15.5A, 10hp			1		
8	20-P-202B					1		
9	90-X-903A	1	Cooling Tower Fan Motor , 380v, 210A,			1		
10	90-X-903B		150hp			1		
11	90-X-903C	1				1		
12	90-P-911A	1	Raw Water P. Motor 380v, 138A,			1		
13	90-P-911B	1	100hp			1		
14	90-P-911C	7				1		
15	90-P-902A		L.P Boiler Feed Water P. Motor 380v, 66.4A,			1		
16	90-P-902B		50hp			1		
17	Siemens Pond 1		Siemens Pond water motor modules, 380 V,			1		
18	Siemens Pond 2		40 HP			1		
19	Siemens Pond 3					1		
20	HP Bolier Switchgear		H.P Boiler Switch gear			1		
21	HP Boiler Feed Water Switchgear	1	HP Boiler Feed Water Switchgear			1		
22	90-X-904A	1	Incinerator F.D Fan Motor , 380v, 22A,			1		
23	90-X-904B	1	15kw			1		
24	10-P-200A	1	Glycol Circulation P. Motor 25kw,			1		
25	10-P-200B	1	380v, 52amps			1		
26	20-P-200A	1	Glycol Circulation P. Motor 25kw,			1		
27	20-P-200B	1	380v, 52amps			1		

		OGDCL UCH-1 GAS	S PROCESSING PLANT - ATA 2022 (EL	ECTRICAL SCO	OPE OF WORK)			
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
28	UCH2-BL-ST		UCH-2 Black Start Panel			1		
29	2A		ABLOC Fan Motor 380v, 25.8A, 9.5 Kw			1		
30	3A					1		
31	4A					1		
32	2A		Enclosure Vent Fan Motor 380v, 55A, 30kw			1		
33	3A					1		
34	4A					1		
35	2A	1	Gen: CACA Fan Motor 380v. 8.7A, 4kw			1		
36	2B	1				1		
37	3A					1		
38	3B	•				1		
39	4A	•				1		
40	4B	•				1		
41	2A	•	VGV Motor 380v, 3.6A, 1.5kw			1		
42	3A	•				1		
43	4A	•				1		
44	Incomer Tafo 1 & 2		LV incomer of trafo 1 & 2, ACB, 3200 Amp,TERASAKI		LV incomer of Trafo 1 & 2	2		
45	LV Bus ACBs		ACBs installed on LV Bus 2000 Amp, TERASAKI		LV Bus 181 & 176 ACBs	2		
46	Essential Bus ACBs		ACBs installed on Essential bus 1200 Amp & 800 Amp, Merlin Gerin		Essential Bus ACBs	2		
47	LV Bus	<b>LV(380V) Bus Bar</b> Inspection, Cleaning, Tightening, Maggar,Thermography of Bus Bars	LV Bus Bar 176,181		LV Bus Bar	2		
48	10-P-201A	MV(6.6KV) ModulesInspection,	Amine Circulation P. Motor, 6.6kv, 117A,		MV Modules	1		
49	10-P-201B	Servicing, Cleaning, Testing of	1500hp			1		
50	20-P-201A	Contactors, Thermal Relays, Aux. Contactors, Power Points, & Tightening	Amine Circulation P. Motor 20-P-201, 6.6 Kv,			1		
51	20-P-201B	of all connections. Thermography of all	117A, 1500hp			1		
52	90-P-900A	modules.	Cooling Water Circulation P.			1		

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
53	90-P-900B		Motor,6.6kv, 67A, 700hp	•		1		
54	90-P-900C					1		
55	90-X-902A	]	L. P. Boiler F. D. Fan Motor, 6.6kv, 20A,			1		
56	90-X-902B		250hp			1		
57	52-A		Main Incoming Vacuum Circuit Breaker 52			1		
58	52-B		A/B/Tie, 6.6kv, 1200A			1		
59	Transformer MV Modules		Vacuum Contactors of Transformer 1 & 2, 2500 KVA, 6.6KV			2		
60	EGT VCBs	Inspection, service, maintenance, tightening of connections and function test of VCBs.Measurement of VCB closing time and opening time for EGTs VCBs (04 Nos, 630 Amps, make: ABB) with help of proper, calibrated tools and equipments. This job is to be carried out by OEM of VCB i.e. M/S ABB Engineer Only.	Vacuum Circuit Breaker of EGTs and Unit Transformer, 6.6KV		VCBs	5		
61	Transformers	Inspection, cleaning of transformers, BTD, Power/ control connections. Complete oil testing i.e. multi DGA and dielectric strength test, water content for all transformers. Oil dehydration if required after test. Testing/Calibration of instruments installed on transformers.	Transformer 1 and 2, Unit Transformer, UCH-2 Black Start, Colony and Pat FeederTransformer		Transformers	6		
62	MV Bus	MV(6.6KV) Bus Bar Inspection, Cleaning, Tightening, Thermography of Bus Bar	MV Bus Bar		MV Bus Bar	1		
63	1	Battery Charger and Battery Bank	Battery Chargers and Battery Banks Of EGTs		Battery Room	1		

	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
2	Inspection, Cleaning, Checking And				1		
	Tightening of connections, Chargers &						
3	Battery Cabinets. Batteries Inspection,				1		
4					1		
1		20 1/1/4 1105		LIDC	1		
1		30 KVA UPS		UPS	T		
1		30 KVA UPS (Stand by)			1		
_					_		
	Servicing. Replacement of bank if						
	required after inspection.						
1	Inspection, Tightening of	Static Transfer Switch		STS	1		
	connections, Preventive maintenance						
	on by pass mode and general cleaning.						
X-200A	LV(380V) ModulesInspection, Servicing,	Inst. Air Comp. Main Motor (Caps) , 380v,		Instrument Air	1		
X-200B		67A, 50hp		Compressors	1		
X-200C		Quincy Inst. Air Comp. Motor, 380v, 67A,			1		
X-200D	Points, rightening of all connections.	50hp			1		
X-201A(181)	7	Inert Gas Comp. Motor, 380v, 44A, 30hp			1		
X-201B(176)					1		
2	EGT Generators	Main Generator, PMG & Exciter Units.		EGTs	1		
2					1		
5					1		
4	Generator's outer body.				1		
LP3-MCC	LV(380V) Modules	MCC Panel of LP Boiler 3		LP boiler 3	5		
	X-200A X-200B X-200C X-200D X-201A(181) X-201B(176) 2 3 4	of bank if required after inspection.1Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.1Batteries Inspection, load testing, tightening, greasing of connections & Servicing. Replacement of bank if required after inspection.1Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.1Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.X-200ALV(380V) ModulesInspection, Servicing, Cleaning, Testing of Contactors, Thermal Relays, Aux. Contactors, Power Points, Tightening of all connections.X-201A(181)ZX-201B(176)EGT Generators Checking of Generators' connections, Exciters, PMGs, Diode Assembly. Inspection and removal of dust and webs. Cleaning & Washing of Generator's outer body.4	4     connections & Servicing. Replacement of bank if required after inspection.     30 KVA UPS       1     Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.     30 KVA UPS (Stand by)       1     Batteries Inspection, load testing, tightening, greasing of connections & Servicing. Replacement of bank if required after inspection.     30 KVA UPS (Stand by)       1     Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.     30 KVA UPS (Stand by)       1     Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.     Static Transfer Switch       X-200A     LV(380V) ModulesInspection, Servicing, Cleaning, Testing of Contactors, Thermal Relays, Aux. Contactors, Power Points, Tightening of all connections.     Inst. Air Comp. Main Motor (Caps) , 380v, 67A, 50hp       X-201A(181)     X-2014(181)     Intert Gas Comp. Motor, 380v, 44A, 30hp       X-2018(176)     EGT Generators Checking of Generators' connections, Exciters, PMGs,Diode Assembly. Inspection and removal of dust and webs. Cleaning & Washing of Generator's outer body.     Main Generator, PMG & Exciter Units.       4     LV(380V) Modules Inspection, Servicing, Cleaning, Testing of Contactors, Thermal Relays, Aux. Contactors, Power Points, Tightening of     MCC Panel of LP Boiler 3	4       connections & Servicing. Replacement of bank if required after inspection.       30 KVA UPS         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning, tightening, greasing of connections & Servicing. Replacement of bank if required after inspection.       30 KVA UPS (Stand by)         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.       30 KVA UPS (Stand by)         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.       Static Transfer Switch         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.       Inst. Air Comp. Main Motor (Caps) , 380v, 67A, S0hp         X-200A       LV(380V) ModulesInspection, Servicing, Cleaning, Testing of Contactors, Points, Tightening of all connections.       Inst. Air Comp. Main Motor (Caps) , 380v, 67A, 50hp         X-201A(181)       Inert Gas Comp. Motor, 380v, 44A, 30hp       Inert Gas Comp. Motor, 380v, 44A, 30hp         X-201B(176)       EGT Generators' Checking of Generators' connections, Exciters, PMGs, Diode Assembly. Inspection and removal of dust and webs. Cleaning & Washing of Generator's outer body.       Main Generator, PMG & Exciter Units.         4       LV(380V) Modules Inspection, Servicing, Cleaning, Testing of Contactors, Power Points, Tightening of       MCC Panel of LP Boiler 3         Inspection, Servicing, Cleaning, Testing of Contactors, Power Points, Tightening of       MCC Panel of LP B	4       connections & Servicing, Replacement of bank if required after inspection. Inspection, Fightening of connections, Preventive maintenance on by pass mode and general cleaning. Tequired after inspection.       30 KVA UPS       UPS         1       Batteries Inspection, load testing, tightening, greasing of connections & Servicing. Replacement of bank if required after inspection.       30 KVA UPS (Stand by)       UPS         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.       Static Transfer Switch       STS         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.       Inst. Air Comp. Main Motor (Caps), 380v, 67A, 50hp       Instrument Air Compressors         X-200A       LV(380V) Modulesinspection, Servicing, Thermal Relays, Aux. Contactors, Power Points, Tightening of all connections, X-200B       Inst. Air Comp. Motor, 380v, 67A, 50hp       Instrument Air Compressors         X-201B(176)       EGT Generators       Inert Gas Comp. Motor, 380v, 44A, 30hp       EGTs         2       EGT Generators Checking of Generators' connections, Exciters, PMGs, Diode Assembly.       Main Generator, PMG & Exciter Units.       EGTs         3       Inspection and removal of dust and webs. Cleaning & Washing of Generator's outer body.       MCC Panel of LP Boiler 3       LP boiler 3         4       LP3-MCC       LV(380V) Modules Inspection, Servicing, Cleaning, Testing of Contactors, Newer Points, Tightening of       MCC Panel of L	4       connections & Servicing, Replacement of bank if required after inspection.       1       1         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning, tightening, greasing of connections & Servicing, Replacement of bank if required after inspection.       30 KVA UPS (Stand by)       1         1       Batteries Inspection, load testing, tightening, greasing of connections, Servicing, Replacement of bank if required after inspection.       30 KVA UPS (Stand by)       1         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.       Static Transfer Switch       STS       1         X-200A       LV(380V) ModulesInspection, Servicing, Cleaning, Testing of Contactors, Thermal Relays, Aux. Contactors, Power Points, Tightening of all connections, X-200B       Inst. Air Comp. Main Motor (Caps) , 380v, 67A, 50hp       Instrument Air Quincy Inst. Air Comp. Motor, 380v, 67A, 50hp       Instrument Air Compressors       1         2       EGT Generators Checking of Generators' connections, Exciters, PMGs, Diode Assembly.       Main Generator, PMG & Exciter Units.       EGTs       1         3       Main Generator, PMG & Exciter Units.       EGTs       1       1         4       Checking of Generators' connections, Exciters, PMGs, Diode Assembly.       Main Generator, PMG & Exciter Units.       IP boiler 3       1         3       Inspection, Servicing, Cleaning, Testing of Contactors, New Points, Tight	4       connections & Servicing, Replacement of bank if required after inspection, connections, Preventive maintenance on by pass mode and general cleaning.       30 KVA UPS       UPS       1         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.       30 KVA UPS (Stand by)       1       1         1       Batteries inspection, load testing, tightening, greasing of connections & Servicing, Replacement of bank if required after inspection.       30 KVA UPS (Stand by)       1       1         1       Inspection, Tightening of connections, Preventive maintenance on by pass mode and general cleaning.       Static Transfer Switch       Static Transfer Switch       1       1         X-200A       LV[380V] Modules inspection, Servicing, Connections, Preventive maintenance on by pass mode and general cleaning.       Inst. Air Comp. Main Motor (Caps), 380v, 67A, 50hp       1       1         X-200A       LV[380V] Modules inspection, Servicing, Connections, Preventive maintenance on by pass mode and general cleaning.       Inst. Air Comp. Motor, 380v, 67A, 50hp       1       1         X-201A(181)       Instrument Air Compressors       1       1       1         X-201A(181)       Instrument Air Checking of Generators' connections, Exciters, PMGs, Diode Assembly, Sectiers, PMGs, Diode Assembly, Sectiers, PMGs, Diode Assembly, Sectiers, PMGs, Diode Assembly, Sectiers, PMGs, Diode Assembly, Number Connectors, Power Points, Tightening of Contactors, Thermal Relays, Aux, Contactors, Thermal Relays,

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
79		Allied Services for Electric Supply At Different Locations of Plant.	Allied Services		Whole Plant			
80	Eps	Cleaning, testing and resistivity measurement of Earth pits at UCH-1 and Colony	Earth Resistance Measurement			70		
81	LIGHTS	Maintenance, cleaning, refurbishement, replacement (if required) of skid(2x36W) and ploe lights (250W, 400W) at UCH-1 and Colony	Job on Skid and Pole lights		Amine, Dehydration , EGTs, Utility Systems, Colony	75		
82	1 job	Inspection, Cleaning Of Switch Gear,DBs, tightening of control and	LT Switch Gear Installed in Residential Colony		LV Switch Gear	1		
83	1 job	power cables.	LT Switch Gear installed at Pat Feeder Wa Pumping Station	er	LV Switch Gear and MCCs	1		
84	DBs	Inspection, servicing cleaning, tightness of DBs Installed in plant area, workshops, offices and admin building of UCH-1	Maintenance of DBs		LT DBs	25		
85	DBs	Inspection, servicing cleaning, tightness of DBs Installed in different Areas of UCH Colony and colony water supply motor modules	Maintenance of DBs		LT DBs	30		
H2S REN	10VAL PLANT ARE	EA MOTORS			Location			
1	10-P-201A	MV (6.6KV) MOTORS Cleaning of motor and heat exchanger, Meggering Of Windings, Inspection,	Amine Circulation P. Motor, 6.6kv, 117A, 1500hp		Train – 10	1		
2	10-P-201B	Tightening Of Connections In JBs, And Earth Testing. Bearings clearance check.				1		
3	20-P-201A	Replacement Of Bearings (If Required after Inspection)	Amine Circulation P. Motor, 6.6kv 117A, 1500hp		Train – 20	1		
4	20-P-201B					1		
5	10-P-200A	LV (380V) MOTORS	Amine Booster P. Motor, 380v,		Train – 10	1		
6	10-P-200B	Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required),	138A, 100hp			1		
7	20-P-200A	<ul> <li>Meggering Of Windings, Inspection,</li> </ul>	Amine Booster P. Motor, 380v,		Train – 20	1		
8	20-P-200B		138A, 100hp			1		

Act #	Tag #.	Job Description	Specifications		Tools Required	Remarks	Qty	Unit Rate	Total Cost
9	10-P-202A	Tightening Of Connections In JBs and	-	v, 15.5A,		Train – 10	1		
10	10-P-202B	Earth Testing	10hp				1		
11	20-P-202A		Amine S. Reflux P. Motor,	380v,		Train – 20	1		
12	20-P-202B		15.5A, 10hp				1		
UTILITY	AREA MOTORS		·			Location			
13	90-P-900A	MV (6.6KV) MOTORS Cleaning, Greasing , Meggering Of Windings, Inspection, Tightening Of	Cooling Water Circulation P. Me 6.6kv, 67A, 700hp	otor,		Cooling Tower	1		
14	90-P-900B	Connections In JBs, Earth Testing and Paint Job. Replacement of Bearings (If					1		
15	90-P-900C	<ul> <li>Required after Inspection)</li> </ul>					1		
16	90-X-903A	LV (380V) MOTORS Cleaning, Greasing & Replacement Of	Cooling Tower Fan Motor, 210A, 150hp	380v,		Top Of Cooling Tower	1		
17	90-X-903B	Bearings and Paint Job (If Required), Meggering Of Windings, Inspection,					1		
18	90-X-903C	Tightening Of Connections In JBs, And Earth Testing.					1		
19	90-X-903D						1		
JTILITY	AREA MOTORS					Location			
20	90-P-901A	LV (380V) MOTORS Cleaning, Greasing & Replacement Of	Treated Water P. Motor, 14.5A, 10hp	380v,		Blow The De-Rater Tank.	1		
21	90-P-901B	Bearings and Paint Job (If Required),					1		
22	90-P-901C	Meggering Of Windings, Inspection,		200			1		
23	90-P-902A	Tightening Of Connections In JBs, And	L.P.B. Feed Water P. Motor, 66.4A, 50hp	380v,			1		
24	90-P-902B	Earth Testing.	ig. 00.4A, 50ip		1				
25 26	90-P-902C 90-P-902D						1		
20	90-P-902D 90-P-903B	LV (380V) MOTORS Cleaning, Greasing & Replacement Of	H.P.B. Feed Water P. Motor 380V, 40HP, 53A	· ,		Below The De- Rater Tank.	1		
28	90-P-903C	<ul> <li>Bearings and Paint Job (If Required),</li> <li>Meggering Of Windings, Inspection,</li> <li>Tightening Of Connections In JBs, And</li> </ul>					1		

		OGDCL UCH-1 GAS	S PROCESSING PLANT - ATA 2022 (E	LECTRICAL SCO	OPE OF WORK)			
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
29	90-P-903D	Earth Testing.				1		
30	90-X-902A	MV (6.6KV) MOTORS Cleaning, Greasing, & Replacement Of	F. D. Fan Motor 6.6kv, 20A, 250hp		L.P. Boiler "A" & "B"	1		
31	90-X-902B	Bearings, Paint Job (If Required) Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.				1		
32	HP-1	LV (380V) MOTORS Cleaning, Greasing & Replacement Of	H.P. Boiler Air Blower Motor 380v, 4.5A, 2.2kw		H.P Boiler	1		
33	HP-1	Bearings, Paint Job (If Required), Meggering Of Windings, Inspection,	H.P. Boiler FD Fan Motor 380v, 22A, 15kw			1		
34	HP-2	Tightening Of Connections In Jbs, And Earth Testing.	H.P. Boiler Air Blower Motor 380v, 22A, 11kw			1		
35	90-X-902C	LV (380V) MOTORS Cleaning, Greasing & Replacement Of Bearings, Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.	Boiler Air Blower Motor 400V,271A,160KW,		L.P.3 Boiler	1		
36	L.P.3-A	LT (380V) MOTORS Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required), Meggering Of Windings, Inspection,	L.P.3 B. Feed Water P. Motor 400V, 92.9A, 55KW		L.P.3 Boiler	1		
37	L.P.3-B	Tightening Of Connections In Jbs, And Earth Testing.				1		
POWER	GENERATION (TU	RBINE) AREA MOTORS			Location			
38	2A	LT (380V) MOTORS	ABLOC Fan Motor 380v, 25.8A, 9.5 Kw		European Gas	1		
39	3A	Cleaning, Greasing & Replacement Of			Turbines	1		
40	4A	Bearings and Paint Job (If Required),				1		
41	2A	Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And	Enclosure Vent Fan Motor 380v, 55A, 30kw	1		1		
42	3A	Earth Testing.	, , ,			1		
43	4A					1		

Act #	Tag #.	Job Description	Specifications		Tools Required	Remarks	Qty	Unit Rate	Total Cost
44	2A		Gen: CACA Fan Motor 380v. 8	3.7A, 4kw			1		
45	2B						1		
46	3A						1		
47	3B						1		
48	4A						1		
49	4B						1		
50	2A		VGV Motor 380v, 3.6A, 1	5kw			1		
51	3A						1		
52	4A						1		
NCINER	ATOR AREA MOTO	DRS	•			Location			
53 54	90-X-904A 90-X-904B	LV (380V) MOTORS Cleaning, Greasing & Replacement Of Bearings and Paint job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.	Incinerator F.D Fan Motor, 22A, 15kw	380v,		Incinerator	1		
AMINE S	STORAGE TANK AR					Location			
55	90-P-905A	LV (380V) MOTORS Cleaning, Greasing & Replacement Of Bearings,Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections In Jbs, And Earth Testing.	Amine Sump Motor 4kw	380v, 6A,		Amine Storage Tank Area	1		
RAWWA	ATER PUMP AREA	MOTORS	•			Location			
56	90-P-911A	LV (380V) MOTORS Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required),	Raw Water P. Motor 138A, 100hp	380v,		Pond Water Area	1		
57	90-P-911B	<ul> <li>Bearings and Paint Job (If Required),</li> <li>Meggering Of Windings, Inspection,</li> <li>Tightening Of Connections In Jbs, And</li> </ul>					1		
58	90-P-911C	Earth Testing.					1		
OMPRE	SSOR AREA MOTO		1			Location			

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
59	X-200A	LV (380V) MOTORS	Inst. Air Comp. Main Motor (Caps), 380v,	-	Compressor Area	1		
60	X-200B	Cleaning, Greasing & Replacement Of	67A, 50HP			1		
61	X-200A	<ul> <li>Bearings, Paint Job (If Required),</li> <li>Meggering Of Windings, Inspection,</li> </ul>	Inst. Air Comp. Condenser Fan Motor (Caps),			1		
62	X-200B	Tightening Of Connections In Jbs, And	380v, 22A, 15HP			1		
63	X-200C	Earth Testing.	Quincy Inst. Air Comp. Motor, 380v, 67A,			1		
64	X-200D		50hp			1		
65	X-201A(181)	7	Inert Gas Comp. Motor, 380v, 44A, 30hp			1		
66	X-201B(176)					1		
IRE W	ATER STORAGE TAI	NK AREA MOTORS			Location			
67	160-P-101A	LV (380V) MOTORS	Fire Water P. Motor (Jockey) ,		Fire Water	1		
68	160-P-101B	<ul> <li>Cleaning, Greasing &amp; Replacement Of Bearings (If Required), Paint Job (If Required), Meggering Of Windings, Inspection, Tightening Of Connections</li> </ul>	380v, 21.2A, 15hp		Storage Tank	1		
69	10-P-200A	In JBs, & Earth Testing LV (380V) MOTORS Cleaning, Greasing & Replacement Of	Glycol Circulation P. Motor 25kw, 380v, 52amps		Train-10	1		
70	10-P-200B	Bearings and Paint Job (If Required), Meggering Of Windings, Inspection,				1		
71	20-P-200A	Tightening Of Connections In JBs, And Earth Testing	Glycol Circulation P. Motor, 25KW, 380V, 52Amps		Train-20	1		
72	20-P-200B	Replacement of Bearings if Required	Souv, SzAmps			1		
73	GSP-A		Glycol Sump P. Motor		Dehydration Area	1		
			380v, 6A, 4kw			1		
74	170-P-101A	LV (380V) MOTORS Cleaning, Greasing & Replacement Of Bearings and Paint Job (If Required), Meggering Of Windings, Inspection,	ETP Sump P. Motor 380v, 15kw		ETP Area	1		
75	170-P-101B	Tightening Of Connections In JBs, & Earth Testing				1		

		OGDCL UCH-I GA	AS PROCESSING PLANT -	ATA 2022 (INSTRUN	<b>MENT SCOPE OF WO</b>	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
		H2S Removal	Plant Train – 10		Location			
1	10-PCV- 1280	To record as found calibration data. Site calibration and integrity checks of	Size: 10" CL 150 Fisher Control Valve	Screw Driver Set, Terminal Screw Drivers,	REFLUX DRUM	1		
2	10-TCV- 1112	actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft	Size: 4" CL 150 Fisher Control Valve	Spanner Set mm/Inch, Multimeter, mA Current	STEAM TO INLET GAS	1		
3	10-PCV- 1106	and hard copies of assignments.	Size: 6" CL 600 Fisher Control Valve	Source, HART Communicator, consumables	CONTACTOR OUTLET	1		
4	10-TCV- 1254		Size: 8" CL 150 Fisher Control Valve		BYPASS OF STRIP EX.	1		
5	10-PCV- 1103	]	Size: 12" CL 600 AES(ROBOTARM)	Valve Lifting and shifting equipment, Scrwe Driver Set,	MAIN INLET	1		
6	10-LCV- 1140	]	Size: 1" CL 600 Fisher Control Valve	Terminal Screw Drivers, Spanner Set	CONTACTOR OUTLET	1		
7	10-LCV- 1203		Size: 8" CL 150 Fisher Control Valve	mm/Inch, Multimeter, mA Current Source, HART	FLASH DRUM O/L TO STRP.	1		
8	10-PCV- 1200	-	Size: 4" CL 150 Fisher Control Valve	Communicator, consumables	FLASH DRUM	1		
9	10-LCV- 1276		Size: 2" CL 150 Control Valve Fisher		REFLUX DRUM LEVEL	1		
10	10-FCV- 1133	Dismantling, shifting to W/S, body & trim inspection, lapping of plug/seat	Size: 6" CL 600 Fisher Control Valve		CIR PUMP TO CONTACTOR	1		
11	10-LCV- 1136	(if reqd.), hydro testing, replacement of kits,	Size: 6" CL 600 Fisher Control Valve		FLASH DRUM O-LET TO STR	1		
12	10-LCV- 102	actuator integrity testing and calibration, service of pneumatic	Size: 1" CL 600 Fisher Control Valve		P/W INLET GAS SEPARATOR	1		
13	10-LCV- 104	regulator, I/P converter & positioner. Inspection/testing of SOVs (if required). Loop testing with DCS, Replacement of Poritioner if required	Size: 1" CL 600 Fisher Control Valve		HC INLET GAS SEPARATOR	1		
14	10-LCV- 9314	To record as found calibration data. Site calibration and integrity checks of	Size: 3" CL 150 Fisher Control Valve		STEAM CONDANSATE POT	1		
15	10-FCV- 9315	actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments.	Size: 1- 1/2" CL 150 Fisher Control Valve		STEAM TO STRIPPER	1		

		OGDCL UCH-I GA	AS PROCESSING PLANT	ATA 2022 (INSTRU	MENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
16	10-PCV- 1217	Replacement of Poritioner if required	Size: 2" Regulator, Make: Fisher		Surge Drum	1		
17	10-PCV- 1218		Size: 2" Regulator, Make: Fisher		BLANKETING REGULATOR	1		
18	10-SDV- 101	Greasing, testing of loop & on/off position,	Size: 1" CL 600 EL-O-MATIC	Grease Gun, all necessarytools for the job	INLET GAS SEPT	1		
19	10-SDV- 102	verification of position switches, service of all local pneumatic regulators, loop testing, testing/overhauling of SOVs	Size: 1" CL 600 EL-O-MATIC		INLET GAS SEPT	1		
20	10-XSV- 1101	Greasing, testing of loop & on/off position, verification of position	SIZE:12" CL 600 Rotork	Grease Gun, all necessarytools for the job	TREATED GAS OUTLET	1		
21	10-XSV- 1102	switches, service of all local pneumatic regulators, loop testing,	SIZE:12" CL 600 Rotork		FEED GAS INLET	1		
22	10-XSV- 1144	testing/overhauling of SOVs.	SIZE:10" CL 600 Rotork		AMINE CONTACTOR O/L	1		
23	10-PT- 1103	Onsite pressure calibration, leak test of connectors, checking of isolating valves,	Pressure Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers,	MAIN INLET	1		
24	10-PT- 1106	loop verification.		Spanner Set mm/Inch, Multimeter, mA Current	FLARE INLET	1		
25	10-FT- 1133	Dismantling, shifting to W/S, Record as fond	Flow Transmitter Rosemount	Source, Resistance box, Pressure Calibrators Low	CIR PUMP TO CONT	1		
26	10-FT- 1269	calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.		Pressure and High Pressure Ranges.HART Communicator, consumables.	REF PMP TO STRPP	1		
27	10-FT- 1107	Onsite calibration, leak test of connectors, checking of isolating valves, loop verification.	Flow Transmitter Rosemount		MAIN GAS INLET	1		
28	10-FT- 9311	Dismantling, shifting to W/S, Record as fond	Flow Transmitter Rosemount		STEAM TO REBOILER	1		
29	10-FT- 9315	calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.			STEAM TO STRIPPER	1		
30	10-DPT- 1151	Onsite calibration, leak test of connectors, checking of isolating valves,	DP Transmitter Rosemount	]	ACROSS CONTACTOR	1		
31	10-DPT- 1292	loop verification. Dismanteling and overhauling if required			ACROSS STRIPPER	1		

	Tea #		S PROCESSING PLANT	•		· · · ·	Linit Data	Total Cast
t#	Tag #. 10-LT-102	Job Description	Specifications Level Transmitter Masoneilan	Tools Required	Remarks	Qty	Unit Rate	Total Cost
2 1	10-L1-102	Level troll internal cleaning, Sensor inspection and setting, field signal	Level Transmitter Masonellan	Spanners Set (In/mm) Screw Drivers Set Hex Key set.	INLET SEPERATOR P/W	1		
3 1	10-LT-104	electric connection checking, onsite		Multi-meter	INLET SEPERATOR H/C	1		
-		calibration, verification and loop testing.		Pipe Wrench 18", 12" <sup>2</sup> .				
	10-LT-			Transparent nylon tube of 1"	OVERHEAD SCRUBBER	1		
	1140			dia, 10 meter length.				
	10-LT-				FLASH DRUM	1		
	1203 10-LT-				SURG DRUM	1		
	10-11-					1		
	1215 10-LT-				REFLUX DRUM	1		
	1276							
8 1	10-LT-				STEAM CONDENSATE POT	1		
ç	9314							
	10-LT-	Dismantling, shifting to W/S, Record as	Level Transmitter Rosemount	General Tool Kit. Pressure	CONTACTOR	1		
1	1136	fond calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating		Calibrators.				
0 1	10-LT-			HART Communicator, consumables.	STRIPPER	1		
1	1250			consumables.				
	10 <del></del>	valves, loop verification.	575					
	10-TT- 1139	Integrity testing of sensor, onsite calibration of transmitters, checking of	RTDs	Spanners Set(In/mm) Screw Drivers Set Multi-meter	CONT.FLASH DRUM	1		
	1159 10-TT-	electric signals and verification of		Temperature Bath (500DegF)	STRIPPER TO XHE	1		
	1253	complete loop.			STRIFFERTOXILE	1		
	10-TT-				XHE TO STRIPPER	1		
1	1254							
4 1	10-TT-				STRIPPER TOP	1		
	1264							
5 C	DPI-10	Dismantling, shifting to W/S, Record as	Transmitter Rosemount	Screw Driver Set,	H2S Train 10 (Coaleser	1		
		fond calibration data, Sensor and		Terminal Screw Drivers,	Filters Train 10/)			
		cleaning, Calibration, re-installation, leak test of connectors, checking of isolating		Spanner Set mm/Inch, Multimeter, mA Current				
		valves, loop verification.		Source, Resistance box,				
		valves, loop vernication.		Pressure Calibrators Low				
				Pressure and High Pressure				
				Ranges.HART				
				Communicator,				
				consumables.				
				consumables.				

		OGDCL UCH-I GA	AS PROCESSING PLANT	ATA 2022 (INSTRUN	<b>MENT SCOPE OF W</b>	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
H2S R	emoval Plant	Train – 20	•	·	Location			
46	20-PCV- 2280	To record as found calibration data. Site calibration and integrity checks of	Size: 10" CL 150 Fisher Control Valve	Screw Driver Set, Terminal Screw Drivers,	REFLUX DRUM	1		
47	20-TCV- 2112	actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft	Size: 4" CL 150 Fisher Control Valve	Spanner Set mm/Inch, Multimeter, mA Current	STEAM TO INLET GAS	1		
48	20-TCV- 2254	and hard copies of assignments.	Size: 6" CL 600 Fisher Control Valve	Source, HART Communicator, consumables	BYPASS OF STRIP EX.	1		
49	20-PCV- 2106	-	Size: 8" CL 150 Fisher Control Valve	-	CONTACTOR OUTLET	1		
50	20-PCV- 2103		Size: 12" CL 600 AES(ROBOTARM)	Valve Lifting and shifting equipment, Scrwe Driver Set,	MAIN INLET	1		
51	20-LCV- 2140	]	Size: 1" CL 600 Fisher Control Valve	Terminal Screw Drivers, Spanner Set	CONTACTOR OUTLET	1		
52	20-LCV- 2203		Size: 8" CL 150 Fisher Control Valve	mm/Inch, Multimeter, mA Current Source, HART	FLASH DRUM O/L TO STRP.	1		
53	20-PCV- 2200		Size: 4" CL 150 Fisher Control Valve	Communicator, consumables	FLASH DRUM	1		
54	20-LCV- 2276		Size: 2" CL 150 Control Valve Fisher		REFLUX DRUM LEVEL	1		
55	20-FCV- 2133	Dismantling, shifting to W/S, body & trim inspection, lapping of plug/seat (if reqd.),	Size: 6" CL 600 Fisher Control Valve		CIR PUMP TO CONTACTOR	1		
56	20-LCV- 2136	hydro testing, replacement of kits, actuator integrity testing and	Size: 6" CL 600 Fisher Control Valve		FLASH DRUM O-LET TO STR	1		
57	20-LCV-102	calibration, service of pneumatic	Size: 1" CL 600 Fisher Control Valve		P/W INLET GAS SEPARATOR	1		
58	20-LCV-104	alibration, service of pneumatic egulator, I/P converter & positioner, Inspection/testing of	Size: 1" CL 600 Fisher Control Valve		HC INLET GAS SEPARATOR	1		
59	20-LCV- 9514	To record as found calibration data. Site calibration and integrity checks of	Size: 3" CL 150 Fisher Control Valve		STEAM CONDANSATE POT			
60	20-FCV- 9515	actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft	Size: 1- 1/2" CL 150 Fisher Control Valve	Valve Lifting and shifting equipment, Scrwe Driver	STEAM TO STRIPPER			
61	20-PCV- 2217	and hard conies of assignments	Size: 2" Regulator, Make: Fisher	Set, Terminal Screw Drivers, Spanner Set				

		OGDCL UCH-I GA	AS PROCESSING PLANT	ATA 2022 (INSTRUN	VENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
62	20-PCV- 2218		Size: 2" Regulator, Make: Fisher	mm/Inch, Multimeter, mA Current Source, HART Communicator, consumables	BLANKETING REGULATOR	1		
63	20-SDV-101	Greasing, testing of loop & on/off position, verification of position	Size: 1" CL 600 EL-O-MATIC	Grease Gun, all necessarytools for the job	INLET GAS SEPT	1		
64	20-SDV-102	switches, service of all local pneumatic regulators, loop testing, testing/overhauling of SOVs.	Size: 1" CL 600 EL-O-MATIC		INLET GAS SEPT	1		
65	20-XSV- 2101	Greasing, testing of loop & on/off position, verification of position	SIZE:12" CL 600 Rotork	Grease Gun, all necessarytools for the job	TREATED GAS OUTLET	1		
66	20-XSV- 2102	switches, service of all local pneumatic regulators, loop testing,	SIZE:12" CL 600 Rotork		FEED GAS INLET	1		
67	20-XSV- 2144	testing/overhauling of SOVs.	SIZE:10" CL 600 Rotork		AMINE CONTACTOR O/L	1		
68	20-PT-2103	Onsite pressure calibration, leak test of connectors, checking of isolating valves,	Pressure Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers, Spanner Set	MAIN INLET	1		
69	20-PT-2106	loop verification. Dismaneling and overhauling if required.		mm/Inch, Multimeter, mA Current Source, Resistance	FLARE INLET	1		
70	20-FT-2133	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and	Flow Transmitter Rosemount	box, Pressure Calibrators Low Pressure and High	CIR PUMP TO CONT	1		
71	20-FT-2269	cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.		Pressure Ranges.HART Communicator,consumables.	REF PMP TO STRPP	1		
72	20-FT-2107	Onsite calibration, leak test of connectors, checking of isolating valves, loop verification. Dimantling, Sensor cleaning or replacement if required.	Flow Transmitter Rosemount		MAIN GAS INLET	1		
73	20-FT-9511	Dismantling, shifting to W/S, Record as fond			STEAM TO REBOILER	1		
74	20-FT-9515	calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.			STEAM TO STRIPPER	1		
75	20-DPT-	Onsite calibration, leak test of	Diff Pressure Transmitters		ACROSS CONTACTOR	1		
	2151	connectors, checking of isolating valves,	Rosemount					

		OGDCL UCH-I GA	AS PROCESSING PLANT	- ATA 2022 (INSTRUN	AENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
76	20-DPT- 2292	loop verification.			ACROSS STRIPPER	1		
77	20-LT-102	Level troll internal cleaning, Sensor inspection and setting, field signal	Level Transmitter Masoneilan	Spanners Set (In/mm) Screw Drivers Set Hex Key set.	INLET SEPERATOR P/W	1		
78	20-LT-104	electric connection checking, onsite calibration, loop testing.		Multi-meter Pipe Wrench 18", 12" <sup>2</sup> .	INLET SEPERATOR H/C	1		
79	20-LT-2140			Transparent nylon tube of 1" dia, 10 meter length.	OVERHEAD SCRUBBER	1		
80	20-LT-2203				FLASH DRUM	1		
81	20-LT-2219	-			SURG DRUM	1		
82	20-LT-2276	-			REFLUX DRUM	1		
83	20-LT-9514				STEAM CONDENSATE POT	1		
84	20-LT-2136	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning,	Level Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch,	CONTACTOR	1		
85	20-LT-2250	Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.		Multimeter, mA Current Source, Resistance box, Pressure Calibrators Low	STRIPPER	1		
86	20-LT-9501	Onsite calibration, leak test of connectors, checking of isolating valves, loop verification. Dimantling, Sensor cleaning or replacement if required.		Pressure and High Pressure Ranges.HART Communicator, consumables.		1		
87	20-TT-2139	Integrity testing of sensor, onsite	RTDs	Spanners Set(In/mm) Screw Drivers Set Multi-	CONT.FLASH DRUM	1		
88	20-TT-2253	calibration of transmitters, checking of electric signals and verification of complete loop.		meter, Temperature Bath	STRIPPER TO XHE	1		
89	20-TT-2254			(500DegF)	XHE TO STRIPPER	1		
90	20-TT-2264				STRIPPER TOP	1		

		OGDCL UCH-I GA	S PROCESSING PLANT	- ATA 2022 (INSTRUI	MENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
91	DPI-20	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.	Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, Resistance box, Pressure Calibrators Low Pressure and High Pressure Ranges.HART Communicator, consumables.	H2S Train Train 20 (Coaleser Filters Train 20)	1		
Dehyo	dration Train -				Location			
92	20-TCV-200	Dismantling, shifting to W/S, body & trim inspection, lapping of plug/seat (if reqd.), hydro testing, replacement of kits, actuator integrity testing and	Size: 4" CL 300 Fisher Control Valve		STEAM LINE TO REBOILER	1		
93	20-PCV-111	calibration, service of pneumatic regulator, I/P converter & positioner. Inspection/testing of SOVs (if required). Loop testing with DCS.Replacement of Poritioner if required	Size: 6" CL 600 Fisher Control Valve		SCRUBBER OUT TO FLARE	1		
94	20-PCV-215	To record as found calibration data. Site calibration and integrity checks of	Size: 1" CL 150 Fisher Control Valve		FLASH DRUM TO FLARE	1		
95	20-LCV-108	actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft	Size: 1" CL 600 Fisher Control Valve	_	INTEGRAL SCRUBBER	1		
96	20-LCV-112	and hard copies of assignments. Replacement of Poritioner if required	Size: 1- 1/2" CL 600 Fisher Control Valve		GLYCOL CONTACTOR	1		
97	20-LCV-208		Size: 1- 1/2" CL 150 Fisher Control Valve		FLASH DRUM	1		
98	20-PCV-100		Size: 12" CL 600 Fisher Control Valve		DEHY O/L TO SALE GAS	1		
99	10-FT-100	Onsite calibration, leak test of	Transmitter Rosemount	Screw Driver Set,	DEHY INLET	1		
100	10-FT-101A	connectors, checking of isolating valves, loop verification. Dismantelling, Sensor		Terminal Screw Drivers, Spanner Set mm/Inch,	DEHY OUTLET	1		
101	10-FT-101B	cleaning, replacement if required		Multimeter, mA Current	DEHY OUTLET	1		
102	10-FT-200	1		Source, Resistance box, Pressure Calibrators Low	DEHY REBOILER	1		

		OGDCL UCH-I GA	<b>AS PROCESSING PLANT</b>	- ATA 2022 (INSTRUI	MENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
103	10-FT-201			Pressure and High Pressure	GLYCOL PUM OUTLET	1		
104	10-LT-206	•		Ranges.HART Communicator,	SURGE DRUM	1		
105	10-DPT-107			consumables.	CONTACTOR	1		
106	10-DPT-213	Dismantling, shifting to W/S, Record as fondcalibration data, Sensor and cleaning, Calibration, re-installation, leak			CARTRIDGE FILTER	1		
107	10-DPT-214	test of connectors, checking of isolating valves, loop verification.			CHARCOL FILTER	1		
108	10-PT-201	Onsite calibration, leak test of connectors, checking of isolating valves,	-		REBOILER PRESSURE	1		
109	10-PT-203	loop verification. Dismantelling, Sensor			REBOILER.INLET	1		
110	10-PT-215	cleaning, replacement if required			FLASH DRUM	1		
111	10-PT-100	nsite calibration, leak test of onnectors, checking of isolating valves, op verification. Dismantelling, Sensor eaning, replacement if required	Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch,	SYSTEM PRESSURE	1		
112	10-PT-109	- cleaning, replacement if required		Multimeter, mA Current Source, Resistance box, Pressure Calibrators Low Pressure and High Pressure	SALE GAS	1		
113	10-PT-212			Ranges.HART Communicator, consumables.	GLYCOL PUMP OUTLET	1		
114	10-LT-108	On Site Level troll internal Cleaning, Sensor cleaning and setting, Field signal	Level Troll Masoneilan	Spanners Set (In/mm),Screw Drivers Set,	INTEGRAL SCRUBBER	1		
115	10-LT-112	electric connection checking, Calibration verifications, loop testing.		Hex Key set, Multi- meter, Pipe Wrench 18", 12",	GLYCOL CONTACTOR	1		
116	10-LT-116			Transparent nylon tube of	O/ HEAD SCRUBBER	1		
117	10-LT-208			1"dia, 10 meter length.	FLASH DRUM	1		
118	10- SDV- 103	Greasing, Testing of loop & On/ Off position, Verification of Position	Size: 10" CL 600 LEDEEN ITALIA	Crane, Spanner Set mm/Inch, Screw Driver Set,	MAIN INLET	1		
119	10- SDV- 104	Switches, Testing/Overhauling Of SOVs, service of	Size: 2" CL 600 EL-O-MATIC	General Tools.	CONTACTOR.OUT LET	1		
120	10- SDV- 105	all local Pneumatic regulators.	Size: 10" CL 600 LEDEEN ITALIA		SALE GAS LINE	1		
Dehvo	dration Train -	20		•	Location			

		OGDCL UCH-I GA	S PROCESSING PLANT	- ATA 2022 (INSTRU	MENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
121	20-TCV-200	Dismantling, shifting to W/S, body & trim inspection, lapping of plug/seat (if reqd.), hydro testing, replacement of kits, actuator integrity testing and calibration, service of pneumatic	Size: 4" CL 300 Fisher Control Valve		STEAM LINE TO REBOILER	1		
122	20-PCV-111	regulator, I/P converter & positioner. Inspection/testing of SOVs (if required). Loop testing with DCS.Replacement of Poritioner if required	Size: 6" CL 600 Fisher Control Valve		SCRUBBER OUT TO FLARE	1		
123	20-PCV-215	To record as found calibration data. Site calibration and integrity checks of	Size: 1" CL 150 Fisher Control Valve		FLASH DRUM TO FLARE	1		
124	20-LCV-108	actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments.	Size: 1" CL 600 Fisher Control Valve		INTEGRAL SCRUBBER	1		
125	20-LCV-112	Replacement of Poritioner if required	Size: 1- 1/2" CL 600 Fisher ControlValve		GLYCOL CONTACTOR	1		
126	20-LCV-208		Size: 1- 1/2" CL 150 Fisher Control Valve	_	FLASH DRUM	1		
127	20-PCV-100		Size: 12" CL 600 Fisher Control Valve	_	DEHY O/L TO SALE GAS	1		
128	20-FT-100	Onsite calibration, leak test of connectors, checking of isolating valves,	Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers,	DEHY INLET	1		
129	20-FT-101A	loop verification. Dismantelling, Sensor cleaning, replacement if required		Spanner Set mm/Inch, Multimeter, mA Current	DEHY OUTLET	1		
130	20-FT-101B	cleaning, replacement in required		Source, Resistance box,	DEHY OUTLET	1		
131	20-FT-200			Pressure Calibrators Low Pressure and High Pressure	DEHY REBOILER	1		
132	20-FT-201			Ranges.HART Communicator,	GLYCOL PUM OUTLET	1		
133	20-LT-206			consumables.	SURGE DRUM	1		
134	20-DPT-107				CONTACTOR	1		
135	20-DPT-213	Dismantling, shifting to W/S, Record as			CARTRIDGE FILTER	1		
136	20-DPT-214	fond calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves,			CHARCOL FILTER	1		

		OGDCL UCH-I GA	S PROCESSING PLANT	<u>- ATA 2022 (INSTRUN</u>	VENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
		loop verification.						
137	20-PT-201	Onsite calibration, leak test of	-		REBOILER PRESSURE	1		
420		connectors, checking of isolating valves,				1		
138	20-PT-203	loop verification. Dismantling, Sensor			REBOILER.INLET	1		
139	20-PT-215	cleaning, replacement if required			FLASH DRUM	1		
140	20-PT-100	Onsite calibration, leak test of	Transmitter Rosemount	Same As Job No. 3	SYSTEM PRESSURE	1		
141	20-PT-109	connectors, checking of isolating valves, loop verification. Dismantling, Sensor			SALE GAS	1		
		cleaning, replacement if required						
142	20-PT-212				GLYCOL PUMP OUTLET	1		
143	20-LT-108	On Site Level troll internal Cleaning, Sensor cleaning and setting, Field signal	Level Troll Masoneilan	Spanners Set (In/mm) Screw Drivers Set Hex Key set.	INTEGRAL SCRUBBER	1		
144	20-LT-112	electric connection checking, Calibration		Multi-meter	GLYCOL CONTACTOR	1		
	-	verifications, loop testing.		Pipe Wrench 18", 12" <sup>2</sup> .				
145	20-LT-116			Transparent nylon tube of 1"	O/ HEAD SCRUBBER	1		
146	20-LT-208	-		dia, 10 meter length.	FLASH DRUM	1		
140	20-L1-208					T		
147	20- SDV-103	Greasing, Testing of loop & On/ Off	Size: 10" CL 600 LEDEEN ITALIA	Crane, Spanner Set	MAIN INLET	1		
		position, Verification of Position		mm/Inch, Screw Driver Set,				
148	20- SDV-104	Switches,	Size: 2" CL 600 EL-O-MATIC	General Tools.	CONTACTOR.OUT LET	1		
149	20- SDV-105	Testing/Overhauling Of SOVs, service of	Size: 10" CL 600 LEDEEN ITALIA	_		1		
-		all local Pneumatic regulators.	SIZE: 10 CL 600 LEDEEN ITALIA		SALE GAS LINE	T		
	Iration Train -				Location			
150	30-TCV-200	Dismantling, shifting to W/S, body & trim inspection, lapping of plug/seat (if	Size: 4" CL 300 Fisher Control Valve		STEAM LINE TO REBOILER	1		
		reqd.), hydro testing, replacement of	Valve					
		kits, actuator integrity testing and						
		calibration, service of pneumatic						
151	30-PCV-111	regulator, I/P converter & positioner.	Size: 6" CL 600 Fisher Control		SCRUBBER OUT TO FLARE	1		
		Inspection/testing of SOVs (if required).	Valve					
		Loop testing with DCS.Replacement of						
		Poritioner if required						
152	30-PCV-215	To record as found calibration data. Site	Size: 1" CL 150 Fisher Control		FLASH DRUM TO FLARE	1		
		calibration and integrity checks of	Valve					
153	30-LCV-108	actuator, positioner, I/P converter. Loop	Size: 1" CL 600 Fisher Control		INTEGRAL SCRUBBER	1		
		calibration through DCS. Provide soft	Valve					

		OGDCL UCH-I GA	AS PROCESSING PLANT	- ATA 2022 (INSTRUM	MENT SCOPE OF W	/ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
154	30-LCV-112	and hard copies of assignments. Replacement of Poritioner if required	Size: 1- 1/2" CL 600 Fisher Control Valve		GLYCOL CONTACTOR	1		
155	30-LCV-208		Size: 1- 1/2" CL 150 Fisher Control Valve		FLASH DRUM	1		
156	30-PCV-100		Size: 12" CL 600 Fisher Control Valve		DEHY O/L TO SALE GAS	1		
157	30-FT-100	Onsite calibration, leak test of	Transmitter Rosemount	Screw Driver Set,	DEHY INLET	1		
158	30-FT-101A	connectors, checking of isolating valves, loop verification. Dismantelling, Sensor		Terminal Screw Drivers, Spanner Set mm/Inch,	DEHY OUTLET	1		
159	30-FT-101B	cleaning, replacement if required		Multimeter, mA Current	DEHY OUTLET	1		
160	30-FT-200			Source, Resistance box, Pressure Calibrators Low	DEHY REBOILER	1		
161	30-FT-201			Pressure and High Pressure	GLYCOL PUM OUTLET	1		
162	30-LT-206	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.		Ranges.HART Communicator,	SURGE DRUM	1		
163	30-DPT-107			consumables.	CONTACTOR	1		
164	30-DPT-213				CARTRIDGE FILTER	1		
165	30-DPT-214				CHARCOL FILTER	1		
166	30-PT-201	Onsite calibration, leak test of			REBOILER PRESSURE	1		
167	30-PT-203	connectors, checking of isolating valves, loop verification. Dismantling, Sensor			REBOILER.INLET	1		
168	30-PT-215	cleaning, replacement if required			FLASH DRUM	1		
169	30-PT-100	Onsite calibration, leak test of	Transmitter Rosemount	Same As Job No. 3	SYSTEM PRESSURE	1		
170	30-PT-109	connectors, checking of isolating valves, loop verification. Dismantling, Sensor			SALE GAS	1		
171	30-PT-212	cleaning, replacement if required			GLYCOL PUMP OUTLET	1		
172	30-LT-108	On Site Level troll internal Cleaning,	Level Troll Masoneilan	Spanners Set (In/mm) Screw	INTEGRAL SCRUBBER	1		
173	30-LT-112	Sensor cleaning and setting, Field signal electric connection checking, Calibration		Drivers Set Hex Key set. Multi-meter	GLYCOL CONTACTOR	1		
174	30-LT-116	verifications, loop testing.		Pipe Wrench 18", 12" <sup>2</sup> .	O/ HEAD SCRUBBER	1		

		OGDCL UCH-I GA	S PROCESSING PLANT	ATA 2022 (INSTRUN	IENT SCOPE OF V	VORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
175	30-LT-208			Transparent nylon tube of 1" dia, 10 meter length.	FLASH DRUM	1		
176	30- SDV-103	Greasing, Testing of loop & On/ Off	Size: 10" CL 600 LEDEEN ITALIA	Crane, Spanner Set	MAIN INLET	1		
177	30- SDV-104	position, Verification of Position Switches,	Size: 2" CL 600 EL-O-MATIC	mm/Inch, Screw Driver Set, General Tools.	CONTACTOR.OUT LET	1		
178	30- SDV-105	Testing/Overhauling Of SOVs, service of all local Pneumatic regulators.	Size: 10" CL 600 LEDEEN ITALIA		SALE GAS LINE	1		
Uch-I	DCS	•						
179	DCS	On Site Technical/Engineering Services of ABB Lahore/ Nextreme Techno Solutions Lahore for 05 Day. Scope of Work: General Checks for Health Status. Minor Changes on HMI. Software Backups of Servers and Controller.	Back End: Infi-90 DCS Front End: 800xA	ABB Software tools	DCS			
LP Boi	ilers 1 & 2				Location			
180	FCV-8062 (Both boilers)	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 6" CL 150 Fisher Control Valve	Valve Lifting and shifting equipment, Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, HART Communicator, consumables	FUEL GAS BURNER	2		
181	LCV-8048 (Both boilers)	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 3" CL 300 Fisher Control Valve	All necessarytools	FEED WATER IN LET	2		
182	PCV-8063 (Both boilers)	Dismantling, shifting to W/S, Inspection of Trim and cleaning, reassembling and testing.	Size: 6" Fisher Regulator	Screw Driver Set, Spanner Set mm/Inch, Hex Key Set, Consumables	GAS FUEL TRAIN	2		
183	LGP	Inspection & Calibration of Switch,	Pressure Switches	Spanners Set (In/mm) Screw	SWITCH, LOW GAS	2		

		OGDCL UCH-I GA	S PROCESSING PLANT	- ATA 2022 (INSTRU	MENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
		Verification of Electrical Connections,		Drivers Set, Hex Key Set	PRESSURE			
184	HGP	inspection of loop,		Multi-meter	SWITCH HIGH GAS PRESS.	2		
185	HFP			Pressure Calibrator/Dead	SWITCH HIGH FURNACE	2		
				Weight Tester (300 Psi).	PRESS			
186	AS				SWITCH LOW COMB. Air	2		
					Press.			
187	IAP	Inspection & Calibration of Switch,	Pressure Switches	Spanners Set (In/mm) Screw	SWITCH LOW INST. AIR	2		
		Verification of Electrical Connections,		Drivers Set, Hex Key Set	PRESS.			
188	HSP	inspection of loop		Multi-meter	SWITCH, HIGH STEM	2		
				Pressure Calibrator/Dead	PRESS			
189	EHSP			Weight Tester (300 Psi).	SWITCH, EXCESS high	2		
					steam			
					press			
190	(Both					2		
	boilers)							
191	WLS(Both	Dismantling, shifting to W/S, cleaning of	Float type level switch	Screw Driver Set, Spanner	SWITCH, WATER LEVEL	2		
	boilers)	float and internal body, re-installation,		Set, Hex Key				
		Testing of operation, leak test of connectors, checking ofisolating valves,		Set, Consumables				
192	Low Cutout,		Conductive Probe type Level	Screw Driver Set, Spanner	DRUM LEVEL	2		
	Low Alarm,	loop verification.	Detector	Set, Hex Key Set,		_		
	High alarm		Detector	Consumables				
	(Both			0011001100100				
	boilers)							
193	PCV-9802	The loop test and Calibration, at	Size: 16" CL 150 Fisher Control	General Calibration Tools	LP STEAM HEADER	1		
		location is required only. With I/P	Valve					
		converter & Positioner						
194	LT	Dismantling, shifting to W/S, Record as	Level Transmitter	General Calibration Tools	DRUM LEVEL	2		
		fond calibration data, Sensor and						
		cleaning, Calibration, re-installation, leak						
195	FT	test of connectors, checking of isolating	Flow Transmitter	General Calibration Tools	FUEL GAS LINE	2		
		valves, loop verification.						
196	PT-9802	On Site setting, Calibration, Field	Press Transmitter	General Calibration Tools	LP STEAM HEADER	1		
		signal electric connection, Leak test of						
		connectors. Checking of isolating valves,						
		Loop verification						
LP Boi	ilers 3				Location			
197	LCV-101	Record of as found calibration data, site	Size: 4" CL 300 ARCA REGLER	General Calibration Tools	LEVEL CONTROL VALVE	1		

		OGDCL UCH-I GA	S PROCESSING PLAN	IT - ATA 2022 (INSTRUN	AENT SCOPE OF WO	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
198	FCV-301	calibration, Actuator, Positioner, I/P Converter testing and replacement if	Size: 8" CL 150 PARCOL		GAS FLOW CONTROL VALVE	1		
199	PCV-301	required. Loop Test with HMI at Local and Boiler operator room.	Size: 6" CL 150 PARCOL		GAS PRESSURE CONTROL VALVE	1		
200	PSH-101	Inspection & Calibration of Switch, Verification of Electrical Connections, inspection of loop,	Switches	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Pressure	BOILER DRUM VERY HIGH PRESSURE (PRESSURE SWITCH)	1		
201	LSLL-101			Calibrators Low Pressure and High Pressure Ranges.HART	BOILER DRUM VERY LOW LEVEL (LEVEL SWITCH)	1		
202	LSL-101			Communicator, consumables.	BOILER DRUM LOW LEVEL (LEVEL SWITCH)	1		
203	LSH-101				BOILER DRUM HIGH LEVEL (LEVEL SWITCH)	1		
204	PSL-202	Inspection & Calibration of Switch, Verification of Electrical Connections, inspection of loop,	Switches	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Pressure Calibrators Low Pressure and	INSTRUMENT AIR VERY LOW PRESSURE(PRESSURE SWITCH)	1		
205	PSLL-301			High Pressure Ranges.HART Communicator, consumables.	GAS VERY LOW PRESSURE(PRESSURE SWITCH)	1		
206	PSHH-301				GAS VERY HIGHPRESSURE(PRESSURE SWITCH)	1		
207	PSL-101				PRESSURE SWITCH	1		
208	LT-101	Dismantling, shifting to W/S, Record as fond calibration data, Sensor and	Level Transmitter	Screw Driver Set, Terminal Screw Drivers, Spanner Set	UPPER STEAM DRUM LEVEL TRANSMITTER	1		
209	FT-101	cleaning, Calibration, re-installation, leak test of connectors, checking of isolating valves, loop verification.	Flow Transmitter	<ul> <li>mm/Inch, Pressure</li> <li>Calibrators Low Pressure and</li> <li>High</li> </ul>	FLOW TRANSMITTER	1		
210	FT-102		Flow Transmitter	Pressure Ranges.HART Communicator, consumables.	STEAM FLOW TRANSMITTER	1		
211	PT-101	On Site setting, Calibration, Field signal electric connection, Leak test of connectors. Checking of isolating valves,	Transmitters	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA	UPPER STEAM DRUM PRESSURE TRANSMITTER	1		
212	PT-201				PRESSURE TRANSMIITER	1		

		OGDCL UCH-I GA	S PROCESSING PLANT	- ATA 2022 (INSTRUN	IENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
213	FT-201	Loop verification		Current Source, Resistance box, Pressure Calibrators Low	COMBUSTION AIR FLOW TRANSMITTER	1		
214	AT-201			Pressure and High Pressure	OXYGEN TRANSMITTER	1		
215	PT-301			Ranges.HART Communicator, consumables.	GAS PRESSURE TRANSMITTER	1		
216	PT-302				GAS PRESSURE TRANSMITTER	1		
217	FT-301				GAS FLOW TRANSMITTER	1		
218	TT-301				GAS TEMPERATURE TRANSMITTER	1		
219	SDV-301	Inspection, Functional Testing & Calibration of Switch, Service/overhauling/parts replacement if	Size: 8" CL 150 VALBIA	Scrwe Driver Set, Multimeter, Consumables	MAIN GAS SHUT-OFF VALVE (SDV)	1		
220	SDV-302	required. Verification of Electrical Connections, inspection of loop,	Size: 2" CL 150 ADLER		MAIN GAS VENT VALVE (SDV)	1		
221	SDV-303		Size: 8" CL 150 VALBIA		BURNER GAS SHUT-OFF- VALVE (SDV)	1		
222	XV-304		SOV	_	PILOT GAS VENT VALVE (SOV)	1		
223	XV-305		SOV	-	PILOT GAS VENT VALVE (SOV)	1		
224	XV-306		SOV		PILOT GAS SHUT-OFF VALVE (SOV)	1		
Deaer	rator		•	•	Location			
225	LV-9110	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop	Size: 1-1/2" CL 150 SPIRAX SARCO	Scrwe Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA	SOFT WATER TO DEAERATOR	1		
226	PV-9101	calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 1-1/2" CL 150 SPIRAX SARCO	Current Source, HART Communicator, consumables	SATURATED STEAM I/ LET	1		
227	LT-9110	On Site Level troll internal Cleaning, Sensor cleaning and setting, Field signal electric connection checking, Calibration verifications, loop testing.	Level Troll Magnitroll	General Tools for LT Calibrations.	DEAERATOR LEVEL	1		
228	PT-9101	On Site setting, Calibration, Field signal electric connection, Leak test of	Press Transmitter Rosemount	General Tools for PT Calibrations.	DEAERATOR PRESSURE	1		

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
		connectors. Checking of isolating valves, Loop verification						
229	TT-9101	Inspection of sensor, Hydro test of thermo well. Calibration of Transmitters,. Checking of electric signals and verification of complete loop.	Temp Transmitter Rosemount	General Tools for TT Calibration, Temp Bath 500 Deg F	DEAERATOR	1		
Fuel G	as Skid				Location			
230	PCV-9601	To record as found calibration data. Site calibration and integrity checks of	Size: 3" CL 600 Fisher Control Valve	Screw Driver Set, Terminal Screw Drivers, Spanner Set	RAW GAS TO HP SCRUBBER	1		
231	PCV-9603	actuator, positioner, I/P converter. Loop calibration through DCS. Provide	Size: 4" CL 600 Fisher Control Valve	mm/Inch, Multimeter, mA Current Source, HART	HP. SCRUBBER INLET	1		
232	PCV-9615	soft and hard copies of assignments. Replacement of Poritioner if required	Size: 4" CL 300 Fisher Control Valve	Communicator, consumables	LP. SCRUBBER INLET	1		
233	PT-9601	Sensor cleaning and setting, Calibration, Field signal electric connection checking,	Press. Transmitter Rosemount	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA	RAW GAS TO HPSCRUBBER	1		
234	PT-9603	<ul> <li>leak test of connectors. Checking of isolating valves, Loop verification</li> </ul>		Current Source, Resistance HP. SCRUBBER INLET box, Pressure Calibrators Low	HP. SCRUBBER INLET	1		
235	PT-9615			Pressure and High Pressure Ranges.HART Communicator, consumables.	LP. SCRUBBER INLET	1		
236	TE-9613	Inspection of sensor, Calibration of	Temp. Transmitter Rosemount	Temp Bath, General Tools	TO HP BOILER	1		
237	TE-9616	Transmitters, Checking of electric signals and verification of complete loop.			TO LP FUEL	1		
238	FT-9612	On Site setting, Calibration, Field signal electric connection, Leak test of	Flow Transmitter Rosemount	Pressure Calibrator, General Tools	HP. OUTLET TO HP BOILER	1		
239	FT -9617	connectors. Checking of isolating valves, Loop verification			LP. OUTLET TO UTILITIES	1		
240	XSV-9602	Greasing, Testing of loop & On/ Off position, Verification of Position Switches, Testing/Overhauling Of SOVs,	SIZE:8" CL 600 Rotork	General Tools	MAIN INLET TO FUEL GAS SKID	1		
241	90-LCV- 9609	To record as found calibration data. Site calibration and integrity checks of actuator positioner 1/P converter 1000	Size: 1" CL 300 Fisher Dump Valve	General Tools	HP Scrubber	1		
242	90-LCV- 9622	canoration through Des. I tovide soft and	Size: 1" CL 150 Fisher Dump Valve	General Tools	LP Scrubber	1		
HP Bo	iler				Location	I T		

		OGDCL UCH-I GA	S PROCESSING PLANT -	ATA 2022 (INSTRUM	<b>MENT SCOPE OF W</b>	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
243	PSL- N/A	Inspection of sensor, tubing/ electric	Pressure Switch	Pressure Calibrator, General	FUEL GAS LINE	1		
244	PSH- N/A	connections. Calibration of switch,		Tools	FUEL GAS LINE	1		
245	PSL-1045	Inspection of loop			COOLING AIR	1		
246	PSHH- N/A				STEAM PRESS	1		
247	PCV Control Valve Valtek	On site calibration of positioner / Convertor and valve Calibration, Loop Calibration/ Test	Size: 3" CL 150 Valtek Valve	General Tools	FUEL GAS LINE (VALTEK)	1		
248	FT-911	Sensor cleaning, inspection of electric signal and connections. Verification of operating parameters and calibration,	Transmitters	General calibrtion Equipment/Tools	STEAM FLOW	1		
249	LT-910	loop test. Replacement of damaged and choked tubes. Leak test of joints and connectors.			DRUM LEVEL	1		
250	PT-910	On Site Calibration, Checking of isolating valves, Loop verification	Transmitters	General calibrtion Equipment/Tools	STEAM PRESSURE	1		
251	LSLL	Inspection & Cleaning of Float, Verification of Security.	Level Switch	General Tools	DRUM LEVEL	1		
252	LCV (Feed Water)	Onsite Calibration	Size: 1-1/2" CL 300 Melso Control Valve			1		
Incine	rator		•		Location			
253	PDSLL-9951	INSPECTION, CALIBRATION & MAINTENAINCE JOB (If Reqd)	PDSLL-9951	General calibrtion Equipment/Tools	AIR DAMPERS	1		
254	PDSLL- 9950		PDSLL- 9950			1		
255	TCV- 9917	INSPECTION, CALIBRATION & MAINTENAINCE JOB (If Reqd) Body Hydro test in Workshop	SIZE: 4" CL 150 WORCESTER	General calibrtion Equipment/Tools	GAS FUEL LINE	1		
256	TT- 9917	INSPECTION, CALIBRATION & MAINTENAINCE (If Reqd)		General Tools	CONTROL CABINET	1		
257	XSV- 9933	Dismantling, Shifting To W/S, Body & Trim inspection, Lapping of Plug/Seat (If	SIZE: 1-1/2" CL 150 MAXON	Grease Gun, General Tools.	FLASHGASTO INCINERATOR	1		

		OGDCL UCH-I GA	S PROCESSING PLANT	<sup>-</sup> - ATA 2022 (INSTRUN	<b>IENT SCOPE OF W</b>	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
258	XSV- 9935	Reqd.) Replacement of kits, Actuator integrity, Hydro test, Calibration, Shifting to location, Re- Installation, loop test, service of all local Pneumatic regulators, I/P Converters & Positioner. Painting Body as actual color arranged by Contractor.	SIZE: 1-1/2'' CL 150 MAXON		FLASHGASTO INCINERATOR	1		
259	Actuators & Positioner	Inspection / Testing / Position Verification Any Maintenance Job If Required	Actuators & Positioner	General Tools	DAMPERS	1		
260	PSLL-9912	Inspection & Calibration Of Switch, Verification of Electrical Connections,	PSLL-9912	General calibrtion Equipment/Tools	FUEL GAS TO INCINERATOR	1		
261	PSHH-9918	inspection of loop,	PSHH-9918		FUEL GAS TO INCINERATOR	1		
Coolin	ng Tower				Location			
262	FCV- 9803	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 4" CL 150 Fisher Control Valve	Scrwe Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, HART Communicator, consumables	COOLING TOWER BLOW DOWN	1		
263	LT-9801	Onsite calibration, leak test of connectors, checking of isolating valves, loop verification.	Level Transmitter Masoneilan	Spanners Set (In/mm) Screw Drivers Set Hex Key set. Multi-meter Pipe Wrench 18", 12" <sup>2</sup> . Transparent nylon tube of 1" dia, 10 meter length.	COOLING WATER MAKE- UP (BASIN)	1		
264	LCV-9801	To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through DCS. Provide soft and hard copies of assignments. Replacement of Poritioner if required	Size: 6" CL 150 Fisher Control Valve	Scrwe Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Multimeter, mA Current Source, HART Communicator, consumables	COOLING WATER MAKE- UP	1		
265	FT- 9803	Sensor cleaning and setting, Field signal electric connection checking,	Flow Transmitter Rosemount	General calibrtion Equipment/Tools	COOLING TOWER BLOW DOWN	1		

		OGDCL UCH-I GA	S PROCESSING PLANT	- ATA 2022 (INSTRU	MENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
266	FT-9805	Calibration verifications, loop testing. Checking of isolating valves			COOLING WATER MAKE- UP	1		
267	FT-9809				COOLING TOWER SUPPLY	1		
268	PT-9813	On Site Level troll internal Cleaning, Sensor cleaning and setting, Field signal electric connection checking, Calibration verifications, loop testing. Checking of isolating valves	Press. Transmitter Rosemount	General calibrtion Equipment/Tools	COOLING TOWER SUPPLY	1		
Wate	r Treatment Pl	ant			Location			
269	KV-9001-A	Dismantling, Shifting to W/S	Size: 6" Butterfly Valves	Screw Driver Set, Terminal	PRESS.FILTERS A	1		
270	KV-9002-A	Inspection and cleaning of respective SOVs, Body, Disc and Seal		Screw Drivers, Spanner Set mm/Inch, Hex Key Set	PRESS.FILTERS A	1		
271	KV-9003-A	Inspection, Checking the integrity of		miny men, nex key set	PRESS.FILTERS A	1		
272	KV-9004-A	actuator, Cleaning/overhauling of Manual			PRESS.FILTERS A	1		
273	KV-9005-A	Override, Shifting to location, Re- Installation, On/Off Testing			PRESS.FILTERS A	1		
274	KV-9006-A				PRESS.FILTERS A	1		
275	KV-9009-A				PRESS.FILTERS A	1		
276	KV-9027-A				PRESS.FILTERS A	1		
277	KV-9001-B	Dismantling, Shifting to W/S Inspection and cleaning of respective	Size: 6" Butterfly Valves	Screw Driver Set, Terminal Screw Drivers, Spanner Set	PRESS.FILTERS B	1		
278	KV-9002-B	SOVs, Body, Disc and Seal Inspection, Checking the integrity of		mm/Inch, Hex Key Set	PRESS.FILTERS B	1		
279	KV-9003-B	actuator, Cleaning/overhauling of Manual			PRESS.FILTERS B	1		
280	KV-9004-B	Override, Shifting to location, Re- Installation, On/Off Testing			PRESS.FILTERS B	1		
281	KV-9005-B	Installation, On On Testing			PRESS.FILTERS B	1		
282	KV-9028-A	Dismantling, Shifting to W/S	Size: 6" Butterfly Valves	Screw Driver Set, Terminal	SIDE STREAM FILTERS A	1		
283	KV-9029-A	Inspection and cleaning of respective SOVs, Body, Disc and Seal		Screw Drivers, Spanner Set mm/Inch, Hex Key Set	SIDE STREAM FILTERS A	1		
284	KV-9030-A	Inspection, Checking the integrity of actuator, Cleaning/overhauling of Manual			SIDE STREAM FILTERS A	1		
285	KV-9033-A	Override, Shifting to location, Re-			SIDE STREAM FILTERS A	1		
286	KV-9034-A	Installation, On/Off Testing			SIDE STREAM FILTERS A	1		

		OGDCL UCH-I GA	S PROCESSING PLANT	- ATA 2022 (INSTRUN	IENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
287	KV-9028-B	Dismantling, Shifting to W/S Inspection and cleaning of respective	Size: 6" Butterfly Valves	Screw Driver Set, Terminal Screw Drivers, Spanner Set	SIDE STREAM FILTERS B	1		
288	KV-9029-B	SOVs, Body, Disc and Seal Inspection, Checking the integrity of		mm/Inch, Hex Key Set	SIDE STREAM FILTERS B	1		
289	KV-9030-B	actuator, Cleaning/overhauling of Manual Override, Shifting to location, Re-			SIDE STREAM FILTERS B	1		
290	KV-9031-B	Installation, On/Off Testing			SIDE STREAM FILTERS B	1		
291	KV-9028-C	Dismantling, Shifting to W/S Inspection and cleaning of respective	Size: 6" Butterfly Valves	Screw Driver Set, Terminal Screw Drivers, Spanner Set	SIDE STREAM FILTERS C.	1		
292	KV-9029-C	SOVs, Body, Disc and Seal Inspection, Checking the integrity of		mm/Inch, Hex Key Set		1		
293	KV-9030-C	actuator, Cleaning/overhauling of Manual Override, Shifting to location, Re-				1		
294	KV-9031-C	Installation, On/Off Testing				1		
EGTs 2	1,2,3 & 4 Fue	el GAS Skid/Turbine Skid/TCM		I	Location			
295	PCV-1	Iel GAS Skid/Turbine Skid/TCM           Calibration, loop test, service of all local           Pneumatic regulators. The calibrations           Tools of the vender must be certified by           some recognizedinstitution.	Size: 1-1/2" CL 600 Valtek Valve	Pressure Calibrator, General Tools	EGT's Fuel gas skid	1		
296	PCV-1A		Size: 1-1/2" CL 600 Valtek Valve			1		
297	PSV-1	Removing from location, testing in workshop/bench and record "as found set" value (Psig/Bar), disassembling for	Size 4"x6"	Crane, Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Hex	EGT's Fuel gas skid	1		
298	PSV-2	Lapping trim and overhauling completely(if required), assembling, setting (provided by OGDCL) cold set	Size 1"x1"	Key Set, Pressure Source 2000PSI, Other calibration equipment.	EGT's Fuel gas skid	1		
299	PSV-3	points and reinstallation	Size I"x1"	PSV Test Bench. Consumables	EGT's Fuel gas skid	1		
300	NYA	Dismantling, Shifting To W/S, Body & Trim inspection, Lapping of Plug/Seat (If Reqd.) Replacement of kits, Actuator integrity, Hydro test, Calibration, Shifting to location, Re- Installation, loop test, service of all local Pneumatic regulators.	Dump Valve 1'' 600CL	General Tools	Horizontal K/O Vessel at EGT's Area.	4		

		OGDCL UCH-I GA	S PROCESSING PLANT	- ATA 2022 (INSTRUM	MENT SCOPE OF W	ORK)		
Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
301	Off Skid Valves	Dismantling, Shifting to W/S Inspection and cleaning of respective SOVs, Body, Disc and Seal Inspection, Checking the integrity of actuator, Cleaning/overhauling of Manual Override, Shifting to location, Re-Installation, On/Off Testing	1"	Screw Driver Set, Terminal Screw Drivers, Spanner Set mm/Inch, Hex Key Set	EGTS Off Skids valves	8		
302	04 Turbines	Inspection/ cleaning of all SOV's and Diaphragm Valves.	Pneumatic purging Cleaning by pulse controller	General Tools	Enclosure and Ventilation Purging and ventilation system.	76		
303	04 Turbines	Dismantling of valves from location, shifting to workshop, inspection and maintenance, changing of repair kit, reinstallation and verification of operation, on-off position		General Tools	BLOW OFF VALVE (01 No. Each Unit)	4		
304	04 Turbines	Pressure Switches On Site Calibration Check	Hand Pump Pneumatic Pressure Calibrator, General Tools	General Tools	Pressure Switches (05 Nos. Each Unit)	20		
305	04 turbines	Pressure Tx On Site Calibration Check	Hand Pump Pneumatic Pressure Calibration General Tools.	General Tools	Transmitters (06 Nos. Each Unit)	24		
PRES	SURE SAFETY	VALVES: -						
Boiler	/Utilities Area				Location			
306	LP1-PSV- 8001	Removing from location, testing in workshop/bench and record "as found	Size: 4" x 6"	Crane, Screw Driver Set, Terminal Screw Drivers,	LP1 BOILER	1		
307	LP1-PSV- 8002	set" value (Psig/Bar), disassembling for Lapping trim and	Size: 6" x 6"	Spanner Set mm/Inch, Hex Key Set, Pressure Source	LP1- BOILER	1		
308	LP2-PSV- 8001	overhauling completely(if required), assembling, setting (provided by OGDCL)	Size: 4" x 6"	2000PSI, Other calibration equipment.	LP2- BOILER	1		
309	LP2-PSV- 8002	cold set points and reinstallation.	Size: 6" x 6"	PSV Test Bench. Consumables.	LP2- BOILER	1		
310	HP1-PSV- 915		Size: 1" x 1", Make: ESER		HP1- BOILER	1		
311	HP1-PSV- 916		Size: 1" x 1", Make: ESER	]	HP1- BOILER	1		

Act #	Tag #.	Job Description	Specifications	Tools Required	Remarks	Qty	Unit Rate	Total Cost
312	HP1-PSV- 917		Size: 1" x 1", Make: ESER		HP1- BOILER	1		
313	HP2-PSV-A		Size: 2" x 3", Make: FARRIS		HP2-A	1		
314	HP2-PSV-B		Size: 2" x 3", Make: FARRIS		HP2-B	1		
315	HP2-PSV-C		Size: 2" x 3", Make: FARRIS		HP2-C	1		
316	DE- AREATOR		Size: 3" x 4", Make: TELEDYNE		DE-AREATOR	1		
317	LP3-PSV-A		Size: 6" x 8", Make: CROSBY		LP3 Boiler	1		
318	LP3-PSV-B		Size: 6" x 8", Make: CROSBY		LP3 Boiler	1		
319	LP3-PSV-C		Size: 6" x 8", Make: CROSBY		LP3 Boiler	1		
320	PSV-9606		Size: 6" x 8", Make: TELEDYNE		Fuel Gas Skid	1		
321	PSV-9619		Size: 6" x 8", Make: TELEDYNE		Fuel Gas Skid	1		
322	10-PSV-201		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharge Train-10	1		
323	10-PSV-202		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharge Train-10	1		
324	20-PSV-201		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharge Train-20	1		
325	20-PSV-202		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharge Train-20	1		
326	30-PSV-201		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharge Train-30	1		
327	30-PSV-202		Size: 2"x 3/4", Make: HYDROSEAL		Glycol Pump Discharge Train-30	1		

Sr. #	Instruments Type / Make	Qty	Job Description	Terms/Tools/Eqps. Required	Unit Rate	Total Cost
UPL E	ND (DERA MURAD JAMALI) -PROI	DUCTION	FACILITIES			
1	Epoxy painting of delivery station that includes mainly. 1: 4 Nos vetical vessels of dia 42" ,20 ft height/each 2: 3 Nos meter runs of 14"dia, 12 ft lenghth/each 3: Riser and pig receiving assebly of 26" dia, 50 ft length 4: Inlet/outlet piping of 14" dia of 04 vessels (total 80ft length) & headers of 24" dia.(100 ft length) 5: Plate form around 4 no vertical vessels (5ftX 100ft)	01 Nos (Lupm sum)	2 coat epoxy painting of delivery station	<ul> <li>Contractor will arrange all certified machinery/tools like crane, scafolding,compressor and lifting gears.</li> <li>Contractor will arrange proper tool for roughing of surfaces</li> <li>Contractor will arrange its transport for mob/demob of its manpower to/from UPL</li> <li>Contractor will pay messing charges to m/S UPL as per UPL rate. No ousource messing is allowed.</li> <li>Contractor will arrange its boarding/lodging/pick &amp; drop in nearby city if it is not provided by m/S UPL.</li> <li>Contractor will follow all covid-19 protocols</li> </ul>		
2	42" dia vertical filter vessels-B ( 27 filter elements )	01 Nos	Replacement of filters from 01 Nos 42'' dia vertical filter vessels ( 27 filter elements/vessel)	<ul> <li>including qurantine on its own cost as required by m/s UPL.</li> <li>Contractor will provide police verification of its manpower</li> </ul>		
Activi	ties at UGF, Gathering Area					
1	Prefabricated SS spool of 1" dia	1	Replacement of boot line at slug catcher.LCV-2025			
2	Ball Balve, 12'',#600 ,RF	2	Deblinding and installation of valve at pig launcher/reciever			
3	Ball Balve, 12",#600 ,RF	1	Replacemnt of valve of inter connecting line well#21 at header			
4	Ball Balve, 8",#600 ,RF	6	Deblinding and installation of valve at pig launcher/reciever			
5	Ball Balve, 6'',#600 ,RF	1	Replacement of isolation valve at LCV-2020			
6	Ball Balve, 6'',#600 ,RF	1	Replacement of isolation valve at LCV-2021			
7	Wafer Type NRVs of size 26" of SGL	1	Dismantling, repairing, leakage testing & box up			

			OG	DCL T&I- SECTION (PE&FD), PRODUC	CTION DEPARTMENT ATA-2	2022 - UCH-I			
Sr. No.	Location	Tag No.	Instruments Type /Make	Job Description	Tools/Eqps. Required	Remarks	Qty	Unit Rate	Total Cost
1.	<u>Gathering</u>	g Area:-							
1		PRV_2001A PRV_2001B	16" Emergency Valve Morin/Emerson	<ul> <li>Onsite Testing &amp; Rectification of PRVS</li> <li>Opening / Closing indications(Limit</li> <li>Switch) through CCR HMI Display</li> <li>Greasing &amp; Cleaning of PRVs</li> </ul>	All tools, consumables, calibration equipments at contractor's end 1-Multi-meter 2-Engineering Station 3-Hart Communicator 4-Spanners Set (In/mm) 5-Screw Drivers Set	<ol> <li>OGDCL will deduct from actual cost if any job is not possible to be carried out.</li> <li>OGDCL will deduct in case of non-availability of tools and calibration equipments.</li> <li>mA Source and pressure</li> </ol>	2		
		ESDV_2001A ESDV_2001B		Onsite Testing & Rectification of PRVS     Opening / Closing indications(Limit     Switch) through CCR HMI Display     Greasing & Cleaning of ESDVs			2		
	Western & Centr	FCV_2001A FCV_2001B	Control Valves 16" / Fisher	<ul> <li>Onsite Testing, Calibration, integrity checks of actuator, positioner, I/P converter and service verified by CCR HMI</li> <li>Rectify Feedback transmitting signals Open/Close of FCV &amp; etc</li> <li>Rectify faulty indications of all instruments / valves etc (if required)</li> </ul>	6-Resistance Box. 7-Pressure Calibrator 8-mA Source 9-Heavy Machinery (if reqd.).	calibrator at Contractor end 4. All the procedure as per manual will be provided by OGDCL that must be followed. 5. Site test with SCADA left as per process requirement	2		
		MVT_2001A MVT_2001B	Rosemount	Onsite Testing, Calibration, integrity of service verified by SCADA CCR HMI			2		
2	Eastern Lobe	FCV_2001C FCV_2001D FCV_2001F FCV_2001E	Control Valves 8" / Fisher	<ul> <li>Onsite Testing, Calibration, integrity checks of actuator, positioner, I/P converter and service verified by CCR HMI</li> <li>Rectify Feedback transmitting signals Open/ Close of FCV &amp; etc</li> <li>Rectify faulty indications of all instruments / valves etc (if required)</li> </ul>			4		

			OGI	DCL T&I- SECTION (PE&FD), PRODUC	CTION DEPARTMENT ATA-2	2022 - UCH-I			
Sr. No.	Location	Tag No.	Instruments Type /Make	Job Description	Tools/Eqps. Required	Remarks	Qty	Unit Rate	Total Cost
		ESDV_2001C ESDV_2001D ESDV_2001F ESDV_2001E	8" ESDV Valve Morin/Emerson	<ul> <li>Dismantling of Actuator , shifting to W/S, replacement of Gaskit &amp; O Rings and maintenance etc.</li> <li>Actuator integrity testing and calibration, • Onsite Testing &amp; Rectification of PRVS Opening / Closing indications(Limit Switch) through CCR HMI Display</li> <li>Greasing &amp; Cleaning of ESDVs</li> </ul>			4		
		PRV_2001C PRV_2001D PRV_2001F PRV_2001E	8" ESDV Valve Morin/Emerson	<ul> <li>Onsite Testing &amp; Rectification of PRVS</li> <li>Opening / Closing indications(Limit</li> <li>Switch) through CCR HMI Display</li> <li>Greasing &amp; Cleaning of PRVs</li> </ul>			4		
		MVT_2001C MVT_2001D MVT_2001E MVT_2001F		Onsite Testing, Calibration, integrity of service verified by SCADA CCR HMI			4		
2	Well Site:-	———							•
1 2		FCV _07 FCV_08	Flow Control Valve , Size 4" / Mokveld	• Onsite Testing, Calibration, integrity checks of actuator, positioner, I/P converter and service verified by CCR	All tools, consumables, calibration equipments at contractor's end	<ol> <li>OGDCL will deduct from actual cost if any job is not possible to be carried out.</li> <li>OGDCL will deduct in case of non-availability of</li> </ol>	4		
3		FCV_09		HMI • Rectify Feedback transmitting signals	1-Multi-meter 2-Engineering assistance				
4	þe	FCV_06B		Open/ Close of FCV & etc • Rectify faulty indications of all instruments / valves etc (if required)	software 3-Hart Communicator 4-Spanners Set (In/mm)	tools and calibration equipments. 3. mA Source and pressure			
5	Eastern Lobe	ESDV _07	TK valve , Emergency	Onsite Testing & Rectification of PRVS     Opening / Closing indications(Limit	5-Screw Drivers Set 6-Resistance Box.	calibrator at Contractor end 4. All the procedure as per	4		
6	East	ESDVV_08	Shutdown Valve	Switch) through CCR HMI Display	7-Pressure Calibrator	manual will be provided by OGDCL that must be			
7	1	ESDV_09	Size 4"	Greasing & Cleaning of ESDVs	8-mA Source 9-Heavy Machinery (if reqd.).	followed. 5. Site			
8	1	ESDV_06B	1			test with SCADA left as per			
9	]	FT_07	MVT / Rosemount	Calibration, servicing and maintenance		process requirement	4		
10		FT_08	3095	will be carried out and verification of					
11		FT_09		reading will be monitored by CCR-HMI					
12		FT_6B							

			OGI	DCL T&I- SECTION (PE&FD), PRODUC	TION DEPARTMENT ATA-202	2 - UCH-I			
Sr. No.	Location	Tag No.	Instruments Type /Make	Job Description	Tools/Eqps. Required	Remarks	Qty	Unit Rate	Total Cost
13		FCV_03	Flow Control Valve , Size 4" /	• Onsite Testing, Calibration, integrity checks of actuator, positioner, I/P			5		
.4		FCV_17	Mokveld	converter and service verified by CCR HMI • Rectify Feedback transmitting signals Open/ Close of FCV & etc					
5		FCV_18							
6		FCV_11		Rectify faulty indications of all     instruments / valves etc (if required)					
.7	e	FCV_14		instruments / valves etc (in required)					
8	Central Lobe	ESDV_03	TK valve ,	<ul> <li>Onsite Testing &amp; Rectification of PRVS</li> </ul>			5		
9	tral	ESDV_17	Emergency	Opening / Closing indications(Limit					
0	Cen	ESDV_18	Shutdown Valve	Switch) through CCR HMI Display					
1		ESDV_11	Size 4"	<ul> <li>Greasing &amp; Cleaning of ESDVs</li> </ul>					
2		ESDV_14							
3		FT_03	MVT / Rosemount	<ul> <li>Calibration, servicing and maintenance</li> </ul>			5		
4		FT_17	3095	will be carried out and verification of					
5		FT_18		reading will be monitored by CCR-HMI					
6		FT_11							
7		FT_14							
8		FCV_12	Flow Control Valve	Onsite Testing, Calibration, integrity			6		
9	e	FCV_13	, Size 4" /	checks of actuator , positioner , I/P					
0	Lot Lot	FCV_15	Mokveld	converter and service verified by CCR					
1	Western Lobe	FCV_16		HMI <ul> <li>Rectify Feedback transmitting signals</li> </ul>					
2	/est	FCV_02		Open/ Close of FCV & etc					
3	5	FCV_10		<ul> <li>Rectify faulty indications of all instruments / valves etc (if required)</li> </ul>					
4	1	ESDV _12	TK valve ,	Onsite Testing & Rectification of PRVS			6		
5	1	ESDV_13	Emergency	Opening / Closing indications(Limit					
6	1	ESDV_15	Shutdown Valve	Switch) through CCR HMI Display					
7	1	 ESDV_16	Size 4"	<ul> <li>Greasing &amp; Cleaning of ESDVs</li> </ul>					
8	1	 ESDV_02	1						
9		 ESDV_10	1						
0		FT _12	MVT / Rosemount	Calibration, servicing and maintenance			6		
1	1 1	FT_13	3095	will be carried out and verification of					

			OG	DCL T&I- SECTION (PE&FD), PRODU	CTION DEPARTMENT ATA-	2022 - UCH-I			
Sr. No.	Location	Tag No.	Instruments Type /Make	Job Description	Tools/Eqps. Required	Remarks	Qty	Unit Rate	Total Cost
42		FT_15		reading will be monitored by CCR-HMI					
43		FT_16							
44		FT_02							
45		FT_10							
	P Separators	(V-100 & V-101):-							
1	LP Separator	LT -3201 LT-3250 25-PSV-3205 25-PSV-3255 PCV-3215 PCV-3271	LT PSV, Size= 4"/ Anderson Greenwood & Co. PCV , Size=2" / Fisher	<ul> <li>V-100 &amp; V-101 (LCVs, PSVs, PCVs) Inspection, calibration and maintenance will be carried out and verification of controlling will be executed by CCR- HMI [operator command].</li> <li>To record as found calibration data. Site calibration and integrity checks of actuator, positioner, I/P converter. Loop calibration through SCADA</li> </ul>	<ul> <li>All tools, calibration equipments at contractor's end Spanners Set (In/mm)</li> <li>Screw Drivers Set</li> <li>Hex Key set.</li> <li>Multi-meter</li> <li>Pipe Wrench set</li> <li>Engineering assistance software</li> <li>Hart Communicator</li> <li>Spanners Set (In/mm)</li> <li>Screw Drivers Set</li> <li>Multi-meter</li> <li>Resistance Box.</li> <li>Pressure Calibrator</li> </ul>	<ol> <li>OGDCL will deduct from actual cost if any job is not possible to be carried out.</li> <li>OGDCL will deduct in case of non-availability of tools and calibration equipments.</li> <li>mA Source and pressure calibrator at Contractor end</li> <li>All the procedure as per manual will be provided by OGDCL that must be followed.</li> <li>Site test with SCADA left as per process requirement</li> </ol>	2		
2	Slug Catcher	:-							
1	Slug Catcher	LT_2025 LT_2020	LT	Rectify following inspection, calibration and maintenance will be carried out and verification of controlling will be executed by CCR- HMI [operator command]. [Boot calibration & Servicing] [calibration and servicing]	<ul> <li>All tools, consumables, calibration equipments at contractor's end Spanners Set (In/mm)</li> <li>Screw Drivers Set</li> <li>Hart Communicator &amp; Etc</li> <li>Spanners Set (In/mm)</li> <li>Screw Drivers Set</li> </ul>	<ol> <li>OGDCL will deduct from actual cost if any job is not possible to be carried out.</li> <li>OGDCL will deduct in case of non-availability of tools and calibration equipments.</li> <li>mA Source and pressure calibrator at Contractor end</li> </ol>	2		

Sr. No.	Location	Tag No.	Instruments Type /Make	Job Description	Tools/Eqps. Required	Remarks	Qty	Unit Rate	Total Cost
					<ul> <li>Multi-meter</li> <li>Resistance Box.</li> <li>Pressure Calibrator</li> </ul>	<ol> <li>All the procedure as per manual will be provided by OGDCL that must be followed.</li> </ol>			
		FT_2002	MVT / Rosemount	Calibration, servicing and maintenance will be carried out and verification of reading will be monitored by CCR-HMI.	<ul> <li>Hart Communicator</li> <li>Spanners Set (In/mm)</li> <li>Screw Drivers Set</li> <li>Multi-meter</li> <li>Resistance Box.</li> <li>Pressure Calibrator</li> <li>Engineering Assistence software</li> </ul>	5. Site test with SCADA left as per process requirement	1		
		25-PSV-2015	PSV , Size = 4" / Anderson Greenwood & Co	Calibration, servicing and maintenance will be carried out and verification of reading will be monitored by CCR-HMI.	<ul> <li>Hart Communicator</li> <li>Spanners Set (In/mm)</li> <li>Screw Drivers Set</li> <li>Multi-meter</li> <li>Resistance Box.</li> <li>Pressure Calibrator</li> </ul>		1		
5	Condensat	e Storage Tanks	(T-101 & T-102)						
1	Condensate Tanks	LT_3405 LT_3305	LT-[T-101 & T- 102]	Rectify error and calibrations of the LT- ( T-101 & T- 102 ) will be carried out and verified by CCR – HMI , Operator command	<ul> <li>Hart Communicator</li> <li>Spanners Set (In/mm)</li> <li>Screw Drivers Set</li> <li>Multi-meter</li> <li>Resistance Box.</li> <li>Pressure Calibrator</li> </ul>	<ul> <li>OGDCL will deduct from actual cost if any job is not possible to be carried out.</li> <li>OGDCL will deduct in case of non-availability of tools and calibration equipments.</li> <li>mA Source and pressure calibrator at Contractor end</li> <li>All the procedure as per manual will be provided by OGDCL that must be followed.</li> </ul>	2		
	Cor	LS_3310 LS_3410	LS- [T-101 & T- 102]	Rectification of error and calibration job will be executed both LS-(T-101 & T-102); will be verified by CCR- HMI, Operator command.		<ul> <li>Site test with SCADA left as per process requirement</li> </ul>	2		

Sr.	Location	Tag No.	Instruments	Job Description	Tools/Eqps. Required	Remarks	Qty	Unit Rate	Total
No.			Type /Make						Cost
6-	Inlet Statio	<u>on</u>							
1	Inlet Station	SDV-2001	SDV/Fluid System Lucca-Italy	Repair / Inspection/ Greasing of inlet station sale line SDV	Grease Gun, Spanner Set (in/mm), Screw driver set, Pipe wrench set, Multimeter	The Valve has passing issue	1		
7-	Inlet Statio	<u>n</u>							
1	UPL1	SDV-2260	SDV/Fluid System Lucca-Italy	Repair / Inspection/ Greasing of inlet station sale line SDV	Grease Gun, Spanner Set (in/mm), Screw driver set, Pipe wrench set, Multimeter	The Valve has stuck issue	1		
		SDV-2260			(in/mm), Screw driver set,	The Valve has stuck issue	1		
1 8- 1					(in/mm), Screw driver set,	The Valve has stuck issue Require experties of IntelliMax and Factory Talk	1		

## NOTE:

- **1.** Contractor will responsible to provide all mandatory equipments for calibration and maintenance of above mentioned instruments.
- 2. Deidcated Double Cabin Vehicle and Crane Mounted Truck with man hoisting cradle must be provided by Contractor to ensure smooth ATA activities on Well Sites i.e. 5-28 Km approx and at UPL i.e 85 Km in distance from Plant.

## **REFERENCES:**

- ASME Sec II Part-A (Ferrous material Specifications)
- ASME Sec II Part-C (Specifications for welding rods, electrodes and filler materials)
- ASME VIII Div-I (Rules for Construction of Pressure Vessels) ASME Sec IX

(Welding and Brazing Qualifications)

- ASME B31.3 (Process Piping)
- ASME Sec V (Non Destructive Examination)
- API-510 (Code for Inspection of pressure vessels repair, alteration and re-rating)
- API-572 (Inspection of Pressure Vessels)
- API-570 (Inspection, Repair, Alteration and re-rating of piping)
- API-598 (Valves Inspection & Testing)
- MSS-SP-61 (Pressure Testing of Steel Valves)
- NACE MR-0175
- OGDCL's Specifications & HSEQ Manual