

TECHNICAL EVALUATION REPORT
TENDER NO. PROC-FE/CB/PROD-3068/2017
FOR BUG BLOWERS

Sr. No.	Bidder Name	Technically Responsive (Yes/No)	Reason for Rejection
1	M/s Baoji Oil Field Machinery Co., Ltd., China C/o M/s Karimi Universal Peshawar	No	i) Quoted motor has 960 rpm against requirement of 1200 rpm. ii) Bidder quoted model having air flow of 27,075 CFM as against the requirement of 37,000 CFM. Material deviation w.r.t to tender specification / clarifications.
2	M/s Bronco Manufacturing LLC., USA . C/o M/s Bronco Middle East., UAE	No	Quoted model has 60Hz frequency as against the requirement of 50 Hz. This is considered as material deviation w.r.t to tender specification / clarifications.
3	M/s Dezhou Yatai Group Co., Ltd., China C/o M/s Route One Engineering, Islamabad	Yes	
4	M/s Woodhouse International FZE, UAE . C/O M/s Petro Allied Solutions, IBA	Yes	
5	M/s Ace Pressureweld Int'l (Pte) Ltd, Singapore . C/o M/s TEK-ORO (Pvt) Ltd., IBA	Yes	
6	M/s Enerquip Limited, UAE C/o M/s Enerquip (Pvt.) Ltd., Islamabad	No	Quoted cable is not armoured as against the OGDCL requirement of armoured cable. This is considered as material deviation w.r.t to tender specification / clarifications.
7	M/s Corrigo Technical Services SDN BHD, Malaysia C/o M/s Mudarian International, Islamabad.	No	i) Bidder quoted 80 Meter Cable as against the requirement of 100 Meter. ii) Bidder quoted model having air flow of 26,485 CFM as against the requirement of 37,000 CFM. Material deviation w.r.t to tender specification / clarifications
8	M/s Indam International inc, USA C/o M/s Acumen International., Islamabad	Yes	
9	M/s AZEN, Singapore . C/o M/s SynerGeze FZC., UAE	No	i) Quoted motor has 960 rpm against requirement of 1200 rpm. ii) Quoted model has air flow of 35,000 CFM as against the requirement of 37,000 CFM. Material deviation w.r.t to tender specification / clarifications
10	M/s Smart Climate IBA, Islamabad	No	i) Quoted motor has 960 rpm as against the requirement of 1200 rpm. ii) Quoted model has air flow of 35,000 CFM as against the requirement of 37,000 CFM. Material deviation w.r.t to tender specification / clarifications
11	M/s Energy Co., Ltd., China C/o M/s Dynamics Engineering., Karachi	No	Quoted impeller size of Bug Blower is 31" as against the requirement of 48". This is considered as material deviation w.r.t to tender specification / clarifications