TECHNICAL EVALUATION REPORT PROC-FC/CB/P&P/DKN-4272/2019

SUPPLY OF ISOLATION VALVES FOR DAKHNI PLANT

S#	Bidder Name	local agent	Technical evaluation status	Reason for Rejection
1	American international industries pte ltd Singapore	AJCL Islamabad	Technically non responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.
2	Arflu indsutrial valves Spain	Engineering equipment.	Technically responsive	NA
3	OVIKO group co ltd China	Rana traders	Technically non responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.
4	ShandongKerui Petroluem equipment co ltd China	Tabani Global	Technically responsive	NA
5	Wuzhou valve co ltd china	Enerquip	Technically non responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.
6	Koflow valve group co ltd china	Capricorn Petroluem	Technically responsive	NA
7	Zhejiang Chenggao valve co Itd China	OTC Lahore	Technically non Responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.
8	Morrells International General Trading Bahrain	Salaria & Shaikh Int Pvt Itd	Technically non Responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.
9	Zhejiang Med Valves Co ltd	Bid rejected due to different	t formate of bid bond.	
10	Energyco Itd China	Dynamics engineering	Technically non Responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.
11	Growin Business & contracting wenzhou co ltd China	continental trading corpoation	Technically non Responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.
12	Kaistong valve co ltd China	Fasin international Lahore	Technically non Responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.
13	China oil & gas engineering technology Ltd China	Ehsan corporation pvt ltd Lahore	Technically non Responsive	Body material of valves (except S#2 & 10) is not as per tender requirement/ clarification No 4.