

TECHNICAL EVALUATION REPORT

RFP NO.: OGDCL-SCM-FB-CB-PROD-213804724-2023

DESCRIPTION OF THE RFP: 8 INCH PIPE LINE

TECHNICAL BID OPENING DATE: November 10, 2023

Sr. No.	Bidder and Local Agent	Remarks	Technically Responsive (YES/NO)
1	M/s China Petroleum Pipeline Material and Equipment Company Limited	*****	YES
2	M/s Jereh Global Development LLC, China	*****	YES
3	M/s Linzhou Fengbao Pipe Industry Co., Ltd, China	*****	YES
4	M/s Marubeni-Itochu Tubulars Asia Pte Ltd., Singapore	*****	YES
5	M/s. INTERTRADE-CANADA, INC, Canada	<ol style="list-style-type: none">1. Document 4985-DS-1801 as Annexure "2" not vetted from manufacturer.2. Document 4985-PA-2006 as Annexure "3" not vetted from manufacturer.3. Document 4985-PA-2008 as Annexure "4" not vetted from coating mill.4. Bidder refused to withdraw its delivery tolerance limit mentioned in bid and to accept OGDCL delivery tolerance limit as per tender documents.5. Bidder didn't provide its supply record.6. Bidder refused to share its Last consecutive three years Audited Financial reports as required by tender documents vide documents submission checklist as Annexure "1" Sr. No.12 and Technical Evaluation Criteria as Annexure-VI Sr. No. 8.7. Bidder didn't declared coating mill for this project and didn't shared coating mill requisite documents.	No

		<p>8. Bidder refused to share both its own and manufacturer's priced purchase order copies for last 5 years as required by tender documents vide documents submission checklist as Annexure "1" Sr. No.7 and Technical Evaluation Criteria as Annexure-VI Sr. No. 5.</p> <p>9. TOR FOR THIRD PARTY INSPECTION & EXPEDITING has not been vetted by bidder, manufacturer and coating mill.</p> <p>10. Bidder has scored 30% marks against requirement of 70% marks.</p>	
6	M/s. U&A Drilling Equipment & Tubular Supplies DMCC. UAE	<p><u>Main Treason of Rejection</u></p> <p>1. As per Bid Summary Sheet Annexure-E, bidder has declared "DALIPAL PIPE COMPANY" with site address "No. 1 Equipment Manufacturing Park, Nanshugang Road, Bohai New Area, Cangzhou, Hebei, China" as Line Pipe manufacturer having API Certificate No. 5L-1195. Also, authorization letter in favor of bidder is from same site of "DALIPAL PIPE COMPANY". This Site having API Certificate No. 5L-1195 (No. 1 Equipment Manufacturing Park, Nanshugang Road, Bohai New Area, Cangzhou, Hebei, China) of "DALIPAL PIPE COMPANY" does not meet tender criteria due to following reasons.</p> <ul style="list-style-type: none"> i. API is not authorizing for Manufacturing of Line Pipe PSL 2 - Service Annex H with delivery condition N for API 5L-1195. ii. API 5L-1195 is not for consecutive last five years which is the requirement of tender documents. <p><u>Other Reasons of Rejection</u></p> <p>1. Bidder didn't shared manufacturer's priced purchase order copies for last 5 years as required by tender documents vide documents submission checklist as Annexure "1" Sr. No.7 and Technical Evaluation Criteria as Annexure-VI Sr. No. 5.</p> <p>2. Bidder has scored 50% marks against requirement of at least 70% marks.</p>	No