

Technical Evaluation Report

Tender Reference # PROC-FB/CB/PROD-4094/2018 (Purchase of Hydroset Packers, Sub Surface Safety Valves and other related equipment)

| S.# | Bidder | Manufacturer | Evaluation Results | Reasons for Rejection |
|-----|--|--|-----------------------------------|--|
| 01 | M/s China National Logging Corporation China | M/s Shanghai Extrong Oilfield Technology Co Ltd China | Technically Non Responsive | <p>i. The manufacturer is not certified for the last five years under API Specs. 14A, 14L and 11D1 as required in the tender specifications.</p> <p>ii. The supply record of the manufacturer does not fulfill the requirements of Technical Data Sheet clause #5, especially the total sales figures are less than the specified figure of 250 sets of Packers and TRSCSSVs and most of the clients are not foreign E&P companies and the contact information of the foreign clients is not available to independently verify the sale figures.</p> <p>iii. No satisfactory performance certificate in favor of its manufacturer have been provided as required under clause # 8 of Technical Data sheet.</p> |
| 02 | M/s Star Petrotech Pte. Ltd Singapore | M/s Star Petrotech Pte. Ltd Singapore. TCO USA | Technically Non Responsive | <p>i. The bidder did not provide the contact details of international E & P companies requested for the Independent verification of their supply record/Performance. The bidder does not fulfill the requirement of Technical Data Sheet clause # 5.</p> <p>ii. The provided satisfactory Performance certificates do not fulfil the requirements of clause # 8 of Technical Data sheet, as same are either issued by supply houses or are not verifiable.</p> |
| 03 | M/s Halliburton FAR East Pte Ltd Singapore | M/s Halliburton FAR East Pte Ltd Singapore | Technically Responsive | ***** |
| 04 | M/s Weatherford Oil Tool M.E Ltd, Dubai UAE | M/s Weatherford ADM/ABU DHABI/MAGNUM | Technically Responsive | ***** |
| 05 | M/s Superior Energy Services LLC-Completion Services USA | M/s Superior Energy Services LLC-Completion Services USA | Technically Responsive | ***** |
| 06 | M/s Baker Eastern S.A Dubai, UAE | M/s Baker Eastern S.A Dubai, UAE | Non Responsive | M/s Baker Eastern bid is declared as Non Responsive due to non-compliance of OGDCL tender standard terms and conditions. |